

FINAL SOUTHEAST ROCKFORD OPERABLE UNIT REMEDIAL INVESTIGATION TECHNICAL MEMORANDUM

PREPARED FOR:

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY DIVISION OF LAND POLLUTION CONTROL REMEDIAL PROJECT MANAGEMENT SECTION FEDERAL SITE MANAGEMENT UNIT 2200 CHURCHILL ROAD SPRINGFIELD, ILLINOIS 62794-9276

SEPTEMBER 1990



TABLE OF CONTENTS

Section			Page
1.0	INTRO	DUCTION	1-1
	1.1	PURPOSE OF MEMORANDUM	1-1
	1.2	STUDY AREA BACKGROUND	1-2
		1.2.1 Study Area Location 1.2.2 Study Area Description 1.2.3 Geologic Setting 1.2.4 Study Area History and	1-2 1-4 1-4
		Prior Investigations	1-8
2.0	STUDY	AREA INVESTIGATION	2-1
	2.1	OVERVIEW OF WELL SAMPLING	2-1
	2.2	WELL SAMPLING PROTOCOL	2-8
	2.3	QUALITY ASSURANCE/QUALITY CONTROL	2-9
		2.3.1 Field Procedures2.3.2 Analytical Procedures	2-9 2-10
•	2.4	FIELD MAPPING OF ADDRESSES	2-12
	2.5	DEVIATIONS FROM WORK PLAN	2-12
3.0	NATUR	E AND EXTENT OF GROUNDWATER CONTAMINATION	31
	3.1	DATA ASSESSMENT	3-1
	,	3.1.1 Discussion of QC Sample Results 3.1.2 Comparison of New Data with Existing Data	3-4 3-11
	3.2	VOLATILE ORGANIC CONTAMINATION	3–16
		3.2.1 Data Display and Contouring	3–17
		3.2.2 Distribution and Levels of VOC Contamination 3.2.2.1 IEPA/USEPA Data 3.2.2.2 IDPH Data	3-28 3-29 3-30
	3.3	METALS CONTAMINATION	3–31
	3.4	COMPARISON TO ARARS	3-35
	3 5	3-D CONTOUR PLOTS OF LEPA/LISEPA DATA	3_38

TABLE OF CONTENTS (Continued)

Section				Page
4.0	RISK	ASSESSM	IENT .	4-1
	4.1	PURPOS	E AND SCOPE OF RISK ASSESSMENT	4-1
	4.2	METHOD	OLOGY	4-2
		4.2.1	Data Evaluation Comparison of Data to Maximum Contaminant	4-3
		4.2.3	Levels Calculation of Hazard Indices	4-3 4-6
	4.3	RESULI	PS .	4-6
	4.4	CONCLU	SIONS	4-22
		4.4.1 4.4.2 4.4.3	Comparison of Data to Maximum Contaminant Levels Carcinogenic Hazard Indices Non-Carcinogenic Hazard Indices	4-22 4-23 4-24
5.0	SUMMA	RY AND	CONCLUSIONS	5-1
6.0	REFEF	RENCES		6-1
APPENI	DICES			
	Apper	ndix A	SAMPLE COLLECTION SHEETS	
	Apper	ndix B	FIELD NOTEBOOKS	
	Appen	ndix C	3-D CONTOUR PLOTS OF VOC CONCENTRATIONS FOR IEPA/USEPA DATA	
	Anner	ndix D	SPREADSHEETS USED TO CALCULATE HAZARD INDICES	

LIST OF TABLES

Table		Page
2-1	SAMPLE LOCATIONS TARGETED IN OPERABLE UNIT WORK PLAN	2-3
2–2	SUMMARY OF LOCATIONS SAMPLED	2-4
2-3	SUMMARY OF LOCATIONS FROM WHICH SAMPLES COULD NOT BE COLLECTED	2–7
2-4	SUMMARY OF QA/QC SAMPLE LOCATIONS	2–11
3–1	EXPLANATION OF DATA QUALIFIERS	3-3
3–2	IEPA FIELD BLANK DATA, METALS	3-5
3–3	IEPA FIELD BLANK DATA, VOCs	3–6
3–4	IEPA TRIP BLANK DATA	3–7
3–5	IEPA FIELD DUPLICATES, METALS	3–9
3–6	IEPA FIELD DUPLICATES, VOCs	3-10
3–7	ANALYTICAL RESULTS FOR MULTIPLE SAMPLES (USEPA VS. IDPH DATA)	3–13
3–8	ANALYTICAL RESULTS FOR MULTIPLE SAMPLES (IEPA VS. IDPH DATA)	3–15
3–9	CONTAMINANTS ANALYZED AND DETECTION LIMITS FOR OPERABLE UNIT SAMPLES	3–18
3–10	IEPA VOC DATA	3–19
3–11	USEPA VOC DATA	3–21
3–12	IDPH VOC DATA	3–23
3–13	IEPA METALS DATA	3-32
3–14	POTENTIAL APPLICABLE OR RELEVANT AND APPROPRIATE REQUIREMENTS (ARARS)	3–36
4-1	WELLS WHERE CONTAMINATION NOT DETECTED ABOVE DETECTION LIMITS	4-4
4-2	WELLS WHERE ONE OR MORE MAXIMUM CONTAMINANT LEVEL EXCEEDED	4-7

LIST OF TABLES (Continued)

<u>Table</u>		Page
4-3	WELLS WHERE CONTAMINATION DETECTED ABOVE DETECTION LIMITS BUT BELOW MCL	•
	·	4-10
4-4	INCREMENTAL TARGET ORGAN HAZARD INDICES	
	FOR WELLS WHERE CONTAMINATION DETECTED	
	BELOW MCL	4-16

LIST OF FIGURES

F	'igure		Page
	1-1	SOUTHEAST ROCKFORD STUDY AREA	1-3
	1-2	EAST/WEST CROSS-SECTION OF UNCONSOLIDATED SEDIMENTARY WEDGE IN VICINITY OF STUDY AREA	1-6
	1-2	(CONT.) LEGEND FOR GEOLOGIC CROSS-SECTION	1–7
	3–1	GENERAL ADDRESS MAP FOR SOUTHEAST ROCKFORD STUDY AREA MA	P PACKE
	3–2	IEPA/USEPA SAMPLE LOCATION MAP	n
	3–3	IDPH SAMPLE LOCATIONS MAP, 1988-1989	11
	3-4	TCE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	n
	3-5	TCE CONCENTRATIONS FOR IDPH SAMPLES	"
	3-6	1,1,1-TCA CONCENTRATIONS FOR IEPA/USEPA SAMPLES	11
	3-7	1,1,1-TCA CONCENTRATIONS FOR IDPH SAMPLES	n
	3–8	CIS-1,2-DCE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	. "
	3-9	CIS-1,2-DCE CONCENTRATIONS FOR IDPH SAMPLES	11
	3-10	TRANS-1,2-DCE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	11
	3–11	TRANS-1,2-DCE CONCENTRATIONS FOR IDPH SAMPLES	11
	3–12	1,2-DCA CONCENTRATIONS FOR IEPA/USEPA SAMPLES	11
	3–13	1,2-DCA CONCENTRATIONS FOR IDPH SAMPLES	. 11
	3–14	1,1-DCA CONCENTRATIONS FOR IEPA/USEPA SAMPLES	11
	3–15	1,1-DCA CONCENTRATIONS FOR IDPH SAMPLES	**
	3–16	1,1-DCE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	tt
	3–17	1,1-DCE CONCENTRATIONS FOR IDPH SAMPLES	Ħ
	3–18	PCE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	***
	3_10	DCE CONCENTIONS FOR IDDH SAMDLES	. 11

LIST OF FIGURES (Continued)

rigure		Page
3–20	VINYL CHLORIDE CONCENTRATIONS FOR IEPA/USEPA SAMPLES	MAP PACKET
3-21	ARSENIC CONCENTRATIONS FOR IEPA SAMPLES	tt
3-22	CADMIUM CONCENTRATIONS FOR IEPA SAMPLES	11
3–23	CHROMIUM CONCENTRATIONS FOR IEPA SAMPLES	n
3–24	LEAD CONCENTRATIONS FOR IEPA SAMPLES	#1
3-25	PRIVATE WELLS WHERE AN MCL WAS EXCEEDED FOR ANY CONTAMINANT, IEPA/USEPA SAMPLES	11
3–26	PRIVATE WELLS WHERE MCL IS EXCEEDED FOR ANY CONTAMINANT, IDPH SAMPLES	11
4–1	SOUTHEAST ROCKFORD STUDY AREA: WELLS WHERE CONTAMINATION NOT DETECTED ABOVE DETECTION LIMITS	4–5
4-2	SOUTHEAST ROCKFORD STUDY AREA: WELLS WHERE ONE OR MORE MCL EXCEEDED	4–9
4-3	CARCINOGENIC HAZARD INDEX MAP	MAP PACKET
4-4	NON-CARCINOGENIC HAZARD INDEX MAP	11

1.0 INTRODUCTION

Groundwater sampling programs by the Illinois Department of Public Health (IDPH), the United States Environmental Protection Agency (USEPA), and the Illinois Environmental Protection Agency (IEPA) have established that a major groundwater contamination problem exists in the southeast section of Rockford, Illinois. Previous studies have shown that a plume of Volatile Organic Compound (VOC) contaminated groundwater traverses an area where local residents rely on well water for a potable water source. In response to this threat to public health, IEPA and USEPA are currently involved in a joint effort to remedy the problem by identifying affected residents and providing them with an alternative water source. USEPA is currently constructing new water lines and connecting affected residents to existing water lines to provide city water to all residents in the core of the VOC plume.

IEPA is currently conducting a two-part investigation of the area, consisting of an Operable Unit remedial investigation to address immediate threats to public health on the margins of the plume, and a more comprehensive remedial investigation/feasibility study, (RI/FS) to address long-term remediation of the contamination problem. During June 1990, Camp Dresser & McKee (CDM), under the direction of IEPA, conducted a groundwater sampling investigation of the area in order to identify affected residents on the margins of the plume, as part of the Operable Unit remedial investigation. In this Technical Memorandum, the results of this Operable Unit remedial investigation are presented and synthesized with existing data to summarize the current status of groundwater contamination in the Southeast Rockford area.

1.1 PURPOSE OF MEMORANDUM

The purpose of this Technical Memorandum is to document and present the results of the IEPA Operable Unit remedial investigation that took place in June 1990. The report is organized in four sections. In the first section, general information about the site, such as site geology, RECEIVED

16814/36

physiography, and history is summarized. In the second section, the field techniques employed during the investigation are discussed. In the third section, the results of the groundwater sampling are presented. In the fourth section, the risks to public health are discussed. Following these sections, the conclusions of the study are summarized. This document is intended to provide the technical background to support the Feasibility Study (FS) and Record of Decision (ROD). Other aspects of the groundwater contamination problem in southeast Rockford, such as identifying source areas, predicting contaminant migration pathways, and assessing the impact on the environment, will be addressed in the full-scale RI/FS, which is currently in the planning stage.


1.2 STUDY AREA BACKGROUND

During the course of planning and conducting the Southeast Rockford Operable Unit, previous studies, available literature, and other pertinent information were reviewed. In the following sections, a summary of this review is presented.

1.2.1 STUDY AREA LOCATION

The study area is located near Southeast Rockford in Winnebago County, and consists of approximately 2.4 square miles in Sections 1, 2, and 3, T43N, R1E and Section 6, T43N, R2E. The study area is bounded by Harrison Avenue to the North, Sandy Hollow Road to the South, the north-south center line of Section 6 to the East, and the Rock River to the West. The study area is shown in Figure 1-1.

The study area has been expanded from the boundaries used to score the site for inclusion on the National Priorities List. The site was originally bounded by 8th Street to the West, Sawyer Road to the South, 21st Street to the East and Harrison Avenue to North.



1.2.2 STUDY AREA DESCRIPTION

The study area is predominantly an urban residential area, which includes scattered industrial, retail and commercial operations. A small industrial park is located near the eastern edge of the study area in the vicinity of Laude Drive. Other industrial areas are situated in the vicinity of Harrison Street and Eighth Street, near the Rock River in the northwest part of the study area, and elsewhere in the study area.

The study area is predominantly flat-lying and slopes gently westward towards the Rock River, but locally contains low-relief hilly areas.

Maximum topographic relief across the study area is approximately 120 feet. A small concrete-lined drainage ditch runs across the study area and discharges to the Rock River in the southwest corner. A review of 117 IDPH Well Construction Reports establishes that the majority of the residential wells in the study area are screened in the 40-foot to 70-foot range in a sand and gravel aquifer. Although deeper residential wells are common in the study area, no systematic distribution of the deeper wells is evident.

1.2.3 GEOLOGIC SETTING

The local geology of the study area consists of a valley-train deposit that fills an eroded pre-glacial drainageway. The valley-train deposit forms a wedge of unconsolidated sand and gravel deposits that are interbedded with laterally discontinuous clay- and silt-rich strata. These unconsolidated sediments unconformably overlie eroded bedrock of Ordovician age. Depending on location, the sediments overlie the Galena-Platteville Group or the St. Peter Sandstone, the latter of which is an important aquifer in northern Illinois.

Within the study area, the unconsolidated sediments increase in thickness to the West towards the Rock River. Based on well logs from Municipal Well 35 (located at 2944 Bildahl) and IEPA monitoring wells from Barrett's Mobile Home Park (in the vicinity of Harrison and Marshall), the uncon-

solidated sediments are expected to range in thickness from approximately 50 to 250 feet in the study area. The unconsolidated sedimentary wedge is schematically illustrated in the cross section in Figure 1-2. This cross section is from a report by Wehrmann et al. (1988) on the groundwater quality in the Rockford area, and is based on well logs from locations near the study area.

The Galena-Platteville is a carbonate sequence composed predominantly of fractured and jointed dolomite in the study area. In northern Illinois, the combined thickness of the Galena and Platteville Groups can range as high as approximately 400 feet (Willman et al. 1975), but erosional truncation of the unit can cause abrupt lateral changes in thickness. Although the Galena-Platteville is not a major aquifer in northern Illinois, the unit is water-bearing and is used for water supply wells in some areas.

The Glenwood Formation, which is the lowermost member of the Galena-Platteville, is a unit of varying lithology that separates the upper members of the Galena-Platteville from the St. Peter. In some parts of northern Illinois, the unit is shaly, and may act locally as an aquitard. The Glenwood Formation thins in the vicinity of Rockford, and may not be present in the study area. If present in the study area, fracturing of shale and dolomite members of the formation or a facies change to sandstone could reduce the likelihood that the Glenwood Formation would act as an aquitard.

The Glenwood Formation overlies the St. Peter Sandstone, which is a friable, medium-grained, pure quartz sandstone. In northern Illinois, the St. Peter can locally reach thicknesses of up to 700 feet, but thicknesses on the order of 300 feet are anticipated in the study area (Willman et al. 1975). The unit is an important aquifer in northern Illinois, and several of the City of Rockford's municipal water supply wells derive potable water from the St. Peter.

APPROXIMATE LOCATION OF STUDY AREA West East 11-43N-1E 10-43N-1E 2-43N-1E 9-43N-1E 1-43N-1E | 12-43N-1E | 7-43N-2E 8-43N-1E ISGS-4 WIN-5 ww ww ww 800 ft 800 ft 225 m 700 700 200 hm gor-o Galena-Platteville Dolomite " gor-l 600 600 175 Galena-Platteville gf-o **Dolomite** 150--500 500 Banner Formation vertical exaggeration 40X Glenwood-St. Peter Sandstone 1.5 km 125-ISGS 1986 SOURCE: H. A. Wehrmann, et. al., September 1988

CDM

environmental engineers, scientists, planners, & management consultants

EAST/WEST CROSS-SECTION OF UNCONSOLIDATED SEDIMENTARY WEDGE IN VICINITY OF STUDY AREA

FIGURE NO.

1-2

SYMBOL	UNIT	UTHOLOGY
wia	Argyle	pinkish or buff—tan; often friable sandy till
win	Nimtz	gray—brown or buff; often compact sandy or sandy loam till
wib	Beaver Creek Sand	sand and gravel outwash
ge	Esmond	grayish brown silty clay till
gor	Oregon	pinkish brown or buff sandy loam till
gf	Fairdale	yellowish brown sandy loam till
gk	Kellerville	brown clay loam to silt loam till
1	Lacustrine	fine—grained sediments associated with a specific till
- 0	Outwash	sand and gravel deposits associated with a specific till
С	Cahokia Alluvium	sand, silt, and clay deposited by modern rivers and streams
pl	Parkland Sand	windblown (eolian) sand
pr ·	Peoria Loess and Roxana Silt	windblown (eolian) silt
hm	Henry Formation	Mackinaw Member sand and gravel
ec ,	Equality Formation	Carmi Member lake silts and clays



till



lacustrine silt-clay



outwash sand and gravel



lacustrine sandy silt-sandy clay



lacustrine clay



organic materials or buried soil

TD — total depth

ww - water well boring

WN # - ISGS test boring

TB - tollway boring

NOTE

The Banner Formation is a lower Quaternary glacial formation consisting primarily of till and intercalated sands, silts, and gravels, which are of Yarmouthian age. (Wilman, 1975)

CDM

environmental engineers, scientists, planners, & management consultants

LEGEND FOR
GEOLOGIC CROSS SECTION

FIGURE NO. 1-2 Cont'd The St. Peter Sandstone unconformably overlies the Prairie du Chien, Eminence-Potosi, and Franconia Formations, which are dominantly composed of sandy and argillaceous dolomites. Together these units act as a confining unit which is termed the 'middle confining unit' in Illinois State Geological Survey (ISGS) Co-op Groundwater Report 10. In the vicinity of the study area, the middle confining unit is expected to be approximately 100 feet thick (ISGS, 1985).

The geologic section from the base of the St. Peter to the surface may contain no aquitards in the study area. It is possible, therefore, that hydraulic communication could form a pathway for contaminant migration from the unconsolidated sediments to the Galena-Platteville and St. Peter Sandstone.

1.2.4 STUDY AREA HISTORY AND PRIOR INVESTIGATIONS

Groundwater contamination by volatile organic compounds (VOCs) was initially discovered in the study area by the City of Rockford in 1981. Four municipal wells in Southeast Rockford were taken out of service in December 1981 as a result of the contamination. In 1982, the city discovered that additional wells were contaminated and subsequently closed down more city wells. Contamination of Municipal Well 35, located near Ken Rock Playground (Bildahl Street and Reed Avenue), was discovered during a routine sampling of the well in 1984; the well was tested for 33 priority pollutants and several VOCs were detected.

Because contaminants were present at levels above the Safe Drinking Water Act Maximum Contaminant Level (MCL), the well was taken out of service in 1985. Subsequent analysis of a sample from this municipal well after disinfection with chlorine in 1989 indicated that none of the original contaminants were present above the level of detection; however, the analysis did show the presence of several trihalomethanes at low levels. These compounds are commonly associated with water disinfection and are not attributable to the groundwater contamination problem in the area. Tri-

halomethanes are regulated under the Safe Drinking Water Act, but do not warrant concern for this study because they were detected at levels significantly lower than the MCL.

IEPA discovered that VOCs were present in Southeast Rockford's water in 1984 as a result of a report that plating wastes were being illegally disposed of in a well located at 2613 South 11th Street. In October 1984, IDPH initiated an investigation that involved sampling 49 wells in the vicinity of the well. While the investigation did not find significant levels of contaminants common to plating wastes, it did report high levels of chlorinated solvents. These same contaminants were detected in the City of Rockford's municipal well.

IDPH conducted four separate sampling investigations involving residential wells in the Southeast Rockford area: 49 samples were collected in 1984, 43 samples in 1985, 17 in 1988, and 267 in 1989. For the most part, sample locations varied during the separate sampling investigations; however, in some cases, wells were sampled more than once.

In 1986, the Illinois State Water Survey (ISWS) completed a project that involved a regional characterization of groundwater quality in Rockford. The study indicated that groundwater samples from public and private wells in the Southeast Rockford area contained significant concentrations of VOCs. Seven private well sites sampled in the Southeast Rockford area as part of the study contained greater than 10 ug/l total VOCs; and 5 of those 7 contained greater than 100 ug/l total VOCs. One of the private wells containing greater than 100 ug/l total VOCs was located near the Rock River (Wehrmann, 1988).

In August and October 1989, the USEPA Technical Assistance Team (TAT) sampled 112 residential wells in the Southeast Rockford area and tested for the following abbreviated list of VOCs:

- o Trichloroethylene,
- o Cis-1,2-Dichloroethylene,
- o 1,2-Dichloroethane,

- o 1,1,1-Trichloroethane,
- o Trans-1,2-Dichloroethylene, and
- o 1,1-Dichloroethane.

Fourteen of the 112 samples were analyzed using gas chromatograph/mass spectroscopy (GC/MS) for the above compounds and for 24 additional VOCs. The contaminants detected in the USEPA/TAT study correlate with the full volatile scan IDPH data, indicating that the VOC contaminants of concern in the study area consist of the chlorinated solvents listed above, as well as 1,1-Dichloroethene and Tetrachloroethene.

Metals have been analyzed in only a limited number of samples in the Southeast Rockford Operable Unit study area. Chromium was detected by IEPA in a 1984 investigation of illegal disposal of plating wastes in a well located at 2613 South 11th Street. Detailed information from this investigation is not available. Cadmium and lead were detected at levels in excess of the MCL in groundwater at Barrett's Mobile Home Park (located at Harrison and Marshall) in 1988 during a routine IEPA investigation of community water supply wells. In the same study, arsenic was detected in one well at a concentration of 25% of the MCL for arsenic.

As a result of the sampling events by state and federal agencies, the Southeast Rockford site was proposed for inclusion on the NPL in June 1988 and was added to the National Priorities List (NPL) in March 1989 as a state-lead, federally funded Superfund site. A removal action by USEPA, which is currently in progress, includes extending water mains and providing hookups to city water for residences with private wells contaminated with VOCs at levels greater than 25 percent of the Removal Action Limit (RAL). USEPA began construction of the water main extensions and residential hookups in June 1990.

2.0 STUDY AREA INVESTIGATION

The study area investigation for the Operable Unit did not involve geological investigations, human population surveys, or ecological investigations. Therefore, this memorandum addresses only those activities associated with the groundwater investigation.

2.1 OVERVIEW OF WELL SAMPLING

During the ten-day period spanning June 11 to June 20, 1990, a total of 117 residential, non-residential, and municipal groundwater wells were sampled for a target list of volatile organic and inorganic (metals) analyses by CDM under contract with IEPA. Volatile organics analyzed for in this investigation included trichloroethene (TCE), 1,1,1-trichloroethane (1,1,1-TCA), cis-1,2-dichloroethene (cis-1,2-DCE), trans-1,2-dichloroethene (trans-1,2-DCE), 1,2-dichloroethane (1,2-DCA), 1,1-dichloroethane (1,1-DCA), 1,1-dichloroethene (1,1-DCE), tretrachloroethene (PCE), and vinyl chloride. Metals analyzed for included arsenic, cadmium, chromium and lead.

Several criteria were used to select locations for the samples collected during the IEPA Operable Unit investigation. These factors are discussed in detail in Section 3.4 of the Operable Unit Work Plan, and are summarized below. The primary objective of the sampling effort was to identify residential wells that are contaminated at levels between the Safe Drinking Water Act Maximum Contaminant Level (MCL) and the method detection limit for any of the contaminants analyzed. Because the area contaminated at levels above the MCL for TCE (5 ppb) encompassed the areas where MCLs were exceeded for any other contaminant, the area inside the 5 ppb contour line as defined by USEPA and IDPH data was excluded from further IEPA sampling. It was assumed that groundwater contamination at levels in excess of the MCL had been verified by previous studies within the 5 ppb contour. The 5 ppb TCE contour lines for USEPA and IDPH data do not coincide because of

data incompatibilities between the two data sets. To compensate for this disparity in reported concentrations, the outermost of the IDPH and USEPA 5 ppb contours was used as the area from which further samples were excluded, as a worst-case approach.

In the area outside the 5 ppb TCE contour, the primary criteria used for selection of sample points were sample density and sample availability. Sample locations were chosen based on existence of data gaps, presence of private wells, and results of previous sampling episodes. In all areas outside the 5 ppb TCE contour, a target sample density of 1 to 2 samples per block was chosen. In some areas, field conditions (lack of private wells) precluded collecting one sample per block, as discussed below.

A total of 117 investigative samples were collected during the June 1990 sampling event. These samples included 106 residential wells, 10 nonresidential wells, and 1 municipal well. Exact addresses for targeted sample locations were determined based primarily on an IEPA survey of water use by area residents, and on address maps supplied by the City of Rockford. Table 2-1 lists sampling locations that were targeted using these sources in the Operable Unit Work Plan. Because of inaccuracies and uncertainties in both the IEPA well survey and the address maps, it was not possible to sample all of the locations targeted in the Work Plan. In many cases, alternate sample locations were selected in the field, and in other cases no sample was collected due to an absence of appropriate alternates. The lack of suitable sample locations stemmed from the prevalence of city water or other factors. Locations that were actually sampled as a part of this Operable Unit investigation are listed in Table 2-2. Locations that were originally targeted for sampling but could not be sampled are presented in Table 2-3 along with the reasons that samples could not be collected.

Table 2-1
Sample Locations Targeted in
Operable Unit Work Plan

4th 4th 4th 4th 4th 5th 7th 7th 7th 8th	2805 2820 2917 3011 3045 2604 3115 3221 3305 3337 2914 3009	Barnum Barnum Barnum Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl	505 611 825 3009 3017 3038 3122 3141 3206 3302	Kishwaukee Lapey Lapey Lapey Lapey Lapey Lapey Lapey Lipey Lindale	3336 3013 3038 3137 3213 3230 3325
4th 4th 4th 5th 7th 7th 7th 7th 8th	2917 3011 3045 2604 3115 3221 3305 3337 2914 3009	Barnum Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl	825 3009 3017 3038 3122 3141 3206	Lapey Lapey Lapey Lapey Lapey Lapey Lindale	3038 3137 3213 3230 3325
4th 4th 5th 7th 7th 7th 7th 8th	3011 3045 2604 3115 3221 3305 3337 2914 3009	Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl	3009 3017 3038 3122 3141 3206	Lapey Lapey Lapey Lapey Lapey Lindale	3137 3213 3230 3325
4th 5th 7th 7th 7th 7th 8th	3045 2604 3115 3221 3305 3337 2914 3009	Bildahl Bildahl Bildahl Bildahl Bildahl Bildahl	3017 3038 3122: 3141 3206	Lapey Lapey Lapey Lindale	3213 3230 3325
5th 7th 7th 7th 7th 8th	2604 3115 3221 3305 3337 2914 3009	Bildahl Bildahl Bildahl Bildahl Bildahl	3038 3122 3141 3206	Lapey Lapey Lindale	3230 3325
7th 7th 7th 7th 8th	3115 3221 3305 3337 2914 3009	Bildahl Bildahl Bildahl Bildahl	3122: 3141 3206	Lapey Lindale	3325
7th 7th 7th 8th	3221 3305 3337 2914 3009	Bildahl Bildahl Bildahl	3141 3206	Lapey Lindale	
7th 7th 8th	3305 3337 2914 3009	Bildahl Bildahl	3206	Lindale	2407
7th 8th	3305 3337 2914 3009	Bildahl			2406
8th	3337 2914 3009		2202	Lindale	2620
8th	2914 3009	Bildahl	3302	Lindberg	2412
			3338	Lindberg	2619
		Brooke	106	Lyran	1616
8th	3109	Brooke	202	Lyran	1701
8th	3138	Brooke	326	Marshall	3125
8th	3201	Brooke	411	Marshall	3137
8th	3237	Brooke	430	Martin	430
8th	3301	Brooke	613	Martin	508
8th	3337	Brooke	823	Martin	618
9th	2624	Brooke	914	Mattis	827
9th	2730	Brooke	1101	Olsen	2812
9th	2808	Brooke	1202	Pershing	1637
9th	2842	Brooke	1317	Pershing	1726
9th	2927	Collins	2801	Ranger	801
9th	3102	Collins	2825	River Blvd.	3007
9th	3210	Collins	3029	River Blvd.	3117
9th	3245	Collins	3109	River Blvd.	3125
10th	2627	Collins	3126	Rock Riv. Ave	508
10th	3110	Collins	3245	Roosevelt	843
11th	2613	Collins	3310	Sandy Hollow	728
11th	2955	Fitch	407	Sandy Hollow	826
11th	3015	Fitch	507	Sandy Hollow	1202
11th	3119	Fitch	601	Sandy Hollow	1306
11th	3208	Fitch	807	Sandy Hollow	1820
11th	3215	Grant	3045	Saner	2905
11th	3301	Grant	3107	Saner	3011
11th	3329	Hamilton	1735	Saner	3110
15th	3135	Harrison	733	Sawyer	319
16th	3102	Harrison	1001	Sawyer	407
16th	3122	Harrison	1713	Sawyer	525
17th	2602	Harrison	1817	Sawyer	615
17th	3120	Harrison	2315	Sewell	2622
17th	3141	Johnson	1737	Sewell	2646
18th	3110	Kennon	315	Sewell	3137
19th	2622	Kennon	415	South	527
20th	2703	Kennon	517	South	619
20th	2717	Kennon	621	Taft	801
20th	3109	Kishwaukee	3037	Municipal Well 3	
Barnum	305	Kishwaukee	3112	Transcipal Well 3	
Barnum	409	Kishwaukee	3302		

Table 2-2
Summary of Locations Sampled

Street A	ddress	C-O-C Date	Comments
4th	2819	11-Jun	Alt. for 2805 4th
4th	2828	11-Jun	Alt. for 2917 4th
4th	2901	12-Jun	Alt. for 3011 4th
4th	3045	14-Jun	
5th	2624	15-Jun	Alt. for 2604 5th
7th	3115	15-Jun	
7th	3233	- 13-Jun	Alt. for 3221 7th
7th	3309	14-Jun	Alt. for 3305 7th
8th	2810	14-Jun	Alt. for 2834 8th
8ւհ	2914	14-Jun	
8th	3022	17-Jun	Alt. for 3013 8th
8th	3109	18-Jun	
8th	3138	18-Jun	
8th	3201	13-Jun	
8th	3237	13-Jun	
8th	3301	13-Jun	
8th	3337	13-Jun	·
9th	2910	14-Jun	Alt. for 2929 9th
9th	3101	18-Jun	Alt. for 3102 9th
9th	3210	15-Jun	
9th	3245	14-Jun	
10th	3110	14-Jun	
16th	3102	13-Jun	
16th	3122	13-Jun	
17th	3120	13-Jun	
18th	3110	14-Jun	
20th	2703	18-Jun	
20th	3109	18-Jun	
Barnum	505	20-Jun	
Ваггу	426	18-Jun	Alt. for 415 Kennon
Bildahl	3017	19-Jun	Alt. for 3005 Bildahl
Bildahl	3038	15-Jun	
Bildahl	3122	16-Jun	
Bildahl	3141	15-Jun	
Bildahl	3206	16-Jun	
Bildahl	3302	15-Jun	
Bildahl	3338	15-Jun	
Brooke	110	18-Jun	Alt. for 106 Brooke
Brooke	202	12-Jun	
Brooke	326	12-Jun	
Brookc	409	12-Jun	Alt. for 411 Brooke
Вгооке	823	12-Jun	
Brooke	1202	15-Jun	
Brooke	1317	15-Jun	
Collins	2801	13-Jun	<u> </u>
Collins	3029	14-Jun	

Table 2-2 cont. Summary of Locations Sampled

Street /	Address	C-O-C Date	Comments
Collins	3126	16-Jun	
Collins	3245	14-Jun	
Collins	3310	13-Jun	
Grant	3045	16-Jun	
Grant	3107	18-Jun	
Hamilton	1630	18-Jun	Alt. for 3208 11th
Hamilton	1735	11-Jun	
Harrison	1713	15-Jun	
Harrison	1817	18-Jun	
Harrison	2315	13-Jun	
Horton	3129	15-Jun	Extra Sample Point to Improve Sample Density
Johnson	1737	11-Jun	
Kennon	410	19-Jun	Alt. for 315 Kennon
Kennon	621	19-Jun	
Kishwaukee	3037	19-Jun	
Kishwaukee	3202	15-Jun	Alt. for 3112 Kishwaukee
Kishwaukee	3239	14-Jun	Extra Sample Point to Improve Sample Density
Kishwaukee	3302	14-Jun	
Lapey	3013	19-Jun	
Lapey	3101	16-Jun	Alt. for 3038 Lapey
Lapey	3138	16-Jun	Alt. for 3137 Lapey
Lapey	3213	15-Jun	
Lapey	3230	14-Jun	
Lapey	3329	14-Jun	Alt. for 3325 Lapey
Lindale	2406	13-Jun	
Lindale	2620	12-Jun	
Lindberg	2412	12-Jun	Alt. for 2406 Lindberg, Which Does Not Exist
Lindberg	2619	14-Jun	
Lyran	1617	11-Jun	Alt. for 1616 Lyran
Lyran	1701	12-Jun	′
Marshall	3106	14-Jun	Alt. for 3125 Marshall
Marshall	3137	15-Jun	
Martin	430	13-Jun	
Mattis	827	12-Jun	
New Milford	608	18-Jun	Alt. for 733 Harrison
Olsen	2820	12-Jun	Alt. for 2812 Olsen
Pershing	1637	15-Jun	
Pershing	1726	15-Jun	
Ranger	801	12-Jun	
River Blvd.	3007	12-Jun	
River Blvd.	3117	18-Jun	
River Blvd.	3110	19-Jun	Alt. for 3125 River Blvd.
Rock Riv. Ave.	508	12-Jun	
Roosevelt	841	18-Jun	Alt. for 843 Roosevelt
Sandy Hollow	728	16-Jun	
Sandy Hollow	810	18-Jun	Alt. for 826 Sandy Hollow

Table 2-2 cont. Summary of Locations Sampled

Street	Address	C-O-C Date	Comments
Sandy Hollow	1202	18-Jun	
Sandy Hollow	1306	13-Jun	
Sandy Hollow	1812	13-Jun	Alt. for 1820 Sandy Hollow
Saner	2905	12-Jun	
Saner	3014	19-Jun	Alt. for 3011 Saner
Saner	3110	15-Jun	
Sawyer	319	13-Jun	
Sewell	2646	19-Jun	
Sewell	3135.5	15-Jun	Alt. for 3137 Sewell
South	619	12-Jun	
Taft	804	18-Jun	Alt. for 801 Taft

Non-residential Wells

Street	Address	C-O-C Date	Comments
8th	2647	18-Jun	Estwing Manufacturing — Non Potable
11th	2613	18-Jun	Rockford Cylinder Gas — Potable
11th	2955	11-Jun	Tussing Tile & Flooring — Potable
11th	3015	12-Jun	Smith Auto Repair — Potable
11th	3119	12-Jun	Goodyear Tire Co. — Potable
11th	3237	15-Jun	McDonald's Restaurant — Potable
11th	3329	15-Jun	Pizza Hut Restaurant — Potable
17th	2602	13-Jun	East Rockford Collision Center — Non Potable
Bildahl	2944	19-Jun	Municipal Well 35 — Not In Use
Brooke	1101	19-Jun	Kincade's Service Station — Potable
Collins	3109	16-Jun	Corcoran's Body Shop — Potable
Energy Ave.	123	14-Jun	Commonwealth Edison — Non Potable
Harrison	707	19-Jun	Rockford Products — Non Potable
Kishwaukee	3333	18-Jun	Rock River Reclamation Dist. — Non Potable

[•] C-O-C = Chain of Custody

Table 2-3
Summary of Locations From Which Samples
Could Not Be Collected

Street	Address	Comments
6th	2628	No Such Number, No Alternate Wells Available
7th	3337	No Wells Available
9th	2624	No Wells Available
9th	2730	Hook-up to Existing Water Line Planned by USEPA
9th`	2808	Hook-up to Existing Water Line Planned by USEPA
9th	2845	Hook-up to Existing Water Line Planned by USEPA
10th	2629	No Wells Available
11th	3301	Skipped Because of Proximity to Other Samples
15th	3133	No Wells Available
1 7t h	3141	Well Hit by Lightning — No Appropriate Alternate Available
19th	2622	City Water, No Appropriate Alternates Available
20th	2713	House Abandoned — Well Not Operational
Barnum	311	No Wells Available
Barnum	409	No Wells Available
Barnum /	611	No Wells Available
Barnum	825	No Wells Available
Bildahl	2947	No Wells Available
Brooke	430	No Wells Available
Brooke	613	No Wells Available
Brooke	914	No Wells Available
Fitch	407	No Wells Available
Fitch	503	No Wells Available
Fitch	601	No Wells Available
Fitch	807	No Wells Available
Kennon	517	No Wells Available
Martin	508	No Wells Available
Martin	618	No Wells Available
Saner	2819	Skipped Because of Proximity to Other Samples
Sawyer	407	No Wells Available
Sawyer	525	No Wells Available
Sawyer	615	No Wells Available
Sewell	2622	No Wells Available
South	605	No Wells Available

2.2 WELL SAMPLING PROTOCOL

Well sampling was conducted by teams of two persons who recorded data on Sample Collection Sheets (Appendix A) and in Field Notebooks (Appendix B). Sampling typically began with verification of information such as resident's name and address, as well as relevant details about the well and the sample point. Whenever possible, the well and its waterlines were visually inspected to confirm the absence of a water softener, to note the presence of PVC pipes and other details of well construction, and to ensure that the point of sample collection was located as close as possible to the well. Information provided by the resident was used in cases where visual inspection of the well system was not possible or was not allowed.

In order to ensure that a representative groundwater sample was collected, standing water from the well and plumbing system was purged by running the sample point faucet at full volume for a minimum of 10 to 15 minutes. After a minimum of 10 minutes, the pH, temperature, and conductivity of the purge water was measured at 1 to 2 minute intervals. The purge was considered adequate when three consecutive measurements of pH, temperature, and conductivity fell within the ranges specified on the Sample Collection Sheets (Appendix A). Purge rate was measured by noting the time required to fill a container of known volume, and both purge rate and total purge time were noted on the Sample Collection Sheets.

After adequate purging (generally 15-20 minutes), the flow rate was reduced to a trickle to minimize disturbance to the sample water, and a sample for Volatile Organic Analysis (VOA) was collected in an appropriate number of 40 ml vials. The VOA vials were carefully checked for air bubbles and were retaken if any bubbles were detected. Next, flow rate was increased and the sample for metals analysis was collected in one 1-liter polyethylene bottle. Faucet aerators and hoses were removed prior to sample collection. Surgical gloves were worn at all times during sample collection and were changed frequently at each sample location. The VOA vials were placed in a sealable plastic bag and placed with the metals samples in an ice-bearing

cooler. The samples were then taken to the CDM trailer where the samples for metals analysis were preserved with nitric acid (supplied by IEPA) and checked with pH paper to verify that solution pH was less than 2; VOA samples were not chemically preserved. In the trailer, the paperwork team completed the necessary sample handling and documentation in accordance with USEPA Region V procedures. Finally, the samples were packed following USEPA protocol and shipped by overnight carrier (Federal Express) to the appropriate laboratories for analysis: organic samples were sent to S-Cubed in San Diego, California and the inorganic samples were sent to Centec Analytical Services in Salem, Virginia.

2.3 QUALITY ASSURANCE/QUALITY CONTROL

2.3.1 FIELD PROCEDURES

The electrical conductivity meters and portable pH meters were calibrated every day prior to field measurements. The instruments were calibrated according to the manufacturer's instructions, which varied for each instrument. Commercially prepared conductivity solutions (1,000 umhos and 10,000 umhos) and pH buffer solutions (4 and 7) were used for calibration.

The accuracy of the information on the sample bottle labels was verified by the paperwork personnel in the trailer. Tag numbers attached to the sample bottles were cross-checked with tag numbers from the Chain of Custody Record prior to packaging. Sample handling and documentation were carried out in accordance with guidelines specified in the USEPA Region V Sample Handling Manual (March 1989), which is excerpted in Appendix C of the Sampling and Analysis Plan (SAP) of the Operable Unit Project Plans. All sample bottles were provided by the IEPA Sample Bottle Supply Program as discussed in Appendix D of the Quality Assurance Project Plan.

In addition to investigative samples, the following QA/QC samples were also collected as specified in the Operable Unit Project Plans: 10 field duplicates, 10 field blanks, and 8 Matrix Spike/Matrix Spike Duplicates

(MS/MSDs). In addition, a trip blank consisting of four 40-ml vials was included in each cooler containing samples for organic analysis; a total of 10 trip blanks were shipped. The trip blanks, which contained reagent-grade distilled water, were provided by IEPA. Pertinent information regarding QA/QC samples is listed in Table 2-4. Field duplicates (i.e., replicates of the investigative samples) were collected at the same time, following the same procedures as those for investigative samples. Field blanks containing reagent-grade distilled water were collected at the same time and location and in the same manner as the investigative samples. The MS/MSD sample for organic analysis consisted of four 40 ml vials, whereas the 1-liter inorganic sample was sufficient for both the investigative and MS/MSD analyses.

Samples were packaged and shipped as specified in Sections 3.4 and 3.5 of the Sampling and Analysis Plan (SAP). Samples that were collected late in the day or on Sunday were shipped by overnight carrier (Federal Express) the following day. Samples held overnight were kept on ice in coolers that were secured with custody seals. The trailer was locked at all times when unoccupied.

2.3.2 ANALYTICAL PROCEDURES

Organic samples were analyzed by S-Cubed in San Diego, California using Gas Chromatography/Mass Spectrometry. The organic samples were analyzed for the 9 VOCs listed in Table 3-9. Inorganic samples were analyzed by Centec Analytical Services of Salem, Virginia using Graphite Furnace Atomic Absorption (GFAA) for arsenic, cadmium, and lead, and Inductively Coupled Plasma (ICP) Emission for chromium. Both laboratories are part of the Contract Laboratory Program (CLP). Specific data requirements and QC procedures required of the analytical laboratories are detailed in the Special Analytical Services (SAS) requests, which can be found in Appendix B of the QAPP. The SAS request for organic analysis was based on the Safe Drinking Water Act (SDWA) analytical method 524.2 for low detection limits. The inorganic SAS was derived from the CLP Region V standardized SAS for

Table 2-4
Summary of QA/QC Sample Locations *

Field Duplicate		
Street Add	iress	Date
41h	3045	14-Jun
10th	3110	14-Jun
Bildahl	3122	16-Jun
Brooke	823	12-Jun
Harrison	707	19-Jun
Harrison	2315	13-Jun
Horton	3129	15-Jun
Johnson	1737	11-Jun
Lapey	3013	19-Jun
River	3117	18-Jun

, Field Blank		
Street Ad	dress	Date
8th	3138	18-Jun
11th	3015	12-Jun
17th	2602	13-Jun
18th	3110	14-Jun
Grant	3045	16-Jun
Harrison	707	19-Jun
Lapey	3213	15-Jun
Lapey	3230	14-Jun
Lyran	1617	11-Jun
Saner	3014	19-Jun

Matrix Spike Duplicate		
Street Ada	iress	Date
9th	2910	14-Jun
11th	2955	11-Jun
Bildahl	· 3206	16-Jun
Brooke	326	12-Jun
Collins	2801	13-Jun
Collins	3029	14-Jun
Harrison	1817	18-Jun
Kennon	410	19-Jun

^{* 10} trip blanks were analyzed in addition to the samples listed.

inorganic drinking water analysis. Upon receipt of the analytical results, data validation was performed by CDM in accordance with the general procedures for data assessment outlined in Laboratory Data Validation Functional Guidelines for Evaluating Organic Analyses (February 1, 1988), and in Laboratory Data Validation Functional Guidelines for Evaluating Inorganic Analyses (July 1, 1988). Both documents were prepared by USEPA Data Review Work Group. Factors scrutinized during data validation included sample holding times, instrument tuning and performance, instrument calibration, analyte concentrations in blanks, surrogate recoveries, matrix spike/matrix spike duplicate analysis, and other quality control parameters outlined in the respective SAS requests.

2.4 FIELD MAPPING OF ADDRESSES

Street addresses within the study area were mapped in the field to develop an accurate address database. This task was accomplished by noting street numbers from houses or mailboxes and marking this information on digitized plat maps. The resulting address map is included as Figure 3-1, in the map packet accompanying this report.

2.5 DEVIATIONS FROM WORK PLAN

During the course of field work in the Southeast Rockford Study Area, several deviations from the Operable Unit Work Plan were made in order to expedite field activities and accommodate unforeseen circumstances. In this section, these deviations are discussed and documented.

The major deviation from the Operable Unit Work Plan was the number of samples collected in the field. The Work Plan called for 155 investigative samples, consisting of 144 residential samples, 10 industrial samples and 1 municipal well sample. As field work progressed, it became clear that many of the locations originally targeted for sampling, as well as the nearby alternate sample locations, could not be sampled for a variety of reasons. The bulk of these locations are in the southwestern portion of the study

area, west of Kishwaukee Street and south of Brooke Road, where many of the possible sample locations are serviced with municipal water. Other factors that prevented sample collection are listed in Table 2-3. After conferring with David Dollins, IEPA Project Manager, on June 19, 1990, it was decided that adequate attempts had been made to locate alternates for the sample points originally targeted in the Work Plan, and that the sample coverage from available sample points was sufficient to justify termination of sampling activities. As a result, a total of 117 investigative samples was collected.

Two residential samples not included in the Work Plan were added in order to improve sample density in areas where sample points were available. These samples included 3129 Horton Street and 3239 Kishwaukee Street.

Other deviations from the Work Plan involved industrial well samples. The Work Plan originally called for sampling ten industries that use private wells for potable water. Based on a survey performed by Virginia Wood of IEPA, of the industries in the study area, it was determined that the majority of businesses in the area use municipal water for their potable water supply. Consequently, the industrial wells at Commonwealth Edison, Estwing Manufacturing, and Rockford Products were sampled despite the fact that the wells were not used for potable water supply. This modification was made in order to provide sample coverage in the large industrial areas in the northwest and west-central portions of the study area.

Other samples that were originally classified as residential in the Work Plan were reclassified in order to more accurately reflect the primary use of the establishment owning the well. These wells include the wells at 2613 11th Street (Rockford Cylinder Gas), 2955 11th Street (Tussing Tile and Flooring), 3015 11th Street (Smith Auto Repair), 3119 11th Street (Goodyear Tire Company), 3237 11th Street (McDonald's), 3329 11th Street (Pizza Hut), 2602 17th Street (East Rockford Collision Center), 1101 Brooke Road (Kincades Service), 3109 Collins (Corcoran's Body Shop), and 3333 Kishwaukee (Rock River Reclamation District). Given the variety of

commercial and industrial uses of these establishments, the wells have been reclassified as 'nonresidential.'

The ratio of QA/QC samples to investigative samples was slightly different than originally planned in the Work Plan. The ratios of field blanks, field duplicates, and matrix spike/matrix spike duplicates to investigative samples were approximately 1:12, 1:12, and 1:15, respectively, rather than 1:10, 1:10, and 1:20, as specified in the Work Plan.

3.0 NATURE AND EXTENT OF GROUNDWATER CONTAMINATION

As a result of the IEPA, USEPA and IDPH studies, a great deal of information regarding contamination levels in residential wells in the study area has been collected. In this section of the Technical Memorandum, analytical results from these studies are presented in both map and tabular format. Due to the large study area, graphically presentable information is necessarily shown on maps measuring approximately 18 inches by 36 inches. The maps appear in the map packet which accompanies this report, and the tables appear in the text.

As stated in the introduction to this report, the intention of the Technical Memorandum is to present the data gathered in this and other studies in order to summarize the current status of contamination of residential wells and to provide a site characterization background for the feasibility study and the Record of Decision. In this section of the report, the quality and compatibility of the analytical data generated during this and other studies are discussed, and the current status of groundwater contamination is presented.

3.1 DATA ASSESSMENT

Field QC samples were collected to determine the accuracy and precision of field sampling procedures and to aid in assessing the overall quality of the data. This subsection presents and discusses the analytical results for the QC samples and compares the data generated from the Operable Unit sampling event with the results of prior sampling events.

As discussed in Subsection 2.3.2, data validation was performed in accordance with the Laboratory Data Validation Functional Guidelines for Evaluating Organics (February 1, 1988) and Inorganics (July 1, 1988)

Analyses, prepared by the USEPA Data Review Work Group. Qualifiers were applied to the data based on the results of analytical QC performed by the

laboratories. Data qualifiers follow standard usage as given in USEPA's Statement of Work for Organics Analysis (SOW No. 288) and Statement of Work for Inorganics Analysis (SOW No. 788), hence only a brief explanation of the data flags is given here. Table 3-1 provides an explanation of the data qualifiers used in this report. Overall, there were no significant problems or shortcomings in the data, and all of the data were found to be useable as flagged.

For inorganic analytes, data flagged with "ND" indicate that the analyte was detected at or below the instrument detection limit (IDL) without further qualification. Data flagged with a "B" indicates blank contamination. Blank contamination was ubiquitous but mostly present at low levels that required no further action on the part of the laboratories or by the data validators. A "J" flag signifies that the reported concentration is an estimated value. The value is estimated because one of several possible analytical QC parameters exceeded control limits that were specified in either the SAS request or the <u>Functional Guidelines</u> (July 1, 1988). A "UJ" qualifier means that an analyte is not detected but is still an estimated value because control limits for analytical QC were exceeded. An "R" flag represents data that were rejected on the basis of analytical QC results; only two metal values from the Operable Unit data were rejected.

The data qualifiers used in VOC data assessment are similar to those used in assessment of the metals data (Table 3-1). A "B" is used to indicate contamination in the method (laboratory) blank. A sample is flagged with "B" whenever an analyte is found in the associated method blank, regardless of the level of blank contamination. However, if the concentration of the sample is less than 5 times the concentration in the method blank for a particular compound, the "B" would be dropped and the sample would be flagged with "U". A "U" qualifier also means that the analyte was analyzed for but was not detected. Anytime the concentration of a compound found in the sample is less than 5 times the concentration of the same compound found in the corresponding trip blank, field blank, or method blank, the

Table 3-1 Explanation of Data Qualifiers

Metals

Qualifier	Definition	
ND	Analyzed for but not detected	
В	The analyte was found in the lab	
ļ	blank at below the CRDL *	
J	The associated value is estimated because	
	quality control criteria were not met	
R	Data are not useable	
UJ	Analyzed for but not detected. The associated	
	value is an estimate and may be inaccurate	
	or imprecise	

VOCs

Qualifier	Definition
ND	Analyzed for but not detected
В	Sample concentration is greater than or equal
	to 5 times the method blank contamination
J	The associated value is estimated because
	quality control criteria were not met
U	Analyzed for but not detected
UJ	Analyzed for but not detected. The sample
	quantitation limit is an estimated quantity

^{*} CRDL = Contract Required Detection Limit

sample is flagged with "U." A sample can also be flagged with "U" anytime a quality control specification is grossly exceeded, as specified in the validation guidelines. A sample that is flagged with "J" signifies that the associated numerical value is an estimated quantity. A sample is flagged with "J" because control limits for analytical quality control specifications were exceeded or the detected concentration was between the contract required detection limit (CRDL) and the instrument detection limit (IDL). In some cases, flags are combined, with "UJ" being the most common combination. A "UJ" indicates that a compound is not detected but is estimated because control limits for analytical QC were exceeded. No VOC data were rejected.

3.1.1 DISCUSSION OF QC SAMPLE RESULTS

Field blank data for metals and VOCs are presented in Tables 3-2 and 3-3, respectively. None of the metal analytes were detected above their respective IDLs (as listed at the bottom of Table 3-2), indicating that the field sampling and laboratory procedures did not introduce significant levels of metal contaminants.

The VOC field blanks invariably contained low levels of contamination for certain analytes (Table 3-3). Most of the contamination found in the field blanks was qualified as a result of either minor contamination in the method blank (flagged with "B") or due to very low analyte concentrations in the blanks falling between the IDL and CRDL (flagged with "J"). Field blanks represent worst-case situations because some of them were collected at industrial locations such as automobile repair shops, which can contain significant levels of air-borne VOCs that can become incorporated into the blanks. In general, however, the field blanks did not show significant levels of contamination. The trip blank data (Table 3-4) attests to the pervasiveness of low-level VOC contamination. Trip blanks consisting of reagent-grade distilled water were prepared in "VOC-free" environments and were never directly exposed to the atmosphere during any part of the sampling event or sample shipment. Hence they represent a best-case

Contraction Contraction of the C

Table 3-2 IEPA Field Blank Data, Metals

1617 Lyran		
Residence		
Sample Number	508	
Sample Date	6/11/90	
Arsenic	ND	
Cadmium	ND .	
Chromium	ND	
Lead	ND	

707 Harrison		
Rockford Products		
Sample Number	645	
Sample Date	6/19/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3015 11th	
Smith Auto Repa	air
Sample Number	513
Sample Date	6/12/90
Arsenic	ND
Cadmium	ND
Chromium	ND
Lead	ND

3110 18th Residence		
Sample Date	6/13/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

2602 17th		
East Rockford Collision		
Sample Number	545	
Sample Date	6/13/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3230 Lapey Residence		
Sample Date	6/14/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3045 Grant Park		
Residence		
Sample Number	607	
Sample Date	6/16/90	
Arsenic .	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3213 Lapey		
Residence		
Sample Number	595	
Sample Date	6/15/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3138 8th		
Residence		
Sample Number	619	
Sample Date	6/17/90	
Arsenic	ND	
Cadmium	ND	
Chromium	ND	
Lead	ND	

3014 Saner Residence	
Sample Date	6/18/90
Arsenic	ND
Cadmium	ND
Chromium	ND
Lead	ND

• Instrument Detection Limits (µg/l)

As 2.0

Cd 0.1

Cr 10.0

Pb 1.0

• ND = Not Detected

Table 3-3 IEPA Field Blank Data, VOCs

1617 Lyran	
Residence	
Sample Number	08
Sample Date	6/11/90
TCE	0.1J
1,1,1-TCA	0.4J
cis-1,2-DCE	0.0J
trans-1,2-DCE	0.0J
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	0.0J
PCE	0.0J
Vinyl Chloride	ND

707 Harrison Rockford Products	
Sample Date	6/19/90
TCE	0.1JB
1,1,1-TCA	0.3JB
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.1JB
Vinyl Chloride	ND

3015 11th	
Smith Auto Repa	ir
Sample Number	13
Sample Date	6/12/90
TCE	0.1JB
1,1,1-TCA	0.3JB
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0JB
Vinyl Chloride	ND

3110 18th Residence	
Sample Date	6/13/90
TCE	0.1JB
1,1,1-TCA	1.7
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.1JB
Vinyl Chloride	ND

2602 17th	
East Rockford C	ollision
Sample Number	45
Sample Date	6/13/90
TCE	0.1JB
1,1,1-TCA	0.4J
cis-1,2-DCE	0.0JB
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0JB
Vinyl Chloride	ND

3230 Lapey	
Residence	
Sample Number	68
Sample Date	6/14/90
TCE	0.1J
1,1,1-TCA	0.4J
cis-1,2-DCE	ND.
trans-1,2-DCE	ND ·
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	· 0.1J
Vinyl Chloride	ND

3045 Grant Park	
Residence	
Sample Number	107
Sample Date	6/16/90
TCE	0.1JB
1,1,1-TCA	0.5B
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.1JB
Vinyl Chloride	ND

3213 Lapey	
Residence	
Sample Number	95
Sample Date	6/15/90
TCE	0.1J
1,1,1-TCA	0.5
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.1JB
Vinyl Chloride	ND

3138 8th	
Residence	
Sample Number	119
Sample Date	6/17/90
TCE	0.1JB
1,1,1-TCA	0.3J
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0JB
Vinyl Chloride	ND

3014 Saner	
Residence	
Sample Number	133
Sample Date	6/18/90
TCE	0.5JB
1,1,1-TCA	1.0J
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.3JB
Vinyl Chloride	ND

[•] All concentrations in µg/l

[•] ND = Not Detected, J = Estimated Value, B = Blank Contamination

Table 3-4 IEPA Trip Blank Data

Sample Number 01	
Sample Date	6/11/90
TCE	0.0J
1,1,1-TCA	0.0J
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0J
Vinyl Chloride	ND

Sample Nur	nber 91
Sample Date	6/15/90
TCE	ND
1,1,1-TCA	ND
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0JB
Vinyl Chloride	ND

Sample Number 11		
Sample Date	6/12/90	
TCE	0.1JB	
1,1,1-TCA	0.1JB	
cis-1,2-DCE	0.2JB	
trans-1,2-DCE	ND	
1,2-DCA	0.1JB	
1,1-DCA	0.2JB	
1,1-DCE	0.1JB	
PCE	0.0JB	
Vinyl Chloride	0.0J	

Sample Number 101		
Sample Date	6/16/90	
TCE	0.1JB	
1,1,1-TCA	0.0JB	
cis-1,2-DCE	ND	
trans-1,2-DCE	ND	
1,2-DCA	ND	
1,1-DCA	ND	
1,1-DCE	ND	
PCE	0.1JB	
Vinyl Chloride	ND	

Sample Nun	
Sample Date	6/12/90
TCE	0.0JB
1,1,1-TCA	0.1J
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.1JB
Vinyl Chloride	ND

Sample Number 123		
Sample Date	6/18/90	
TCE	0.0JB	
1,1,1-TCA	0.0J	
cis-1,2-DCE	ND	
trans-1,2-DCE	ND	
1,2-DCA	ND	
1,1-DCA	ND	
1,1-DCE	ND	
PCE	0.0JB	
Vinyl Chloride	ND	

Sample Number 35		
Sample Date	6/13/90	
TCE	0.0JB	
1,1,1-TCA	0.0J	
cis-1,2-DCE	0.1JB	
trans-1,2-DCE	ND	
1,2-DCA	ND	
1,1-DCA	ND	
1,1-DCE	ND	
PCE	0.0JB	
Vinyl Chloride	ND	

Sample Number 137		
5/19/90		
0.1JB		
0.1JB		
ND		
0.0JB		

Sample Number 74		
Sample Date	6/14/90	
TCE	0.0JB	
1,1,1-TCA	ND	
cis-1,2-DCE	ND	
trans-1,2-DCE	ND	
1,2-DCA	ND	
1,1-DCA	ND	
1,1-DCE	- ND	
PCE	0.1JB	
Vinyl Chloride	ND	

Sample Nur	nber 151
Sample Date	6/20/90
TCE	0.0JB
1,1,1-TCA	ND
cis-1,2-DCE	ND
trans-1,2-DCE	ND
1,2-DCA	ND
1,1-DCA	ND
1,1-DCE	ND
PCE	0.0JB
Vinyl Chloride	ND

[•] All concentrations in µg/l

situation with respect to VOC contamination, making the trip blanks a useful reference against which field blank contamination can be judged. Comparison of Tables 3-3 and 3-4 shows that VOC levels are similar for trip blanks and field blanks, suggesting that contamination during field sampling was not significant compared with trip blank contamination. Furthermore, the low levels of VOCs in the trip blanks indicate that contamination from shipping was negligible. Overall, VOC levels in field blanks were somewhat greater than trip blank VOC levels, which is not surprising given the possibility for air-borne contamination accompanying field sampling conditions.

Field duplicates were collected in order to assess the overall precision of field sampling and laboratory procedures. The Relative Percent Difference (RPD) was calculated for each duplicate pair except in cases where one or both of the concentration values fell at or below the detection limit, or where values were reported as not detected. Overall, the correlation among duplicates was good. Results for sample/field duplicate pairs and the RPDs are listed for metals and for VOCs in Tables 3-5 and 3-6, respectively.

For the metals, one or both concentrations for the sample/field duplicate pairs were frequently found to be at or below the IDL. This makes it difficult to judge the reproducibility of the metals data because the absolute concentration values can not be determined. However it should be noted that most of the duplicate pairs had both results reported as not detected, which indicates good reproducibility even though an RPD could not be calculated. Review of the analytical results listed in Table 3-5 indicates that the reported concentrations for samples and duplicates are closely matched. The RPDs for the metals duplicates were less than 30% RPD for all samples except lead at 2315 Harrison, which had a 84% RPD (Table 3-5). Such a large RPD is misleading when it occurs for a sample with low concentration because a small difference in reported values can produce large RPDs. In general, the metals duplicates indicate good reproducibility.

Table 3-7 Analytical Results for Multiple Samples (USEPA vs IDPH Data)

(All concentrations in µg/l)

2826 11th		
Sampling Agency	USEPA	IDPH
Sample Date	10/5/89	8/9/88
TCE	27.2	ND
1,1,1-TCA	68.4	ND
cis-1,2-DCE	21.3	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	22.0	ND
1,1-DCE	*	ND
PCE	*	ND
Vinyl Chloride	•	ND

3141 20th		
Sampling Agency	USEPA	IDPH
Sample Date	10/3/89	8/21/89
TCE	ND	ND
1,1,1-TCA	ND	ND
cis-1,2-DCE	ND	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	ND	ND
1,1-DCE	*	ND
PCE	*	ND
Vinyl Chloride	*	ND

2837 Cannon		
Sampling Agency	USEPA	IDPH
Sample Date	10/4/89	10/17/89
TCE	37.0	47.1
1,1,1-TCA	88.3	89.1
cis-1,2-DCE	24.1	ND
trans-1,2-DCE	ND	ND
1,2-DCA	0.5	ND
1,1-DCA	23.8	16.3
1,1-DCE	*	9.4
PCE	*	0.7
Vinyl Chloride	*	ND

2833 Kinsey		
Sampling Agency	USEPA	IDPH
Sample Date	10/5/89	9/19/89
TCE	17.8	20.9
1,1,1-TCA	62.9	81.0
cis-1,2-DCE	11.9	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	10.9	12.6
1,1-DCE	*	0.8
PCE	+	ND
Vinyl Chloride	*	ND

2722 Sewell		
Sampling Agency	USEPA	IDPH
Sample Date	10/4/89	8/9/88
TCE	2.9	0.5
1,1,1-TCA	27.5	3.2
cis-1,2-DCE	11.5	ND
trans-1,2-DCE	ND ,	ND
1,2-DCA	ND	ND
1,1-DCA	29.9	0.2
1,1-DCE	•	ND
PCE	*	ND
Vinyl Chloride	•	ND

2518 Lindberg		
Sampling Agency	USEPA	IDPH
Sample Date	10/3/89	11/6/89
TCE	3.1	4.2
1,1,1-TCA	7.7	11.2
cis-1,2-DCE	1.9	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	1.2	ND
1,1-DCE	*	1.2
PCE	*	Trace
Vinyl Chloride	•	ND

2904 Cannon		
Sampling Agency	USEPA	IDPH
Sample Date	10/4/89	9/8/88
TCE	15.5	6.4
1,1,1-TCA	35.6	56.0
cis-1,2-DCE	*	ND
trans-1,2-DCE	*	ND
1,2-DCA	ND	ND
1,1-DCA	12.4	2.0
1,1-DCE	7.7	1.4
PCE	ND	0.2
Vinyl Chloride	ND	ND

2814 20th		
Sampling Agency	USEPA	IDPH
Sample Date	10/3/89	9/26/89
TCE	120.0	121.7
1,1,1-TCA	283.0	57.5
cis-1,2-DCE	138.0	ND
trans-1,2-DCE	2.5	ND
1,2-DCA	4.0	ND
1,1-DCA	133.0	46.8
1,1-DCE	*	<1
PCE	•	15.1
Vinyl Chloride	*	ND

ND = Not Detected

^{• =} Not Analyzed for

Table 3-7 cont. Analytical Results for Multiple Samples (USEPA vs IDPH Data)

(All concentrations in µg/l)

2804 Hanson			
Sampling Agency	USEPA	IDPH	IDPH
Sample Date	10/5/89	9/13/88	6/20/89
TCE	19.1	68.0	73.4
1,1,1-TCA	201.0	98.0	204.0
cis-1,2-DCE	47.5	ND	ND
trans-1,2-DCE	0.6	ND	ND
1,2-DCA	1.0	ND	, 0.9
1,1-DCA	43.8	25.0	ND
1,1-DCE	•	3.8	52.2
PCE		3.2	3.3
Vinyl Chloride	*	ND	ND

2746 Lapey			
Sampling Agency	USEPA	USEPA	IDPH
Sample Date	10/5/89	10/5/89	9/26/89
TCE	29.9	30.0	50.0
1,1,1-TCA	158.0	160.0	224.2
cis-1,2-DCE	29.2	28.4	ND
trans-1,2-DCE	ND	ND	ND
1,2-DCA	0.8	0.8	ND
1,1-DCA	32.2	32.6	25.2
1,1-DCE	* .	•	2.7
PCE	+	•	4.1
Vinyl Chloride .	•	•	ND

2741 Cannon			
Sampling Agency	USEPA	USEPA	IDPH
Sample Date	8/9/89	10/24/89	8/9/88
TCE	35.4	36.8	140.0
1,1,1-TCA	•	158.0	140.0
cis-1,2-DCE	*	40.4	ND
trans-1,2-DCE	*	ND	ND
1,2-DCA	*	1.1	ND
1,1-DCA	320.0	38.2	. 13.0
1,1-DCE	47.8	•	2.0
PCE	1.32J	*	4.8
Vinyl Chloride	ND	•	ND

ND = Not Detected

* = Not Analyzed for

Table 3-8 Analytical Results for Multiple Samples (IEPA vs IDPH Data)

(All concentrations in μg/I)

2810 8th			
Sampling Agency	IEPA	IDPH	
Sample Date	6/14/90	12/8/89	
TCE	8.3	5.6	
1,1,1-TCA	27.9	ND	
cis-1,2-DCE	4.7	ND	
trans-1,2-DCE	0.1J	Trace	
1,2-DCA	0.3J	22.5	
1,1-DCA	4.3	Trace	
1,1-DCE	4.3	2.8	
PCE	ND	Trace	
Vinyl Chloride	ND	ND	

13	317 Brook	e
Sampling Agency	IEPA	IDPH
Sample Date	6/15/90	12/4/89
TCE	2.3B	1.0
1,1,1-TCA	4.7	3.2
cis-1,2-DCE	0.5	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	0.7	ND
1,1-DCE	0.5J	ND
PCE	ND	ND
Vinyl Chloride	ND	ND

3230 Lapey		
Sampling Agency	IEPA	IDPH
Sample Date	6/14/90	12/12/89
TCE	ND	ND
1,1,1-TCA	ND	ND
cis-1,2-DCE	ND	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	ND	ND
1,1-DCE	ND	ND
PCE	ND	ND
Vinyl Chloride	ND	ND

1812 Sandy Hollow		
Sampling Agency	IEPA	IDPH
Sample Date	6/13/90	12/5/89
TCE	ND	ND
1,1,1-TCA	ND	ND
cis-1,2-DCE	ND	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	ND	ND
1,1-DCE	ND	ND
PCE	ND	Trace
Vinyl Chloride	ND	ND

3110 18th		
Sampling Agency	IEPA	IDPH
Sample Date	6/14/90	12/11/89
TCE	ND	ND
1,1,1-TCA	3.2U	ND
cis-1,2-DCE	ND	ND
trans-1,2-DCE	ND	2.2
1,2-DCA	ND	ND
1,1-DCA	0.1J	ND
1,1-DCE	ر0.2	ND
PCE	ND	ND
Vinyl Chloride	ND	ND

3	3310 Collins							
Sampling Agency	IEPA	IDPH						
Sample Date	6/13/90	12/5/89						
TCE	0.9B	0.9						
1,1,1-TCA	2.5	2.2						
cis-1,2-DCE	ND	ND						
trans-1,2-DCE	ND	ND						
1,2-DCA	ND	ND						
1,1-DCA	0.1J	Trace						
1,1-DCE	0.1J	ND						
PCE	ND	Trace						
Vinyl Chloride	ND	ND						

16	37 Pershi	ng
Sampling Agency	IEPA	IDPH
Sample Date	6/15/90	11/6/89
TCE	1.7B	2.1
1,1,1-TCA	3.1	4.1
cis-1,2-DCE	0.1J	ND
trans-1,2-DCE	ND	ND
1,2-DCA	ND	ND
1,1-DCA	0.2J	ND
1,1-DCE	0.2J	ND
PCE	ND	ND
Vinyl Chloride	ND	ND

	3120 17th	
Sampling Agency	IEPA	IDPH
Sample Date	6/13/90	8/21/89
TCE	2.0B	1.5
1,1,1-TCA	2.8	2.7
cis-1,2-DCE	ND	ND
trans-1,2-DCE	ND	ND
1,2-DCA	0.1J	ND
1,1-DCA	0.3J	ND
1,1-DCE	0.4J	0.3
PCE	0.3J	ND
Vinyl Chloride	ND	ND

[•] ND= Not Detected, U = Not Detected in Dilution, J = Estimated Value, B = Blank Contamination

IDPH and USEPA samples, but the reported values for 1,1,1-TCA, cis-1,2-DCE, and 1,1-DCA differ by factors ranging from 3 to 276. The match between IEPA and IDPH sample analyses is somewhat better, but there are significant differences among reported concentrations for these multiple samples as well (Table 3-8). For example, at 2810 8th Street, IEPA reports a TCE concentration of 27.9 ppb, whereas IDPH reports a non-detect. At the same location, IEPA reports an estimated 1,2-DCA concentration of 0.3 ppb, whereas IDPH reports 22.5 ppb.

Given these differences in contaminant concentrations reported by different agencies for the same locations, it is clear that the three data sets considered in this investigation are not consistent, and could not be presented together. Because the QA/QC procedures, detection limits, and sample collection techniques are known to be comparable for both the IEPA and USEPA samples, the IEPA and USEPA analytical results were used together to form the primary data set for this investigation. The IDPH sample results are presented separately, and are intended to be used as supplementary data, to complement the primary IEPA/USEPA data set.

As mentioned above, there are no locations that were sampled by both IEPA and USEPA, and therefore it is not possible to directly compare the two data sets. Review of sample results for sample locations geographically close to each other (such as the IEPA and USEPA samples on Lindberg Drive, near Sawyer Road and Marshall Street, and near Lapey Street and Brooke Road) show close agreement. Therefore, the 2 data sets appear to be compatible.

3.2 VOLATILE ORGANIC CONTAMINATION

Groundwater contamination by VOCs at levels ranging from non-detect to hundreds of parts per billion has been established by analytical results from IDPH, USEPA, and IEPA samples. Contaminants of concern in the study area were identified based on previous sampling by IDPH and USEPA, as discussed in Section 2.4 of the Operable Unit Work Plan. The contaminants

of concern and detection limits associated with the analytical procedures used for the IEPA Operable Unit are listed in Table 3-9. Detection limits for analytical procedures used in this investigation are discussed in Section 5.3 of the Quality Assurance Project Plan (QAPP). Analytical results for VOCs from each of the three studies are presented in both tables and maps. VOC data generated from the IEPA Operable Unit study are presented in Table 3-10. Data from the USEPA and IDPH investigations are presented in Tables 3-11 and 3-12, respectively. To assist in locating addresses within the study area that correspond to the analytical results listed in the tables, a comprehensive address map of all addresses in the study area is included as Figure 3-1 in the map packet. Maps of IEPA/USEPA and IDPH sample locations are also included with the map packet as Figures 3-2 and 3-3, respectively.

3.2.1 DATA DISPLAY AND CONTOURING

Based on the analytical data presented in Tables 3-10 through 3-12, plume contour maps depicting the distribution and levels of groundwater contamination across the study area were prepared for each of the nine VOC contaminants of concern. The plume of VOC-contaminated groundwater is shown in the maps as a base map of the study area on which numerical values for contaminant concentrations, laboratory flags, and concentration contours are overlain. The numerical concentration values depicted on the maps are expressed in parts per billion (ppb), which have been rounded to one decimal place to facilitate display and contouring of the data. Laboratory flags displayed on the figures are discussed in the text in Subsection 3.1 and given in Table 3-1. Because of the data incompatibilities discussed in Subsection 3.1.2, the IDPH data has been presented separately from the IEPA and USEPA data.

The contouring process is interpretational, and involves extrapolating contour lines through areas that may have little or no data. As a consequence, the drawings presented with this report represent one of many possible interpretations of the actual configuration of the plume. A

Table 3-9
Contaminants Analyzed and Detection
Limits for Operable Unit Samples

		Operable Unit
Contaminant	Abbreviation	Detection Limit (ppb)
Trichloroethene	TCE	0.5
1,1,1-Trichloroethane	1,1,1-TCA	0.5
cis-1,2-Dichloroethene	cis-1,2-DCE	0.5
trans-1,2-Dichloroethene	trans-1,2-DCE	0.5
1,2-Dichloroethane	1,2-DCA	0.5
1,1-Dichloroethane	1,1-DCA	0.5
1,1-Dichloroethene	1,1-DCE	0.5
Tetrachloroethene	PCE	0.5
Vinyl Chloride		0.25
Arsenic	As	2.0
Cadmium	Cd	0.1
Chromium	Cr	10.0
Lead	Pb	1.0

Table 3-10 IEPA VOC Data

(All concentrations in µg/l)

	0000000000000	5040000000000000	100100000000000000000000000000000000000	100000000000000000000000000000000000000	\$0000000000000000000000000000000000000	\$0000000000000000000000000000000000000	000000000000000000000000000000000000000	**********************			B0000000000000000000000000000000000000		
4.33	Street	Sample	Sampling	DATE	TCE	1,1,1 TCA	ds- 1.2-DCE	trans- 1.2-DCE	1.2-DCA	1,1-DCA	1.1-DCE	PCE	Vinyl Chloride
Address 4th	Ne 2819	No.	Agency IEPA	6/11/90	17.0B	24.9B	13.6B	ND	2.6B	21.0B	7.5B	2.1B	ND
4th	2828	9	IEPA	6/11/90	18.4B	28.8B	13.1B	ND	2.2B	18.4B	8.7B	2.0B	ND
4th	2901	18	IEPA	6/12/90	29.2B	61.8	22.5	0.2J	3.2B	30.7	25.3	4.1B	ND
4th	3045	70/71	IEPA	6/14/90	36.0B	2.7	1.0	ND	ND	0.2J	0.1J	9.7B	ND
5th	2624	77	<u>IEPA</u>	6/15/90	2.8B	1.70	14.1	0.2J	ND_	0.3J	0.3J	2.1B	ND ND
7th	3115	82	IEPA	6/15/90	1.1B	3.0	0.1J ND	ND ND	ND 0.3J	ND 0.4J	ND 0.2J	1.3B 6.8B	ND ND
7th 7th	3233 3309	53 64	IEPA IEPA	6/13/90 6/14/90	1.5B ND	0.9U	ND ND	ND ND	ND	0.43 0.0J	ND	ND	ND ND
8th	2647	130	IEPA	6/18/90	10.0U	528.10	24.7_	0.9J	5.7J	533.2	109.7	10.0U	9.1
8th	2810	58	IEPA	6/14/90	8.3	27.9	4.7	0.1J	0.3J	4.3	4.3	ND	ND
8th	2914	73	IEPA	6/14/90	ND	1.8U	ND	ND	ND	0.2J	ND	15.1B	ND
8th	3022	116	IEPA	6/17/90	ND	2.1	ND.	ND	ND	0.5	ND	ND	ND
8th_	3109	120	IEPA	6/18/90	1.8B	3.3	0.1J	ND	ND ND	0.3J	0.1J	0.3J	ND
8th	3138	118	IEPA	6/17/90	2.5B	3.9	0.2J	ND	ND	0.3J	0.2J	1.0B	ND
8th	3201	46	JEPA	6/13/90	ND	0.6U_	ND_	ND	ND ND	ND	ND_	ND 10	ND
8th 8th	3237 3301	40 39	IEPA IEPA	6/13/90 6/13/90	1.0 0.6	1.5U 1.2U	ND ND	ND ND	ND ND	0.2J 0.1J	0.1J 0.0J	1.8 0.5	ND ND
8th	3337	41	IEPA	6/13/90	ND	ND	ND	ND ND	ND	ND	ND.	0.2J	ND
9th	2910	96	IEPA	6/14/90	0.4J	1.0U	0.2J	ND	ND	0.1J	ND	ND	ND
9th	3101	112	IEPA	6/18/90	2.1B	3.8	0.2J	ND	ND	0.3J	0.2J	ND	ND
9th	3210	87	IEPA	6/15/90	2.0B	3.2	0.1J	ND	ND	0.4J	0.3J	2.4B	ND
9th	3245	65	IEPA	6/14/90	ND	1.9	ND	ND	ND	0.1J	ND	ND	ND
10th	3110	56/57	IEPA	6/13/90	2.9B	5.2U	ND	ND	ND	0.2J	0.2J	ND	ND
11th	2613	127	IEPA	6/18/90	14.3B	73.3	20.5	0.2J	0.4J	13.7	7.8	ND	ND
11th	2955 3015	14	IEPA	6/11/90	1.0 3.3B	1.3U	11.2	0.1J ND	0.1J	0.1J 0.7U	0.1J	ND ND	ND
11th 11th	3119	17	IEPA IEPA	6/12/90 6/12/90	ND	6.3B ND	0.5U ND	ND ND	ND ND	ND	0.5J ND	ND ND	ND ND
11th	3237	80	IEPA	6/15/90	0.9B	2.1	ND	ND	ND	ND	ND	0.7B	ND
11th	3329	79	IEPA	6/15/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
16th	3102	52	IEPA	6/13/90	3.1B	7.0	1.5B	ND	ND	1.1	1.1	0.7B	ND
16th	3122	400	IEPA .	6/13/90	1.3B	2.9	ND	ND	ND	0.1J	0.2J	0.4J	ND
17th	2602	44	IEPA	6/13/90	1.1B	29.1	2.5B	ND_	0.2J	2.5	1.0	0.2J	ND
17th	3120	51	IEPA	6/13/90	2.0B	2.8	ND	ND	0.1J	0.3J	0.4J	0.3J	ND
18th 20th	3110 2703	61 121	IEPA IEPA	6/13/90 6/18/90	ND ND	3.2U 0.2J	ND 0.1J	ND ND	0.2J	0.1J 0.8	0.2J 0.1J	ND ND	ND ND
20th	3109	42	IEPA	6/18/90	1.2B	1.4U	ND	ND	ND	0.8 0.1J	0.1J	0.2J	ND
Barnum	505	150	IEPA	6/20/90	0.5B	0.3J	0.1J	ND	ND	ND	ND	ND	ND
Barry	426	132	IEPA	6/18/90	427.6B	6.5	99.4	0.6	ND	0.6	0.7	0.6B	ND
Bildahl	2944	141	IEPA	6/19/90	ND	ND	0.1J	ND	ND	0.3J	ND	ND	ND
Bildahl	3017	148	IEPA	6/19/90	ND ·	ND	0.1J	ND	1.6	0.9	ND	ND	ND
Bildahl	3038	92	IEPA	6/15/90	1.6	2.9	0.1J	ND	ND	0.2J	0.1J	ND	, ND
Bildahl	3122	109/110	IEPA	6/16/90	2.7B	4.2B	ND	ND	· ND	ND	ND	ND	ND
Bildahl	3141	94	IEPA	6/15/90	2.2	3.8	0.2J	ND	ND	0.4J	0.2J	2.3B	ND ND
Bildahl Bildahl	3206 3302	98	IEPA IEPA	6/16/90 6/15/90	1.9B ND	2.7B 1.0U	ND ND	ND ND	ND ND	ND ND	ND ND	2.6B ND	ND ND
Bildahl	3338	99.	IEPA	6/15/90	ND	ND	ND	ND	ND	ND	ND	ND	ND .
Brooke	110	117	IEPA	6/18/90	125.9B	1.2U	7.4	0.1J	0.1J	1.1	0.6	4.0B	ND
Brooke	202	_29	IEPA	6/12/90	ND	0.7U	ND	ND	ND	0.7U	ND	ND	ND
Brooke	326	19	IEPA	6/12/90	ND	ND	13.6	ND	ND	ND	ND	ND	ND
Brooke	409	26	IEPA	6/12/90	2.4B	3.8B	1.0U	0.1J	ND	0.6U	0.6	2.0B	ND
Brooke	823	27/28	IEPA	6/12/90	19.7B	43.0B	8.0	0.1J	1.7	12.0	5.9	ND	ND
Brooke Brooke	1101 1202	139 81	IEPA	6/19/90	0.7B	2.2B	0.1J	ND	0.3J	1.1	0.1J	ND_	ND
Brooke	1317	84	IEPA IEPA	6/15/90 6/15/90	1.6B 2.3B	4.5 4.7	0.4J 0.5	ND ND	ND ND	0.7 0.7	0.4J	ND ND	ND
Collins	2801	43	IEPA	6/13/90	2.3B 2.0B	8.6B	2.1	ND	ND ND	2.1	0.5J 1.4	<u>ND</u> 0.1J	ND ND
Collins	3029	75	IEPA	6/14/90	0.6B	1.9U	ND	ND	ND	0.4J	0.1J	ND	ND
Collins	3109	105	IEPA	6/16/90	ND	ND	ND	ND	0.1J	0.5B	ND	ND	ND
Collins	3126	108	IEPA	6/16/90	2.0B	2.9B	ND	ND	ND	ND	ND	ND	ND
Collins	3245	60	IEPA	6/14/90	ND	1.0U	ND	ND	ND	0.1J	ND	0.5J	ND
Collins	3310	50	IEPA	6/13/90	0.9B	2.5	ND	ND	ND	0.1J	0.1J	ND	ND
Energy	123	76	IEPA	6/14/90	101.6B	15.7	11.2	ND	0.5J	2.8	3.3	24.0B	ND
Grant Grant	3045 3107	106	IEPA	6/16/90 6/18/90	ND	. ND	ND ND	ND	ND	ND	ND ND	ND ND	ND
Hamilton	1630	115 124	IEPA IEPA	6/18/90	ND 1 OB	ND 3.0	ND 0.11	ND	ND	ND	ND	ND ND	ND ND
manniton	1030	1,24	IEFA	0/16/90	1.9B	3.0	0.1J	ND	ND	0.2J	0.2J	ND	ND

[•] ND = Not Detected, U = Not Detected in Dilution, J = Estimated Value, B = Blank Contamination

Table 3-10 cont. IEPA VOC Data (All concentrations in µg/l)

	Street	Sample	Sampling			1,1,1-	cts-	trans-					Vinyl
Address	No.	No.	Agency	DATE	TCE	TCA	1.2-DCE	1,2-DCE	1,2-DCA	1,1-DCA	1,1 DCE	PCE	Chloride
Hamilton	1735	2	IEPA	6/11/90	0.8	1.3U	ND	ND	ND	0.1J	0.13	ND	ND
Harrison	707	146/147	IEPA	6/19/90	41.4B	93.5B	42.6	0.2J	4.5J	43.7	34.9	10.4B	0.7
Harrison	1713	100	IEPA	6/15/90	3.3	33.4	5.8	0.1J	ND	8.0	1.5	0.7B	ND
Harrison	1817	126	IEPA	6/18/90	62.8B	990.8	22.2	0.1J	ND	16.5	25.4	1.0B	ND
Harrison	2315	47/48	IEPA	6/13/90	0.4J	10.5	0.4J	ND	0.1J	1.8	0.9	ND	ND
Horton	3129	88/89	IEPA	6/15/90	0.8B	1.9U	ND	ND	ND	ND	0.13	ND	ND
Johnson	1737	3&5	IEPA	6/11/90	ND	ND	0.2J	ND	0.2J	0.03	ND	ND	ND
Kennon	410	149	IEPA	6/19/90	ND	ND	ND	ND_	ND	ND	ND	ND	ND
Kennon	621	140	IEPA	6/19/90	6.8B	1.3B	2.4	ND	ND	0.1J	ND	545.0	ND
Kishwaukee	3037	135	IEPA	6/19/90	13.4B	5.4B	1.3	ND	0.43	2.0	1.4	ND	ND
Kishwaukee	3202	90	IEPA	6/15/90	ND	3.4	ND	ND	ND	ND	ND	0.4J	ND
Kishwaukee	3239	66	IEPA	6/14/90	ND	1.8U	ND	ND	0.2J	0.2J	0.1J	_1.8B	ND
Kishwaukee	3302	67	IEPA	6/14/90	ND	2.5	ND	ND_	ND	ND	ND	1.2B	ND
Kishwaukee	3333	131	IEPA	6/18/90	1.3B	0.9U	0.2J	ND	0.0J	1.4	0.7	ND	ND
Lapey	3013	142/143	IEPA	6/19/90	2.2B	4.3B	0.3J	ND	ND	0.5J	0.3J	0.6B	ND
Lapey	3101	104	IEPA	6/16/90	1.8Б	2.8B	ND	ND	ND	ND	ND	ND	ND
Lapey	3138	103	IEPA	6/16/90	2.7B	4.0B	ND	ND	ND	0.4J	ND	ND	ND
Lapey	3213	97	IEPA	6/15/90	1.4	2.6U	0.1J	ND	ND	0.2J	ND	ND	ND
Lapey	3230	69	IEPA	6/14/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Lapey	3329	72	IEPA	6/14/90	ND	0.7U	ND	ND	ND	ND	ND	ND	ND
Lindale	2406	38	IEPA	6/13/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Lindale	2620	21	IEPA	6/12/90	1.1B	1.7	ND ·	ND	ND	ND	ND	0.9B	ND
Lindberg	2412	22	IEPA	6/12/90	1.6B	ND	ND	ND	ND	1.3	0.3J	ND	ND
Lindberg	2619	59	IEPA	6/14/90	3.2B	5.8U	1.1B ·	ND	0.2J	0.9	0.8	0.6B	ND
Lyran	1617	10	IEPA	6/11/90	ND	1.2U	ND	ND	ND	ND	ND	1.1B	ND
Lyran	1701	12	IEPA	6/12/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Marshall	3106	63	IEPA	6/14/90	ND	ND	ND	ND	ND	0.2J	0.1J	ND	ND
Marshall	3137	83	_IEPA	6/15/90	1.8B	3.4	0.1J	ND	ND	0.3J	0.3J	ND	ND
Martin	430	54	IEPA	6/13/90	4.8B	0.9U	2.0B	ND	0.3J	0.1J	0.3J	4.7B	ND
Mattis	827	24	IEPA	6/12/90	31.9B	59.5	17.0	0.1J	2.8B	26.9	20.1	3.2B	ND
New Milford	608	138	IEPA	6/18/90	13.8B	10.0B	0.5J	ND	ND	0.6	1.2	4.6B	ND
Olsen	2820	20	IEPA	6/12/90	10.2B	ND	2.0	ND	ND.	ND	ND	127.3	ND
Pershing	1637	86	IEPA	6/15/90	1.7B	3.1	0.1J	ND	ND	0.2J	0.2J	ND	ND
Pershing	1726	85	IEPA	6/15/90	2.1B	4.1	0.5J	ND	ND	0.5J	0.4J	ND	ND
Ranger	801	6	IEPA	6/12/90	21.4B	31.6B	14.4B	ND	2.8B	21.6B	11.4B	2.1B	0.1J
River Blvd.	3007	16	IEPA	6/12/90	111.4B	1.2U	13.4B	ND	ND	1.0U	0.6B	1.4B	ND
River Blvd.	3110	136	IEPA	6/19/90	ND	ND	0.2J	ND	ND	0.2J	ND	ND	ND
River Blvd.	3117	113/114	IEPA	6/17/90	ND	ND	0.3J	ND	ND	0.2J	ND	ND	ND
Rock River	508	30	IEPA	6/12/90	170.8B	12.5U	1233.0B	12.5U	12.5U	12.5U	12.5U	12.5U	113.5
Roosevelt	841	128	IEPA	6/18/90	0.9B	2.4	0.1J	ND	ND	0.3J	0.2J	2.4B	ND
Sandy Hlw	728	102	IEPA	6/16/90	ND	0.7U	ND	ND	ND	ND	ND	ND	ND
Sandy HIW	810	125	IEPA	6/18/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sandy HIW	1202	122	IEPA	6/18/90	ND	ND	ND	ND	ND	ND	ND	0.3J	ND
Sandy HIW	1306	49	IEPA	6/13/90	ND	ND	ND	ND	ND	ND	ND	0.2J	ND
Sandy HIW	1812	37	IEPA	6/13/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Saner	2905	25	IEPA	6/12/90	1.7B	1.8B	0.7U	0.1J	ND	ND	0.4J	1.0B	ND
Saner	3014	134	IEPA	6/18/90	0.7B	2.0B	0.1J	ND	ND	0.4J	0.2J	2.8B	ND
Saner	3110	78	IEPA	6/15/90	ND	1.0U	ND	ND	ND	ND	ND	ND	ND
Sawyer	319	36	IEPA	6/13/90	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sewell	2646	144	IEPA	6/19/90	0.7	39.3	0.2J	ND	ND	1.5	1.2	ND	ND
Sewell	3135.5	93	IEPA	6/15/90	ND	0.5U	ND	ND	ND	ND	ND	ND	ND
South	619	15	IEPA	6/12/90	18.2B	71.1	2.1	0.0J	ND	ND	3.2	ND	ND
Taft	804	129	IEPA	6/18/90	ND	1.4	ND	ND	ND	0.1J	ND	1.1B	ND
				-1-01/0						U. 2.12	1717	1110	

[•] ND = Not Detected, U = Not Detected in Dilution, J = Estimated Value, B = Blank Contamination

Table 3-11 USEPA VOC Data

(All concentrations in μg/l)

			*****************	KAROKERONOMERTERAKAA	**************************************	50.000 SOP SOP SOP SOP OF SOR	930000000000000000000000000000000000000	800000000000000000	60000000000000000000000000000000000000	***************************************	500000000000000000000000000000000000000	BAGGAAAAAAAA	loocommonatainesia
443	Street No.	Sampling Agency	Sample No.	DATE 1989	TCE	1,1,1. TCA	cis- 1,2-DCE	trans- 1,2-DCE	1.2-DCA	1.1-DCA	1.1.DCE	PCE	Vinyl Chloride
Address 9th	3021	USEPA	S80	10/5/89	ND	3.0J	NA	NA	ND	ND	ND	ND	ND
9th	3226	USEPA	S81	10/5/89	0.6	2.0	ND	ND	ND	ND	NA	NA	NA
9th	3329	USEPA	S82	10/5/89	ND	0.6	ND	ND	ND	ND	NA_	NA	NA
10th	2730	USEPA	S9	10/26/89	28.0	142.0	29.6	ND	ND	31.3	NA	NA	NA
10th	3141	USEPA	S69	10/5/89	2.0	4.3	ND	ND	ND	_ ND	NA_	_NA	NA
11th	2718	USEPA	S14	10/26/89	34.8	167.0	42.9	ND	ND	40.4	NA_	NA	NA
11th	2822	USEPA	S15	10/26/89	9.9	54.5	7.2	ND	ND	8.3	NA	NA	NA
11th	2826	USEPA	S68	10/5/89	27.2	68.4	21.3	ND	ND	22.0	NA	NA	NA
11th	2902	USEPA	S72	10/5/89	10.5	35.2	5.2	_ND_	ND_	4.8	NA	NA	NA
11th	2929	USEPA	S75	10/5/89	3.4	13.2	2.4	ND	ND_	2.0	NA	NA	NA NA
17th	3118	USEPA	S13	10/3/89	1.3	2.5	ND	ND	ND	ND	_NA_	_NA	NA
18th	2701	USEPA	S16	10/26/89	1.4	7.6	5.2	ND	ND_	10.1	NA_	NA	NA
18th	3025	USEPA	S12	10/3/89	2.7	9.3	3.3	ND	ND_	1.8	NA	NA_	NA
19th	3112	USEPA	S10	10/3/89	0.8	1.1	ND_	ND	ND_	_ND	NA	NA	NA_
20th	2814	USEPA	S11	10/3/89	120.0	283.0	138.0	2.5	4.0	133.0	NA_	NA	NA_
20th	2917	USEPA	S100	10/24/89	16.3	88.4	29.8	ND	ND_	18.2	NA_	NA	NA NA
20th	3015	USEPA	S102	10/24/89	2.2	11.3	2.5	ND	ND	ND	NA.	NA	NA.
20th	3141	USEPA	S9	10/3/89	ND_	ND 207.0	ND_	ND	ND_	ND 91.0	NA_	NA	NA NA
21st	2816	USEPA	S95	10/24/89	68.4	297.0	96.4	1.2	1.5	81.9	NA	NA	NA
21st	2825	USEPA	S97	10/24/89	73.8	306.0	95.0	ND	ND_	64.3	NA.	NA	NA
21st	2922	USEPA	S6	10/3/89	31.7	151.0	94.6	ND NA	2.0	40.7 109.0	NA 42.2	NA CZ	NA
22nd	2826	USEPA	S5	10/3/89	67.1	227.0	NA 37.9	ND ND	4.0J		43.2	6.7	ND
22nd	2901	USEPA USEPA	S98	10/24/89	56.2	235.0 75.7	37.8 42.3	ND ND	ND 0.6	33.9 25.6	NA NA	NA	NA NA
22nd	2923		S94 S93	10/24/89	17.0 91.3	384.0	113.0	1.2	0.6 2.1	76.1	NA NA	NA NA	NA NA
23rd 23rd	2817 2830	USEPA USEPA	S93	10/24/89 10/24/89	68.7	261.0	95.2	0.9	1.4	61.2	NA NA	NA	NA NA
23rd	2911	USEPA	S91	10/24/89	65.6	343.0	273.0	1.3	2.9	103.0	NA NA	NA	NA NA
24th	2827	USEPA	_S88	10/24/89	104.0	245.0	NA	NA	2.2J	85.3	42.7	6.6	ND
24th	2917	USEPA	S89	10/24/89	79.3	397.0	323.0	1.6	2.8	117.0	NA	NA	NA
24th	2935	USEPA	S90	10/24/89	17.4	122.0	93.9	ND	1.0	41.7	NA	NA	NA
Alton	1621	USEPA	S73	10/5/89	32.7	162.0	NA	NA	1.8J	57.0	27.6	ND	ND
Bildahl	2717	USEPA	S18	10/24/89	25.1	132.0	27.5	ND	ND	29.8	NA	NA	NA
Brooke	220	USEPA	S20	12/8/89	ND	ND	ND	ND	ND	ND	NA	NA	NA
Cannon	2637	USEPA	S17	10/26/89	2.2	39.6	3.8	ND	ND	6.8	NA	NA	NA
Cannon	2729	USEPA	S105	10/24/89	44.0	168.0	NA	NA	1.5J_	71.2	29.5	ND	ND
Cannon	2741	USEPA	S104	10/24/89	36.8	158.0	40.4	ND	1.1	320.0	47.8	1.3J	ND
Cannon	2741	USEPA	S10	8/9/89	36.8	158.0	40.4	ND	1.1	320.0	47.8	1.3J	ND
Cannon	2822	USEPA	S52	10/4/89	24.6	140.0	42.0	ND	0.8	47.9	NA	NA	NA
Cannon	2837	USEPA	S51	10/4/89	37.0	88.3	24.1	ND	0.5	23.8	NA	NA	NA
Cannon	2904	USEPA	S54	10/4/89	15.5	35.6	NA	NA	ND	12.4	7.7	ND	ND
Cannon	2934	USEPA	S55	10/4/89	9.4	33.5	5.4	ND	ND	4.2	NA	NA	NA
Cannon	3008	USEPA	S56	10/4/89	3.3	13.2	3.1	ND	ND	2.2	NA	NA	NA
Carlson	3007	USEPA	S22	12/8/89	1.4	ND_	1.9	ND	ND	ND	NA_	NA	NA
Carlson	3113	USEPA	S21	12/8/89	21.9	0.6	1.9	ND	ND	ND	NA	NA	NA
Hamilton	1724	USEPA	S47	10/3/89	ND	2.1J	NA_	NA	ND_	ND	ND	ND	NA
Hanson	2737	USEPA	S106	10/24/89	24.8	109.0	26.3	ND	ND_	24.9	NA_	NA	NA.
Hanson	2745	USEPA	S4	10/3/89	41.8	172.0	42.6	ND	1.9	49.1	NA_	NA	NA NA
Hanson	2804	USEPA	.S61	10/5/89	19.1	201.0	47.5	0.6	1.0	43.8	NA NA	NA	NA NA
Hanson	2833 2846	USEPA USEPA	S60 S59	10/5/89 10/5/89	23.9 28.3	52.8	17.6	ND ND	ND	17.8	NA NA	NA NA	NA NA
Hanson Hanson	2913	USEPA	S58	10/5/89		75.0 28.3	20.8 5.3	ND	ND ND	18.8	NA NA	NA NA	NA NA
Hanson	2930	USEPA	\$38 \$3	10/3/89	10.6 6.0	18.5	3.1	ND	ND	4.4 2.7	NA NA	NA NA	NA NA
Hanson	2941	USEPA	S15	10/3/89	26.4	57.4	19.7	ND	1.3	22.0	NA NA	NA NA	NA NA
Harson	3000	USEPA	S57	10/5/89	2.8	11.2	2.5	ND	ND	1.8	NA	NA	. NA
Horton	2725	USEPA	S22	10/3/89	11.4	45.4	39.6	ND	1.4	57.8	NA NA	NA NA	NA NA
Horton	2806	USEPA	S21	10/3/89	40.0	197.0	50.6	0.8	2.8	42.4	NA NA	NA	NA
Horton	2806	USEPA	S20	10/3/89	52.4	255.0	66.1	0.8	2.9	55.3	NA	NA	NA
Horton	2817	USEPA	S19	10/3/89	67.8	305.0	65.5	0.7	2.4	58.8	NA	NA	NA

[•] ND = Not Detected, NA = Not Analyzed, J = Estimated Value

Table 3-11 cont. USEPA VOC Data

(All concentrations in $\mu g/I$)

	Street	Sampling	Sample	DATE		1,1,1-	cis-	trans.					Vinyl
Address	No.	Agency	No.	1989	TCE	TCA	1,2-DCE	1,2-DCE	1,2-DCA		1,1-DCE	PCE	Chloride
Horton	2833	USEPA	S18	10/3/89	59.4	142.0	NA	NA	1.3J	47.0	28.6	2.6J	ND
Horton	2904	USEPA	S16	10/3/89	25.0	60.0	19.0	ND	1.3	21.3	NA	NA	NA
Horton	2914	USEPA	S17	10/3/89	44.0	147.0	40.3	ND	1.6	40.0	NA	NA	NA
Horton	2921	USEPA	S101	10/24/89	22.9	75.5	19.8	ND	ND	15.6	NA	NA	NA
Johnson	1625	USEPA	S48	10/4/89	ND	ND	ND	ND	ND	ND	NA_	NA_	NA
Kinsey	2614	USEPA	S71	10/5/89	1.2	16.7	3.4	ND	ND	9.9	NA	NA	NA
Kinsey	2712	USEPA	S67	10/5/89	33.4	156.0	39.7	ND_	1.5	38.0	NA 07.6	NA	NA ND
Kinsey	2733	USEPA	S11	8/9/89	31.8	NA_	NA	NA	NA	213.0	27.5	0.7J	ND
Kinsey	2815	USEPA	S66	10/5/89	33.7	133.0	27.7	ND	0.6	33.8	NA	NA	NA
Kinsey	2833	USEPA	S65	10/5/89	17.8	62.9	11.9	ND	ND	10.9	NA	NA	NA
Kinsey	2901	USEPA	S64	10/5/89	5.6	18.1	2.6	ND	ND	2.6	NA	NA	NA
Kinsey	2917	USEPA	S63	10/5/89	1.9	7.3	0.9	ND	ND	0.9	NA	NA	NA
Kinsey	2946	USEPA	S62	10/5/89	2.7	5.4	1.9	ND	ND	1.5	NA.	NA	NA
Lapey	2706	USEPA	S10	10/26/89	58.9	143.0	NA	NA	1.9J	56.6	31.0	ND	ND
Lapey	2734	USEPA	S11	10/26/89	17.4	21.0	23.5	ND	ND	27.1	NA	NA	NA
Lapey	2746	USEPA	S86	10/5/89	29.9	158.0	29.2	ND	0.8	32.2	NA	NA	NA
Lapey	2746	USEPA	S87	10/5/89	30.0	160.0	28.4	ND	0.8	32.6	NA	NA	NA
Lapey	2814	USEPA	S12	10/26/89	16.3	65.4	14.0	ND	ND	14.2	NA	NA	NA
Lapey	2825	USEPA	S85	10/5/89	18.1	136.0	NA	NA	ND	1.9J	8.6	ND	ND
Lapey	2845	USEPA	S74	10/5/89	13.3	. 47.3	7.4	ND	ND	7.0	NA	NA	NA
Lapey	2911	USEPA	S76	10/5/89	3.6	14.2	2.1	ND	ND	1.9	NA	NA	NA
Lapey	3002	USEPA	S77	10/5/89	2.3	7.4	0.6	ND	ND	0.7	NA	NA	NA
Lapey	3031	USEPA	S79	10/5/89	1.4	4.8	ND	ND	ND	ND	NA	NA	NA
Lapey	3305	USEPA	S83	10/5/89	ND	ND	ND	ND	ND	ND	NA	NA	NA
Lindale	2512	USEPA	S 7	10/3/89	0.9	1.3	ND	ND	ND	ND	NA	NA	NA
Lindberg	2518	USEPA	<u>S8</u>	10/3/89	3.1	7.7	1.9	ND	ND	/1.2	NA	NA	NA
Marshall	2706	USEPA	S34	10/4/89	11.3	54.8	26.8	ND	1.0	39.9	NA	NA	NA
Marshall	2717	USEPA	S33	10/4/89	1.1	16.0	5.6	ND	ND	17.9	NA	NA	NA
Marshall	2738	USEPA	S32	10/4/89	65.6	329.0	93.0	1.1	2.5	75.3	NA	NA	NA
Marshall	2801	USEPA	S31_	10/4/89	62.4	310.0	74.7	0.8	2.0	61.2	NA	NA	NA.
Marshall	2837	USEPA	S30	10/4/89	39.4	156.0	40.2	ND	1.4	40.8	NA	NA	NA
Marshall	2905	USEPA	S29	10/4/89	38.3	113.0	31.5	ND	0.9	26.0	NA	NA	NA
Marshall	2925	USEPA	S103	10/24/89	19.1	44.4	14.4	ND	ND	12.5	NA	NA	NA
Marshall	2941	USEPA	S28	10/4/89	10.5	30.3	6.8	ND	ND	5.0	NA	NA	NA
Marshall	3006	USEPA	S27_	10/4/89	10.6	13.5	7.6	ND	1.3	12.5	NA	NA	NA
Marshall	3030	USEPA	S26	10/4/89	5.9	3.1	3.8	ND	2.0	9.1	NA	NA	NA
Marshall	3111	USEPA	S25	10/4/89	1.4	2.6	ND	ND	ND	ND	NA	NA	NA
Marshall	3133	USEPA	S24	10/4/89	1.8	3.2	ND	ND	ND	ND	NA	NA	NA
New Milford	606	USEPA	S25	12/8/89	21.7	37.2	0.7	ND	ND	0.9	_NA	NA	NA
Potter	3318	USEPA	S45	10/4/89	ND	ND	ND	ND	ND	ND	NA	NA	NA
Ranger	823	USEPA	S24	12/8/89	17.5	41.3	12.9	ND	1.9	16.3	NA	NA	NA
Sandy Hlw	2106	USEPA	S84	10/5/89	ND	ND	ND	ND	ND	ND	NA	NA	_NA
Sewell	2702	USEPA	S1	10/3/89	1.5	15.6	4.7	ND	ND	14.7	NA	NA	NA
Sewell	2722	USEPA	S44	10/4/89	2.9	27.5	11.5	ND	ND	29.9	NA	NA	NA
Sewell	2742	USEPA	S43	10/4/89	0.5	5.8	0.6	ND	ND	0.8	NA	NA	NA
Sewell	2806	USEPA	S41	10/4/89	40.5	222.0	NA	NA	1.6J	47.3	26.0	2.3J	ND
Sewell	2813	USEPA	S42	10/4/89	38.8	227.0	41.4	ND	1.7	44.0	NA	NA	NA
Sewell	2841	USEPA	S40	10/4/89	24.2	106.0	35.3	ND	1.1	36.7	NA	NA	NA
Sewell	2922	USEPA	S2	10/3/89	18.6	49.5	14.1	ND	ND	11.8	NA	NA	NA
Sewell	3002	USEPA	_S39	10/4/89	9.5	26.4	5.9	ND	ND	4.1	NA	NA	NA
Sewell	3032	USEPA	S38	10/4/89	2.6	9.0	2.1	ND	ND	1.4	NA	NA	NA
Sewell	3131	USEPA	S37	10/4/89	ND	ND	ND	ND	ND	ND	NA	NA	NA
Sewell	3141	USEPA	S36	10/4/89	ND	ND	ND	ND	ND	ND	NA	NA	NA

[•] ND = Not Detected, NA = Not Analyzed, J = Estimated Value

Table 3-12 IDPH VOC Data

(All concentrations in µg/l)

	Street	Sampling			1,1,1.	cis-	trans-					Vinyl
Address	No.	Agency	DATE	TCE	TCA	1,2-DCE	1,2-DCE	1,2-DCA	1,1-DCA	1,1-DCE	PCE	Chloride
7th	3133	IDPH	12/4/89	0.6	1.7	ND	ND	ND	ND	ND	0.2	NI
7th	3209	IDPH	12/4/89	0.9	2.9	ND	ND		ND	ND	3.3	NI
7th	3217	IDPH	12/4/89	0.2	1.2	ND	ND	ND	ND	ND	0.9	NE
7th	3241	IDPH	12/4/89	ND	0.4	ND	ND	ND	ND	ND	0.7	NE
7th	3317	IDPH	12/8/89	0.9	2.0	ND	ND	ND	ND	ND	Trace	NE
8th	2810	IDPH	12/8/89	5.6	ND	ND	Trace	22.5	Ттасе	2.8	Trace	NE
8th	2922	IDPH	9/19/89	1.0	9.3	ND	ND		ND	ND	ND	NE
8th	2929	IDPH	12/5/89	2.6	2.9	ND	ND	ND	Trace	ND	Trace	NE
8th	2940	IDPH	9/19/89	2.0	8.5	ND	ND	ND	ND	ND	ND	NE
8th	3219	IDPH	8/9/88	2.8	4.8	ND	ND		ND	0.1	14.0	ND
8th	3330	IDPH	12/12/89	ND	ŅD	ND	ND	1.3	ND	ND	ND	ND
9th	2726	IDPH	9/19/89	44.2	217.0	ND	ND	ND	24.2	1.3	ND	NE
9th	2905	IDPH	10/25/89	3.2	7.9	ND	ND	ND	ND	0.6	<1	ND
9th	3018	IDPH	12/8/89	ND	ND	ND	ND	0.6	ND	ND	Trace	NE
9th	3110	IDPH	11/7/89	1.7	3.0	ND	ND	ND	ND	ND	ND	ND
9th	3121	IDPH	11/7/89	2.0	3.0	ND	ND	ND	ND	ND	0.4	ND
9th	3125	IDPH	12/14/89	1.5	ND	ND	ND	2.4	ND	ND	Trace	ND
9th	3137	IDPH	12/4/89	1.4	ND	ND	ND	3.9	ND	ND	1.0	ND
9th	3214	IDPH	12/5/89	1.7	2.6	ND	ND	ND	Ттасе	ND	Trace	ND
9th	3238	IDPH	12/12/89	ND	ND	ND	ND	1.7	ND	ND	Trace	ND
9th	3242	IDPH	12/5/89	0.6	1.8	ND	ND	ND	ND	ND	Trace	ND
9th	3321	IDPH	12/12/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
9th	3326	IDPH	12/12/89	ND	ND	ND	ND	ND	ND	ND	Trace	ND
10th	3125	IDPH	12/4/89	ND	2.8	ND	ND	ND	ND	ND	ND	ND
10th	3142	IDPH	12/4/89	2.1	2.8	ND	ND	ND	ND	ND	1.5	ND
10th	3201	IDPH	12/5/89	2.1	3.4	ND	ND	ND	Trace	Trace	Trace	ND
10th	3209	IDPH	12/12/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
10th	3210	IDPH	12/12/89 8/9/88	1.5	2.6	ND	ND	ND	Trace	Trace	Trace	ND
10th 10th	3221 3236	IDPH IDPH		ND 0.9	1.7	ND ND	ND ND	ND ND	ND Trace	ND ND	0.7	ND ND
10th	3236	IDPH	12/12/89 12/5/89	0.9	1.7	ND	ND	ND	ND	ND ND	Trace	
11th	2706	IDPH	9/12/89	65.7	352.6	ND ND	11.6	ND ND	40.6	50.4	Trace 1.6	ND ND
	2707	IDPH	12/12/89		5.9	ND		0.5				ND ND
11th 11th	2734	IDPH	12/12/89	1.6. 55.4	152.8	ND	Trace Trace	1.6	Trace Trace	2.5 30.0	Trace Trace	ND
	2744	IDPH	12/12/89									ND
11th 11th	2826	IDPH	8/9/88	57.7 ND	158.8 ND	ND ND	Trace ND	1.6 ND	Trace ND	30.0 ND	Trace ND	ND
11th	2834	IDPH	12/12/89	18.6	41.7	ND	ND ND	0.5	Trace	ND	Trace	ND
11th	2837	IDPH	12/12/89	17.0	37.0	ND ND	Trace	ND	Ттасе	4.8	Trace	ND ND
11th	2842	IDPH	12/12/89	14.8	29.8	ND	Trace	ND	Trace	3.6	Trace	ND
11th	2901	IDPH	12/12/89	9.3		ND	ND		Trace	Trace	Trace	ND
11th	2926	IDPH	12/12/89	4.4	10.5	ND	Trace	ND	Trace	1.0	Trace	ND
11th	2942	IDPH	12/12/89	3.6	9.7	ND	Trace	ND	Trace	1.0	ND	ND
11th	3132	IDPH	12/12/89	2.1	3.2	ND	ND	ND	Trace	ND	Trace	, ND
16th	3146	IDPH	11/28/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
17th	3012	IDPH	12/5/89	5.0	21.8	ND	Trace	ND	Trace	2.4	Trace	ND
17th	3110	IDPH	11/6/89	1.0	1.9	ND	ND	ND	ND	ND	Trace	ND
17th	3120	IDPH	8/21/89	1.5	2.7	ND	, ND	ND	ND	0.3	ND	ND
17th	3141	IDPH	11/6/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
18th	2601	IDPH	10/25/89	1.0	29.4	ND	ND	ND	1.8	1.8	<1	ND
18th	2603	IDPH	10/25/89	1.3	38.9	ND	ND	ND	3.2	ND	<1	ND
18th	2604	IDPH	10/25/89	ND	<1	ND	ND	ND	ND	ND	ND	ND
18th	2606	IDPH	10/25/89	<1	ND	ND	ND	ND	1.8	ND	ND	ND
18th	3007	IDPH	11/7/89	17.8	49.4	ND	ND	ND	11.0	4.7	4.5	ND
18th	3035	IDPH	11/6/89	2.7	8.8	ND	ND	ND	Trace	Trace	Trace	ND
18th	3110	IDPH	12/11/89	ND	2.2	ND	ND	ND	ND	ND	ND	ND
18th	3117	IDPH	11/28/89	0.7	1.3	ND	ND	ND	ND	ND	ND	ND
18th	3146	IDPH	8/21/89	. ND	ND	ND	ND	ND	ND	ND	ND	ND
19th	2908	IDPH	9/19/89	45.3	192.4	ND	ND	ND	13.7	1.3	ND	ND

174

(All concentrations in $\mu g/l$)

200000000000000000000000000000000000000	000000000000000	000000000000000000000000000000000000000	. 9000000000000000000000000000000000000		000000000000000000000000000000000000000	00000000720000000	100000000000000000000000000000000000000	***************************************	***************************************		200000000000000000000000000000000000000	
	Street	Sampling	the grap	TCE	LLI- TCA	cis-	trans-	1100		1.1-DCE	PCE	Vinyt Chloride
Address	No.	Agency	DATE		***************************************	1,2-DCE ND	1,2-DCE ND	1,2-DCA ND	1,1-DCA ND	ND	0.6	ND
19th	3019	IDPH IDPH	11/28/89 11/28/89	2.0 ND	4.5 ND	ND ND	ND	ND	ND	ND	ND	ND
19th	3101	IDPH		ND	ND	ND ND	ND	ND	ND	ND	ND	ND
19th	3114		11/28/89	1.4	2.5	ND	ND ND	ND	ND	ND	Trace	ND
19th	3117	IDPH IDPH	11/6/89 11/28/89	0.5	ND	ND	ND ND	ND	ND	ND	ND	ND
19th	3120			ND			ND	ND ND	ND ND	ND	ND ND	ND
19th	3121	IDPH	11/28/89	ND ND	ND ND	ND ND	ND	ND ND	ND ND	ND	ND	ND ND
19th	3129	IDPH	8/21/89		57.5		ND	ND	46.8			ND ND
20th	2814	IDPH	9/26/89	121.7		ND	ND ND	ND	19.5	<1 4.0	15.1	ND
20th	2822	IDPH	9/26/89	112.5	436.0	ND				2.2	1.9	
20th	2913	IDPH	9/26/89	44.0	204.8	ND	ND	ND ND	19.2		6.5 3.8	ND ND
20th	2923	IDPH	9/26/89	8.2	83.1	ND	ND		3.1 8.0	<1		
20th	2930	IDPH	9/26/89	21.5	164.8	ND	ND	ND		1.4	1.5	ND
20th	3024	IDPH	11/28/89	0.9	0.6	ND	ND	ND	ND	ND	ND	ND
20th	3025	IDPH	11/6/89	4.1	18.0	ND	ND	0.4	2.4	ND	2.1	ND
20th	3025	IDPH	11/28/89	4.3	15.4	ND	ND	ND	2.8	ND	1.8	ND
20th	3110	IDPH	12/4/89	2.9	2.3	ND	ND	ND	ND	ND	ND	ND
20th	3141	IDPH	8/21/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
21st	2923	IDPH	9/26/89	31.4	89.3	ND	ND	ND	2.3	1.3	6.8	ND
21st	2944	IDPH	9/26/89	19.9	95.3	ND	ND	ND	6.7	<1	5.8	ND
23rd	2912	IDPH	9/26/89	97.1	436.0	ND	ND	ND	34.4	3.1	4.3	ND
23rd	2927	IDPH	9/26/89	9.0	68.1	ND	ND	ND	5.5	<1	ND	ND
23rd	2929	IDPH	10/17/89	4.7	32.4	ND	ND	ND	14.8	4.7	ND	ND
23rd	2931	IDPH	9/26/89	7.0	82.2	ND	ND	ND	6.0	<1	ND	ND
23rd	3115	IDPH	11/7/89	ND	ND	ND	ND	ND	ND	ND	Trace	ND
Alton	2118	IDPH	10/25/89	2.7	20.4	ND	ND	ND	6.4	0.7	1.3	ND
Bildahl	3029	IDPH	12/4/89	0.3	ND	ND	ND	ND	ND	ND	ND	ND
Bildahl	3221	IDPH	12/4/89	1.3	1.3	ND	ND	ND	ND 0.5	ND	ND	ND
Bildahl	3237	IDPH	12/4/89	0.8	1.0	ND	ND	ND	0.5	ND	ND	ND
Bildahl	3242	IDPH	1/10/89	2.0	2.5	ND	ND	ND	ND	ND	<1	ND
Bildahl	3318	IDPH	12/12/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Bildahl	3324	IDPH	12/12/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Brooke	1004	IDPH IDPH	12/5/89	0.5	1.9	ND	ND	ND	Trace	ND	Trace	ND
Brooke	1113	 	12/5/89	0.8	2.6	ND	ND	ND	ND	ND	ND	ND
Brooke	1317 2741	IDPH IDPH	12/4/89	1.0	3.2	ND	ND ND	ND ND	ND 13.0	ND 20	ND	ND
Cannon		}	8/9/88	140.0	140.0 97.5	ND			13.0		4.8	ND
Cannon	2801	IDPH IDPH	10/17/89	30.5	200.0	ND	ND ND	ND	28.5	11.4	1.1	ND
Cannon	2802 2810	IDPH	9/12/89 9/12/89	52.7	283.2	ND	ND ND	9.0 7.2	39.2 36.9	51.1	6.6	ND ND
Cannon				60.6		ND		ND		41.8	5.3	
Cannon	2817 2826	IDPH IDPH	9/12/89 8/21/89	20.7 31.0	83.5 177.0	ND 23.0	ND ND	1.8	24.0 34.0	24.7 25.0	0.8	ND ND
	2826	IDPH			89.1		ND ND				1.2	
Cannon	2842	IDPH	10/17/89 9/8/88	47.1 40.0	86.0	ND ND	ND ND	ND ND	16.3 11.0	9.4	0.7	ND ND
Cannon	2904	IDPH		6.4	56.0	ND ND	ND ND	ND ND	2.0	1.4	0.9	ND
Cannon	2904	IDPH	9/8/88 10/17/89	14.3	49.4	ND ND	ND	ND	5.8	3.4	0.2	ND
Cannon	2913	IDPH	11/7/89	16.2	38.8	ND ND	ND ND	ND ND	4.8	ND	ND	ND ND
Cannon	3004	IDPH	11/28/89	6.3	14.7	ND	ND	ND	1.5	ND	-	ND ND
Collins	3201	IDPH	12/4/89	2.8	4.7	ND ND	ND ND	ND ND	ND	ND ND	ND 4.8	ND ND
Collins	3201	IDPH	12/4/89	1.1	3.7	ND	ND	ND ND	ND ND	ND ND	6.5	ND
Collins	3230	IDPH	12/4/89	0.4	1.3	ND	ND	ND	ND	ND	1.5	ND ND
Collins	3234	IDPH	12/4/89	0.4	ND	ND	ND	ND	ND ND	ND ND	0.8	ND ND
Collins	3310	IDPH	12/5/89	0.0		ND ND	ND	ND	Trace	ND ND	Trace	ND ND
Collins	3317	IDPH	12/12/89	1.1	2.7	ND	Trace	ND	ND	ND	Trace	ND ND
Hamilton	1709	IDPH	11/6/89	0.6	1.6	ND	ND	ND	ND	ND	Trace	ND
Hamilton	1717	IDPH	11/6/89	1.0	1.8	ND	ND	ND	ND	ND	Trace	ND
Hanson	2633	IDPH	9/12/89	2.7	13.9	ND	ND	ND	ND	14.0	0.9	ND
Hanson	2714	IDPH	10/17/89	28.3	141.0	ND	ND	ND	65.4	17.2	0.3	- ND
Hanson	2802	IDPH	9/12/89	68.5	287.5	ND	ND	8.4	39.6	48.0	3.3	ND
Hanson	2804	IDPH	9/13/88	68.0	98.0	ND	ND	ND	25.0	3.8	3.2	ND
			2,13,00	50.0	70.0	שוו	112	עזי	ال.ب	اه.د	اء.د	עיי

5-13.9

574.9

(All concentrations in µg/l)

	Street	Sampling			1,1,1-	cis-	front-	800000000000000000000000000000000000000			800000000000000000000000000000000000000	Vinyl
Address	No.	Agency	DATE	TCE	TCA	12-DCE	1.2-DCE	1.2-DCA	1.1-DCA	1.1-DCE	PCE	Chloride
Hanson	2804	IDPH	6/20/89	73.4	204.0	ND	ND	0.9	ND	52.2	3.3	ND
Hanson	2821	IDPH	9/12/89	40.0	200.0	ND	ND	ND	28.2	32.3	1.6	ND
Hanson	2834	IDPH	9/19/89	29.6	105.8	ND	ND	ND	10.2	0.7	ND	ND
Hanson	2842	IDPH	9/19/89	32.6	101.0	ND	ND	ND	10.9	2.9	ND	ND
Hanson	2901	IDPH	9/26/89	20.3	49.3	ND	ND	ND	5.4	<1	<1	ND
Hanson	2902	IDPH	9/26/89	27.5	97.6	ND	ND	ND	9.0	1.0	1.0	ND
Hanson	2906	IDPH	1/10/89	23.0	31.0	ND	1.0	ND	ND	ND	ND	ND
Hanson	2907	IDPH	10/17/89	14.3	49.7	ND	ND	ND	5.8	3.7	0.4	ND
Hanson	2911	IDPH	10/17/89	13.3	32.1	ND	ND	ND	4.7	2.7	0.4	ND
Hanson	2938	IDPH	11/6/89	6.2	16.7	ND	ND	ND	1.8	ND	ND	ND
Hanson	2946	IDPH	10/17/89	14.8	13.4	ND	ND	ND	14.4	6.1	0.2	ND
Harrison	2313	IDPH	12/12/89	ND	12.3	ND	ND	ND	ND	0.7	Trace	ND
Horton	2717	IDPH	10/17/89	1.7	16.0	ND	ND	ND	28.3	3.6	0.5	ND
Horton	2726	IDPH	9/12/89	2.7	78.6	ND	ND	5.6	22.8	24.8	ND	ND
Horton	2738	IDPH	9/19/89	92.8	411.6	ND	ND	ND	36.5	2.4	ND	ND
Horton	2741	IDPH	9/12/89	68.1	100.0	ND	ND	11.6	48.1	60.2	8.6	ND
Horton	2742	IDPH	9/12/89	75.8	434.3	108.4	ND	13.2	50.5	63.4	4.3	ND
Horton	2746	IDPH	9/12/89	64.3	400.0	ND	ND	13.6	50.6	62.6	2.6	ND
Horton	2805	IDPH	9/19/89	43.1	218.4	ND	ND	ND	23.9	1.5	ND	ND
Horton	2811	IDPH	10/17/89	47.6	249.0	ND	ND	ND	62.3	26.2	3.8	ND
Horton	2818	IDPH	9/12/89	57.6	205.1	ND	ND	7.4	35.6	29.5	3.2	ND
Horton	2834	IDPH	9 /19/89	54.1	228.0	ND	ND	ND	27.5	2.8	ND	ND
Horton	2835	IDPH	9/19/89	26.9	197.3	ND	ND	ND	13.3	1.0	~ ND	ND
Horton	2838	IDPH	9/19/89	51.9	218.8	ND	ND	ND	22.2	1.3	ND	ND
Horton	2905	IDPH	10/17/89	51.6	133.0	ND	ND	ND	44.8	9.4	1.2	ND
Horton	2922	IDPH	8/8/88	51.0	110.0	ND	ND	ND	11.0	1.3	2.0	ND
Horton	2924	IDPH	10/25/89	8.5	26.5	ND	ND	ND	ND	3.2	<1	ND
Horton	2926	IDPH	8/9/88	12.0	23.0	ND	ND	ND	9.1	1.1	2.7	ND
Horton	2942	IDPH	10/17/89	12.6	13.7	ND	ND	ND	7.5	4.2	0.4	ND
Horton	3001	IDPH	11/28/89	8.7	30.1	ND	ND	ND	4.4	ND	1.8	ND
Horton	3006	IDPH	8/9/88	2.7	1.8	ND	-ND	1.7	ND	ND	2.6	ND
Horton	3037	IDPH	11/28/89	0.9	1.1	ND	ND	ND	ND	ND	ND	ND
Horton	3133	IDPH	11/7/89	1.5	2.6	ND	ND	ND	ND	ND	ND	ND
Johnson	1613	IDPH	12/5/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Johnson	1631 1637	IDPH IDPH	12/4/89 12/11/89	ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND ND	ND	ND
Johnson	1638	IDPH	12/11/89	ND ND	ND ND	ND ND	ND ND	ND	· ND	ND ND	ND	ND
Johnson Johnson	1641	IDPH	12/11/89	ND	ND ND	ND ND	ND ND	ND	ND ND	ND ND	Trace ND	ND ND
Johnson	1642	IDPH	12/11/89	ND	ND	ND	ND ND	ND	ND	ND	ND	ND
Johnson	1711	IDPH	12/11/89	ND	ND ND	ND	ND	ND	ND	ND	ND	ND
Johnson	1726	IDPH	12/11/89									
Johnson	1746	IDPH	12/11/89					ND				ND
Kinsey	2726	IDPH	6/20/89		161.0		ND	1.0		53.9	1.8	ND
Kinsey	2803	IDPH	9/12/89		219.0			5.2	30.9	34.3	1.5	ND
Kinsey	2806	IDPH	10/17/89	50.8	197.0			ND		23.5	1.3	ND
Kinsey	2813	IDPH	9/19/89		193.2	ND		ND		0.9		ND
Kinsey	2822	IDPH	9/19/89	28.2	182.6	ND		ND	13.8	0.8	ND	ND
Kinsey	2826	IDPH	10/25/89	58.9	193.8	ND	ND	ND	ND	51.9	3.5	ND
Kinsey	2829	IDPH	10/17/89	15.1	94.3	ND		ND	14.7	8.3	0.2	ND
Kinsey	2829	IDPH	1/10/89		37.0			ND		ND	ND	ND
Kinsey	2833	IDPH	9/19/89	20.9	81.0	ND	ND	ND	12.6	0.8	ND	ND
Kinsey	2909	IDPH	6/20/89	7.0	13.9	ND	ND	0.2	ND	3.5	0.2	ND
Kinsey	2920	IDPH	10/17/89	7.5	29.1	. ND	ND	ND	3.9	2.3	0.2	ND
Kinsey	2929	IDPH	12/4/89	5.0	11.4	2.9	ND	ND	2.1	ND	ND	ND
Kinsey	3002	IDPH	11/7/89	2.8	10.6	ND	ND	ND	ND	0.9	ND	ND
Lapey	2746	IDPH	9/26/89	50.0	224.2	ND	ND	ND	25.2	2.7	4.1	ND
Lapey	2817	IDPH	9/12/89	21.0	114.2	ND	ND	2.9	17.5	23.6	ND	ND
Lapey	2838	IDPH	9/19/89	17.5	50.6	ND	ND	ND	6.5	0.5	ND	ND

543

749.0

(All concentrations in μg/l)

Lindberg 2407 IDPH 11/6/89 1.6 0.6 ND ND ND ND Trace ND ND Lindberg 2421 IDPH 86/9/88 1.1 2.1 ND ND ND ND ND ND ND N													
Lapey 2918 IDPH 9/26/89 ct L.S. ND ND ND ND ND ND ND N						******************							***************************************
Lapey 308 IDPH 12/12/89 1.7 3.0 ND ND ND Trace ND Trace ND Lapey 3116 IDPH 11/R/89 1.8 2.7 ND ND ND ND ND ND ND N									0.000		******		
Lapey 3116 IDPH 11/R89 1.3 3.0 ND ND ND ND ND ND ND N													
Lapey 3117 IDPH 117/R89 1.8 2.77 ND ND ND ND ND ND ND													
Lapey 3121 IDPH 1117/89 1.9 2.7 ND ND ND ND ND ND ND N	_												
Lapey 3125 IDPH 117/789 2.0 4.5 ND ND ND ND ND ND ND N													
Lapey 3130 IDPH 1117/89 2.0 4.5 ND ND ND ND ND ND ND N													
Lapey 3205 IDPH 12/12/89 1.6 2.7 ND ND ND ND ND ND ND N													
Lapey 3230 IDPH 12/12/89 ND ND ND ND ND ND ND N	ĺ												
Lindaler 2412 IDPH 620/89 0.7 1.5 ND ND ND ND ND ND ND N		1											
Lindale													
Lindale													
Lindberg 2407 IDPH 11/6/89 1.3 1.7 ND ND ND ND ND ND ND N		1											
Lindberg 2407 IDPH 11/28/89 0.6 ND ND ND ND ND ND ND N	Lindale												
Lindberg 2407 IDPH 11/6/89 1.6 0.6 ND ND ND ND ND ND ND N													
Lindberg 2413 IDPH 8,9788 0.7 ND ND ND ND ND ND ND N	Lindberg	2402	IDPH	11/28/89		ND	ND					ND	
Lindberg 2421 IDPH 8,998 0.7 ND ND ND ND ND ND ND N	Lindberg	2407	IDPH	11/6/89	1.6	0.6				Trace			
Lindberg 2501 IDPH 11/28/99 1.4 0.8 ND ND ND ND ND ND ND Lindberg 2506 IDPH 11/28/98 2.9 6.0 ND ND ND ND ND ND ND N	Lindberg	2413	IDPH	8/9/88	1.1	2.1	ND		ND	ND	ND	ND	ND
Lindberg 2505 IDPH 1/28/89 2.9 6.0 ND ND ND ND ND 0.8 ND	Lindberg	2421	IDPH	8/9/88	0.7	ND	ND		ND	ND	ND		ND
Lindberg 2505 IDPH 1/28/89 2.9 6.0 ND ND ND ND ND 0.8 ND	Lindberg	2501	IDPH	11/28/89	1.4	0.8	ND	ND	ND	ND	ND	ND	ND
Lindberg 2512 IDPH 12/5/89 2.9 5.5 N.D. Trace N.D. Trace N.D. Lindberg 2515 IDPH 11/6/89 2.2 3.7 N.D. N.		2506			2.9	6.0	ND	ND	ND	ND	ND	0.8	ND
Lindberg 2515 IDPH 11/6/89 2.2 3.7 N.D N.D N.D N.D 0.6 Trace N.D	Lindberg		4		2.9	5.5	ND		ND		0.8	Trace	
Lindberg 2518 IDPH 11/6/89 4.2 11.2 ND ND ND ND 1.2 Trace ND	Lindberg	2515	IDPH	11/6/89	2.2	3.7	ND	, ND	. ND	ND	0.6	Trace	ND
Lindberg 2618 IDPH 8,9/88 6.1 16.0 ND ND ND ND 0.4 2.9 ND	Lindberg		L		4.2	11.2	ND	ND	ND	ND	1.2	Trace	ND
Lyran 1645 IDPH 12/11/89 ND ND ND ND ND ND ND N			IDPH	8/9/88	6.1	16.0	ND	ND	ND	1.0	0.4	2.9	
Lyran 1650 IDPH 12/11/89 ND ND ND ND ND ND ND N					ND	ND		ND	ND	ND	ND	ND	
Lyran 1714 IDPH 12/11/89 ND ND ND ND ND ND ND N						ND	ND	ND	ND	ND		ND	
Lyran 1738 IDPH 12/5/89 ND ND ND ND ND ND ND N							ND						
Marshall 2641 IDPH 11/7/89 7.7 157.0 ND ND ND ND 13.4 ND 1.4 ND Marshall 2721 IDPH 12/4/89 1.8 18.1 13.5 ND ND 31.6 4.6 ND ND Marshall 2722 IDPH 9/12/89 4.1 54.0 ND ND ND ND 12.4 13.3 <1 ND ND Marshall 2730 IDPH 12/4/89 23.7 108.0 64.5 ND ND ND 77.9 28.6 ND ND ND Marshall 2734 IDPH 11/28/89 37.5 170.5 50.6 ND ND ND 80.9 19.2 ND ND ND Marshall 2737 IDPH 11/28/89 ND 1.8 ND ND ND ND ND ND ND N													
Marshall 2721 IDPH 12/4/89 1.8 18.1 13.5 ND ND 31.6 4.6 ND ND ND ND ND ND ND N													
Marshall 2722 IDPH 9/12/89 4.1 54.0 ND ND ND 12.4 13.3 <1 ND ND ND ND 12.4 13.3 <1 ND ND ND ND ND ND ND N													
Marshall 2730 IDPH 12/4/89 23.7 108.0 64.5 ND ND 77.9 28.6 ND ND ND ND Marshall 2734 IDPH 11/28/89 37.5 170.5 50.6 ND ND 80.9 19.2 ND ND ND Marshall 2737 IDPH 11/28/89 ND 1.8 ND ND ND ND ND ND ND O.5 ND Marshall 2745 IDPH 10/17/89 82.9 295.0 ND ND ND ND ND ND O.5 ND Marshall 2813 IDPH 8/21/89 35.0 154.0 26.0 ND 3.1 34.0 38.0 1.7 ND Marshall 2813 IDPH 12/12/89 ND ND ND ND ND ND ND N													
Marshall 2734 IDPH 11/28/89 37.5 170.5 50.6 ND ND 80.9 19.2 ND ND Marshall 2737 IDPH 11/28/89 ND 1.8 ND ND ND ND ND ND O.5 ND Marshall 2745 IDPH 10/17/89 82.9 295.0 ND ND ND ND O.5 ND Marshall 2813 IDPH 12/12/89 ND ND<													
Marshall 2737 IDPH 11/28/89 ND 1.8 ND ND ND ND ND 0.5 ND													
Marshall 2745 IDPH 10/17/89 82.9 295.0 ND ND ND 67.6 30.0 3.9 ND Marshall 2813 IDPH 8/21/89 35.0 154.0 26.0 ND 3.1 34.0 38.0 1.7 ND Marshall 2813 IDPH 12/12/89 ND			1										
Marshall 2813 IDPH 8/21/89 35.0 154.0 26.0 ND 3.1 34.0 38.0 1.7 ND Marshall 2813 IDPH 12/12/89 ND			1										
Marshall 2813 IDPH 12/12/89 ND ND ND ND ND ND ND N			1										
Marshall 2825 IDPH 9/19/89 58.2 246.0 ND ND ND 30.0 1.6 ND ND Marshall 2830 IDPH 9/19/89 40.1 208.4 ND ND ND 18.7 1.1 ND ND Marshall 2838 IDPH 8/21/89 44.0 187.0 27.0 1.1 2.9 39.0 36.0 ND ND Marshall 2845 IDPH 10/17/89 47.9 93.6 ND ND ND 26.9 11.9 0.9 ND Marshall 2909 IDPH 9/19/89 32.6 98.1 ND ND ND 8.8 1.2 ND ND Marshall 2909 IDPH 2/7/89 57.0 24.0 ND 2.0 ND													
Marshall 2830 IDPH 9/19/89 40.1 208.4 ND ND ND 18.7 1.1 ND ND Marshall 2838 IDPH 8/21/89 44.0 187.0 27.0 1.1 2.9 39.0 36.0 ND ND Marshall 2845 IDPH 10/17/89 47.9 93.6 ND ND ND ND 26.9 11.9 0.9 ND Marshall 2909 IDPH 9/19/89 32.6 98.1 ND ND ND ND 8.8 1.2 ND ND Marshall 2926 IDPH 2/7/89 57.0 24.0 ND 2.0 ND ND ND ND ND ND ND N													
Marshall 2838 IDPH 8/21/89 44.0 187.0 27.0 1.1 2.9 39.0 36.0 ND ND Marshall 2845 IDPH 10/17/89 47.9 93.6 ND ND ND 26.9 11.9 0.9 ND Marshall 2909 IDPH 9/19/89 32.6 98.1 ND ND ND 8.8 1.2 ND ND Marshall 2906 IDPH 2//89 57.0 24.0 ND 20 ND													
Marshall 2845 IDPH 10/17/89 47.9 93.6 ND ND ND 26.9 11.9 0.9 ND Marshall 2909 IDPH 9/19/89 32.6 98.1 ND													
Marshall 2909 IDPH 9/19/89 32.6 98.1 ND ND ND 8.8 1.2 ND ND Marshall 2926 IDPH 2/7/89 57.0 24.0 ND 2.0 ND ND </td <td></td> <td>1</td> <td></td>		1											
Marshall 2926 IDPH 2/7/89 57.0 24.0 ND 2.0 ND ND </td <td></td> <td></td> <td>•</td> <td></td>			•										
Marshall 2937 IDPH 10/17/89 5.2 7.0 ND ND ND 6.5 2.3 ND ND Marshall 2946 IDPH 10/17/89 5.0 13.8 ND ND ND 1.8 1.1 0.2 ND Marshall 3018 IDPH 10/25/89 4.0 13.1 ND ND ND 3.1 1.4 1.6 ND Marshall 3038 IDPH 10/25/89 2.3 0.5 ND ND </td <td></td> <td></td> <td></td> <td></td>													
Marshall 2946 IDPH 10/17/89 5.0 13.8 ND ND ND 1.8 1.1 0.2 ND Marshall 3018 IDPH 10/25/89 4.0 13.1 ND ND ND ND 3.1 1.4 1.6 ND Marshall 3038 IDPH 10/25/89 2.3 0.5 ND ND<													
Marshall 3018 IDPH 10/25/89 4.0 13.1 ND ND ND 3.1 1.4 1.6 ND Marshall 3038 IDPH 10/25/89 2.3 0.5 ND ND </td <td></td> <td></td> <td></td>													
Marshall 3038 IDPH 10/25/89 2.3 0.5 ND ND ND 3.7 0.1 ND ND Marshall 3101 IDPH 2/7/89 2.0 <1 ND													
Marshall 3101 IDPH 2/I/89 2.0 <1 ND													
Marshall 3138 IDPH 12/12/89 1.7 2.6 ND ND ND ND ND Trace ND Pershing 1637 IDPH 11/6/89 2.1 4.1 ND ND <td></td>													
Pershing 1637 IDPH 11/6/89 2.1 4.1 ND ND <td></td>													
Pershing 1802 IDPH 12/14/89 2.4 ND ND Trace 1.2 Trace 1.3 ND ND Potter 2700 IDPH 9/12/89 23.4 111.8 ND 6.7 ND 25.2 32.2 2.2 ND Potter 2825 IDPH 9/19/89 40.8 192.5 ND ND ND 15.8 0.9 ND ND Potter 2826 IDPH 10/25/89 27.5 93.1 ND ND ND 10.2 9.1 <1	Marshall												ND
Potter 2700 IDPH 9/12/89 23.4 111.8 ND 6.7 ND 25.2 32.2 2.2 ND Potter 2825 IDPH 9/19/89 40.8 192.5 ND ND ND 15.8 0.9 ND ND Potter 2826 IDPH 10/25/89 27.5 93.1 ND ND ND 10.2 9.1 <1	Pershing												
Potter 2825 IDPH 9/19/89 40.8 192.5 ND ND ND 15.8 0.9 ND ND Potter 2826 IDPH 10/25/89 27.5 93.1 ND ND ND 10.2 9.1 <1													
Potter 2826 IDPH 10/25/89 27.5 93.1 ND ND ND 10.2 9.1 <1 ND Potter 2837 IDPH 8/21/89 24.0 113.0 18.0 ND 1.4 25.0 20.0 1.2 ND Potter 2933 IDPH 11/28/89 12.0 29.8 ND ND 0.3 2.9 ND 0.6 ND Reed 1825 IDPH 10/25/89 35.0 92.1 ND ND ND 14.4 8.5 0.5 ND Reed 1930 IDPH 10/25/89 46.6 93.0 ND ND ND 46.3 12.8 1.5 ND	Potter												
Potter 2837 IDPH 8/21/89 24.0 113.0 18.0 ND 1.4 25.0 20.0 1.2 ND Potter 2933 IDPH 11/28/89 12.0 29.8 ND ND 0.3 2.9 ND 0.6 ND Reed 1825 IDPH 10/25/89 35.0 92.1 ND ND ND 14.4 8.5 0.5 ND Reed 1930 IDPH 10/25/89 46.6 93.0 ND ND ND 46.3 12.8 1.5 ND	Potter											ND	ND
Potter 2933 IDPH 11/28/89 12.0 29.8 ND ND 0.3 2.9 ND 0.6 ND Reed 1825 IDPH 10/25/89 35.0 92.1 ND ND ND 14.4 8.5 0.5 ND Reed 1930 IDPH 10/25/89 46.6 93.0 ND ND ND 46.3 12.8 1.5 ND	Potter												
Reed 1825 IDPH 10/25/89 35.0 92.1 ND ND ND 14.4 8.5 0.5 ND Reed 1930 IDPH 10/25/89 46.6 93.0 ND ND ND 46.3 12.8 1.5 ND	Potter				24.0		18.0		1.4			1.2	ND
Reed 1930 IDPH 10/25/89 46.6 93.0 ND ND ND 46.3 12.8 1.5 ND	Potter					29.8	ND			2.9	ND	0.6	ND
	Reed			1	35.0			ND	ND	14.4	8.5	0.5	ND
Sandy Hiw 1734 IDPH 12/5/89 ND ND ND ND ND Trace ND ND ND	Reed	1930	IDPH	10/25/89	46.6	93.0		ND	ND		12.8	1.5	ND
	Sandy Hiw	1734	IDPH	12/5/89	ND	ND	ND	ND	ND	Trace	ND	ND	ND

(All concentrations in µg/l)

	Street	Sampling			1,1,1	cis-	trans-					Vinyl
Address	No.	Agency	DATE	TCE	TCA	1,2-DCE	1,2-DCE	1,2-DCA	1,1-DCA	1,1-DCE	PCE	Chloride
Sandy Hlw	1810	IDPH	12/5/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sandy HIW	1812	IDPH	12/5/89	ND	ND	ND	ND	ND	ND	ND	Trace	ND
Sandy Hlw	1816	IDPH	12/14/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sewell	2718	IDPH	10/25/89	1.8	ND	ND	ND	15.6	27.2	3.2	0.6	ND
Sewell	2722	IDPH	8/9/88	0.5	3.2	ND	ND	ND	0.2	ND	ND	ND
Sewell	2814	IDPH	9/12/89	73.7	90.0	ND	ND	9.1	55.6	51.0	5.0	ND
Sewell	2822	IDPH	9/12/89	73.2	210.0	ND.	2.2	9.2	54.2	49.0	6.7	ND
Sewell	2826	IDPH	9/19/89	47.9	215.0	ND	ND	ND	18.8	1.1	ND	ND
Sewell	2902	IDPH	6/20/89	21.8	38.9	ND	ND	ND	ND	10.9	0.3	ND
Sewell	2909	IDPH	9/26/89	25.1	88.9	ND	ND	ND	6.7	ND	1.1	ND
Sewell	2909	IDPH	2/7/89	22.0	36.0	ND	2.0	ND	ND	ND	1.0	ND
Sewell	2917	IDPH	9/26/89	28.1	38.6	ND	ND	ND	4.9	<1	ND	ND
Sewell	2921	IDPH	9/26/89	19.5	107.3	ND	ND	ND	4.4	<1	1.0	ND
Sewell	2930	IDPH	9/26/89	19.8	111.2	ND	ND	ND	4.6	<1	1.4	ND
Sewell	2930	IDPH	8/21/89	13.0	28.0	6.9	1.1	0.7	7.3	5.9	1.0	ND
Sewell	2934	IDPH	12/25/89	17.8	48.0	ND	ND	ND	7.3	3.2	1.5	ND
Sewell	3016	IDPH	10/25/89	ND	<1	ND	ND	ND	ND	ND	ND	ND
Sewell	3026	IDPH	10/25/89	9.9	7.7	ND	ND	ND	19.0	4.4	<1	ND
Sewell	3040	IDPH	10/25/89	3.4	8.6	ND	ND	ND	1.5	0.9	0.9	ND
Sewell	3133	IDPH	12/4/89	ND	ND	ND	ND	ND	ND	ND	ND	ND
Sewell	3136	IDPH	11/7/89	2.3	3.9	ND	ND	ND	ND	ND	ND	ND
Sewell	3138	IDPH	11/7/89	2.1	3.4	ND	ND	ND	ND	ND	<1	ND
Sewell	3142	IDPH	11/7/89	1.8	3.0	ND	ND	ND	ND	ND	ND	ND
Wills	1201	IDPH	9/12/89	<1	1.5	ND	ND	ND	ND	ND	<1	ND
Wills	1610	IDPH	10/25/89	37.5	133.0	ND	ND	ND	33.6	12.8	0.9	ND
Wills	1703	IDPH	11/7/89	73.9	220.0	ND	ND	ND	37.0	42.8	1.7	ND
Wills	1920	IDPH	9/12/89	50.0	260.0	ND	ND	9.8	39.7	49.2	4.3	ND
Wills	1935	IDPH	8/21/89	45.0	210.0	42.0	1.1	3.4	55.0	30.0	2.1	ND

[•] ND = Not Detected

à÷

17

Kender No. 245.8

conservative contouring approach was used to produce the plume contour maps in this report, meaning that the contour maps depict a worst-case scenario, showing the maximum contaminant concentration in any given area that is consistent with the data. For example, in cases where contamination of laboratory and field blanks indicated that the concentrations reported for the samples may exceed the actual concentration in the groundwater, the numerical concentrations were plotted on the maps as 'less than' (<) the reported values, but the maps were contoured as if the reported value was actually due entirely to groundwater contamination. Similarly, in some areas where isolated samples showed high concentration values separated by large distances, the isolated points were contoured to represent a single linear feature. Where multiple or duplicate samples were collected at a single location, the highest of the reported concentrations was plotted on This conservative contouring approach was followed to protect the public health by presenting the highest contaminant concentrations that are consistent with the data. However, it must be emphasized that the plume maps presented in this report are interpretations based on the set of data that is presented on the maps. The further removed a location is from a data point, the more interpretive are the contours. It should be noted that the density of data points in the area west of 8th Street is lower than that in the eastern portion of the study area; consequently, the broad features depicted in the western portion of the study area are more open to interpretation than are features in the eastern part of the study area.

3.2.2 DISTRIBUTION AND LEVELS OF VOC CONTAMINATION

Maps depicting the plume of VOC-contaminated groundwater are presented in Figures 3-4 through 3-20, which are included in the separately bound map packet that accompanies this report. In this section, the general features of the plume maps are described briefly. The reader is encouraged to refer to the maps for greater detail.

3.2.2.1 IEPA/USEPA Data

Although each plume map has its own unique aspects, many of the maps share several common features. In general, the maps depict a west-northwest trending plume with an axis of high concentration that runs approximately from 24th Street and Reed Avenue to 9th Street and Alton Avenue. West of 9th Street and Alton Avenue, the plume appears to bend to the southwest and become broader and flatter. Contaminant concentrations vary smoothly from location to location for the most part, and the plume appears to be roughly symmetrical about the axis of high concentration. Isolated hot spots, caused by 1 or 2 sample points appear at several locations in the study area, but these locations are not hot spots on each of the contaminant plume maps, indicating that these isolated locations contain a different group of contaminants than the main body of the plume. The features described above apply to the general distribution of TCE, 1,1,1-TCA, cis-1,2-DCE, 1,2-DCA, 1,1-DCA, and 1,1-DCE in the study area.

The tetrachloroethene (PCE) plume map (Figure 3-18) differs significantly from the general features described above. There appears to be a west-northwest trending linear feature in the vicinity of 24th Street and Reed Avenue as on the other VOC plume maps, but the feature does not extend as far west as the same feature on the other maps. In addition, a second linear feature trends west-southwest from the vicinity of 10th Street and Sawyer Road to the southwest corner of the study area. Samples from the west-central and northwestern portions of the study area show pervasive PCE contamination at low to intermediate levels (0 to 10 ppb). Some of the differences between the PCE plume map and the other VOC plume maps can be attributed to a significantly lower sample density for PCE than for the other VOCs, because many USEPA samples were not analyzed for PCE. However, the linear feature in the southwestern part of the study area is supported by a number of IEPA sample points, which did not show a similar feature for other contaminants. The presence of this southwestern linear feature suggests the existence of a plume of PCE contamination that is independent

16814/38

of the main plume. It must be noted, however, that contaminant levels in this southwestern plume are low (<3 ppb). No Safe Drinking Water Act MCL has been established for PCE, but an MCL of 5 ppb has been proposed (USEPA, 1989).

Vinyl chloride and trans-1,2-DCE were detected at a few scattered locations across the study area, and their distribution does not appear to form a plume.

3.2.2.2 IDPH Data

The contour maps for the IDPH data show some features that are similar to those on the IEPA/USEPA contour maps. In general, for TCE, 1,1,1-TCA, and 1,1-DCA, there appears to be a plume that trends west-northwest and which extends from roughly 24th Street and Reed Avenue to approximately Alton Avenue and 9th Street. The remaining plume maps for the IDPH samples differ somewhat from the corresponding maps for the IEPA/USEPA samples. These differences can be attributed to the incompatibility of the IEPA/USEPA and IDPH data sets, as discussed in Subsection 3.1.2.

Figure 3-9 shows two local hot spots for cis-1,2-DCE that are bounded by Alton Avenue, 11th Street, Pershing Road, and Horton Street. There is no clear overall trend for trans-1,2-DCE, however there are several local areas of low-level concentration in the area bounded by Harrison Avenue, Horton Street, Brooke Road, and Lapey Street (Figure 3-11). It should be noted that the highest IDPH sample concentration for trans-1,2-DCE is less than 12 ppb, which is significantly lower than the proposed MCL of 100 ppb for this contaminant. The plume for 1,2-DCA extends from about Wills Avenue and Horton Street westward to roughly Reed Avenue and 8th Street (Figure 3-13). Figure 3-17 shows a small plume for 1,1-DCE that extends from Horton Street and Wills Avenue to Alton Avenue and 11th Street; local hot spots occur within this plume. The PCE plume extends from the east-central part of the study area to about Alton Avenue and Lapey Street

(Figure 3-19). Local hot spots occur within the plume as well as adjacent to it. In addition to the main PCE plume, there is a small linear feature in the vicinity of Sawyer Road and 8th Street. A similar linear feature is also apparent for the IEPA/USEPA samples (Figure 3-18), as noted in Subsection 3.2.2.1. None of the IDPH samples indicated vinyl chloride levels above the detection limit (Table 3-12), therefore no IDPH map of vinyl chloride distribution was prepared.

3.3 METALS CONTAMINATION

Maps illustrating the distribution of groundwater contamination by the 4 metals analyzed for in the Operable Unit are included as Figures 3-21 through 3-24 in the map packet. Metals analyzed for included arsenic, cadmium, chromium and lead. Detection limits for the analytical procedures used in the Operable Unit investigation are listed in Table 3-9. Only IEPA sample points are depicted on these maps because neither USEPA or IDPH have sampled the area for metals contamination. The analytical results for the metals analyses performed for this investigation are included as Table 3-13.

The maps for arsenic (Figure 3-21) and chromium (Figure 3-23) show only isolated points where the contaminant was detected at levels in excess of the respective detection limits. Arsenic was detected at 5 locations in the study area, which are circled on the figure. Arsenic was detected at a maximum level of 18.5 ppb, which is well below the 50 ppb MCL for arsenic. Chromium was detected at 3 locations in the study area, also circled, at a maximum level of 26.2 ppb, which is well below the 50 ppb MCL for chromium.

The maps for cadmium (Figure 3-22) and lead (Figure 3-24) illustrate that portions of the study area are contaminated at very low levels with these contaminants. Cadmium was not detected at levels greater than 1 ppb at any location in the study area. The MCL for cadmium is 10 ppb. Lead was detected in excess of its 50 ppb MCL in two locations, which are shown on Figure 3-24.

Table 3-13 IEPA Metals Data

(All concentrations in µg/l)

	Street	Sample	Sampling					
Address	No.	No.	Agency	DATE	Arsenic	Cadmium	Chromium	Lead
4th	2819	507	IEPA	6/11/90	ND	0.1B	ND	3.9
4th	2828	509	IEPA	6/11/90	ND	ND	ND	1.4B
4th	2901	518	IEPA	6/12/90	ND	ND	10.0UJ	ND
4th	3045	570/571	IEPA	6/14/90	2.0UJ	0.1B	ND	1.0B
5th	2624	577	IEPA	6/15/90	ND	0.2BJ	ND	ND
7th	3115	582	IEPA	6/15/90	ND	ND	ND	ND
7th	3233	553	IEPA	6/13/90	ND	0.4BJ	10.0UJ	38.9
7th	3309	564	IEPA	6/14/90	2.0UJ	ND	ND	ND
8th	2647	630	IEPA	6/18/90	2.0UJ	0.1UJ	10.0UJ	ND
8th	2810	558	IEPA	6/14/90	2.0UJ	ND	ND	ND
8th	2914	573	IEPA	6/14/90	ND	0.4BJ	ND	1.4B
8th	3022	616	IEPA	6/17/90	. ND	0.8J	10.0UJ	ND
8th	3109	620	IEPA	6/18/90	ND	0.1BJ	10.0UJ	ND
8th	3138	618	IEPA	6/17/90	ND	0.2BJ	10.0UJ	ND
8th	3201	546	IEPA	6/13/90	2.0UJ	ND	ND	ND
8th	3237	540	IEPA	6/13/90	18.5J	0.1B	ND	9.9J
8th	3301	539	IEPA	6/13/90	2.0UJ	0.2B	ND	1.8BJ
8th	3337	541	IEPA	6/13/90	2.0UJ	ND	ND	ND
9th	2910	596	IEPA	6/14/90	ND	0.2BJ	ND	ND
9th	3101	612	IEPA	6/18/90	ND	0.1BJ	10.0UJ	ND
9th	3210	587	IEPA	6/15/90	ND	0.1BJ	ND	ND
9th	3245	565	IEPA	6/14/90	2.0UJ	ND	ND	ND
10th	3110	556/557	IEPA	6/13/90	2.0UJ	ND	ND	ND
11th	2613	627	IEPA	6/18/90	2.0UJ	0.3BJ	10.0UJ	6.9
11th	2955	504	IEPA	6/11/90	ND	0.1B	ND	3.5
11th	3015	514	IEPA	6/12/90	ND	0.1B	10.0UJ	1.7B
11th	3119	517	IEPA	6/12/90	2.0B	0.4B	10.0UJ	3.5
11th	3237	580	IEPA	6/15/90	ND	0.2B 0.1BJ	ND	ND
11th	3329	579	IEPA	6/15/90	ND	0.1BJ	ND	ND
16th	3102	552	IEPA	6/13/90	2.0UJ	ND	ND	ND
16th	3122	401	IEPA	6/13/90	2.0UJ	ND	ND	ND
17th	2602	544	IEPA	6/13/90	2.0UJ	ND	ND	ND
17th	3120	551	IEPA	6/13/90	2.0UJ	ND	ND	2.2J
18th	3110	561	IEPA	6/13/90	2.0UJ	ND	ND	ND
20th	2703	621	IEPA	6/18/90	ND	0.8J	10.0UJ	2.1
20th	3109	542	IEPA	6/18/90	2.0UJ	ND	ND	ND
Barnum	505	650	IEPA	6/20/90	ND	0.2BJ	ND	2.7
Barry	426	632	IEPA	6/18/90	2.0UJ	0.2BJ	10.0UJ	ND
Bildahl	2944	641	IEPA	6/19/90	ND	ND	10.0UJ	1.0UJ
Bildahl	3017							
	+	648	IEPA	6/19/90	ND	ND 0.4D	ND	ND
Bildahl	3038	592	IEPA	6/15/90	ND	0.4BJ	ND	1.9B
Bildahl	3122	609/610	IEPA	6/16/90	ND	0.3BJ	10.0UJ	7.2J
Bildahl	3141	594	IEPA	6/15/90	ND	0.1BJ	ND	ND
Bildahl	3206	611	IEPA	6/16/90	ND	ND	10.0UJ	1.3B
Bildahl	3302	598	IEPA	6/15/90	ND	ND	ND	3.8
Bildahl	3338	599	IEPA	6/15/90	ND	0.1BJ	ND	ND 27
Brooke	110	617	IEPA	6/18/90	ND	0.3B	10.0UJ	2.7
Brooke	202	529	IEPA	6/12/90	2.0UJ	R	ND 10 OUI	ND 10D
Brooke	326	519	IEPA	6/12/90	ND	0.2BJ	10.0UJ	1.8B
Brooke	409	526	IEPA	6/12/90	ND 2 OD I	ND	ND	ND
Brooke	823	527/528	IEPA	6/12/90	2.0BJ	ND/R	ND 10 OUT	ND
Brooke	1101	639	IEPA	6/19/90	ND	ND	10.0UJ	1.0UJ
Brooke	1202	581	IEPA	6/15/90	ND	0.8J	ND	1.8B
Brooke	1317	584	IEPA	6/15/90	ND	0.2BJ	ND	ND 12.51
Collins	2801	543	IEPA	6/13/90	2.0UJ	0.3B	ND	12.5J

[•] ND = Not Detected, UJ= Not Detected, Estimated Value, B = Blank Contamination, R = Rejected

Table 3-13 cont. IEPA Metals Data

(All concentrations in µg/l)

	Street	Sample	Sampling	***************************************		8::::::::::::::::::::::::::::::::::::::		
Address	No.	No.	Agency	DATE	Arsenic	Cadmium	Chromium	Lead
Collins	3029	575	IEPA	6/14/90	ND	ND	ND	1.0B
Collins	3109	605	IEPA	6/16/90	ND	0.1B	10.0UJ	1.1B
Collins	3126	608	IEPA	6/16/90	ND	0.2BJ	10.0UJ	ND
Collins	3245	560	IEPA	6/14/90	2.0UJ	ND	ND	1.3BJ
Collins	3310	550	IEPA	6/13/90	2.0UJ	ND	ND	ND
Energy	123	576	IEPA	6/14/90	ND	0.2BJ	26.2	3.0
Grant	3045	606	IEPA	6/16/90	ND	0.1BJ	10.0UJ	ND
Grant	3107	615	IEPA	6/18/90	ND	0.1BJ	10.0UJ	ND
Hamilton	1630	624	IEPA	6/18/90	ND	0.1BJ	10.0UJ	1.3B
Hamilton	1735	502	IEPA	6/11/90	ND	ND	ND	18.8
Harrison	707	646/647	IEPA	6/19/90	ND	ND	ND	ND
Harrison	1713	600	IEPA.	6/15/90	ND	0.3BJ	ND	7.7
Harrison	1817	626	IEPA	6/18/90	ND	0.6J	10.0UJ	86.3
Harrison	2315	547/548	IEPA	6/13/90	2.3B	0.2BJ	10.0UJ	4.9J
Horton	3129	588/589	IEPA	6/15/90	ND	0.1BJ	ND	1.5B
Johnson	1737	503/505	IEPA	6/11/90	ND	ND	ND	ND
Kennon	410	649	IEPA	6/19/90	ND	0.1BJ	ND	ND
Kennon	621	640	IEPA	6/19/90	ND	0.1BJ	10.0UJ	1.0BJ
Kishwaukee	3037	635	IEPA	6/19/90	2.0UJ	0.5J	10.0UJ	ND
Kishwaukee	3202	590	IEPA	6/15/90	ND	0.3BJ	ND	1.5B
Kishwaukee	3239	566	IEPA	6/14/90	2.0UJ	ND	ND	1.6BJ
Kishwaukee	3302	567	IEPA	6/14/90	2.0UJ	ND	10.5	1.1BJ
Kishwaukee	3333	631	IEPA	6/18/90	2.0UJ	0.2BJ	10.0UJ	ND
Lapey	3013	642/643	IEPA	6/19/90	ND	ND	ND	1.0UJ
Lapey	3101	604	IEPA	6/16/90	ND	ND	ND	ND
Lapey	3138	603	IEPA	6/16/90	ND	0.2BJ	ND	ND
Lapey	3213	597	IEPA	6/15/90	ND	ND	ND	1.2B
Lapey	3230	569	IEPA	6/14/90	2.0UJ	ND	ND	ND
Lapey	3329	572	IEPA	6/14/90	ND	0.1BJ	ND	15.0
Lindale	2406	538	IEPA	6/13/90	2.0UJ	ND	ND	3.0J
Lindale	2620	521	IEPA	6/12/90	ND	ND	10.0UJ	1.8B
Lindberg	2412	522	IEPA	6/12/90	5.1	0.6J	10.0UJ	ND
Lindberg	2619	559	IEPA	6/14/90	2.0UJ	ND	ND	ND
Lyran	1617	510	IEPA	6/11/90	ND	ND	ND	1.6B
Lyran	1701	512	IEPA	6/12/90	2.0	ND	10.0	1.0
Marshall	3106	563	IEPA	6/14/90	2.0UJ	ND	10.0	1.1BJ
Marshall	3137	583	IEPA	6/15/90	ND	0.1BJ	ND	1.6B
Martin	430	554	IEPA	6/13/90	2.1BJ	ND	ND	3.1J
Mattis	827	524	IEPA	6/12/90	ND	ND	ND	ND
New Milford	608	638	IEPA	6/18/90	ND	ND	10.6	1.0UJ
Olsen	2820	520	IEPA	6/12/90	11.6	ND	10.0UJ	ND
Pershing	1637	586	IEPA	6/15/90	ND	0.5BJ	ND	ND
Pershing	1726	585	IEPA	6/15/90	ND	0.3BJ	ND	4.0
Ranger	801	506	IEPA	6/12/90	ND	ND	ND	ND
River Blvd.	3007	516	IEPA	6/12/90	ND	ND	10.0UJ	1.1B
River Blvd.	3110	636	IEPA	6/19/90	ND	0.1BJ	10.0UJ	1.0UJ
River Blvd.	3117	613/614	IEPA	6/17/90	ND	ND	10.0UJ	ND
Rock River	508	530	IEPA	6/12/90	2.0UJ	ND 0.71	ND	ND
Roosevelt	841	628	IEPA	6/18/90	2.0UJ	0.7J	10.0UJ	ND
Sandy Hiw	728	602	IEPA	6/16/90	ND	0.2BJ	ND	ND
Sandy Hlw Sandy Hlw	810 1202	625	IEPA	6/18/90	ND	0.1UJ	10.0UJ	ND
Sandy Hiw	1306	622 549	IEPA IEPA	6/18/90	ND 2 GB I	0.5BJ	10.0UJ ND	2.2
Sandy Hiw		537		6/13/90	2.6BJ	0.2B		56.2J
Salidy HIW	1812	33/	IEPA	6/13/90	2.0UJ	ND	ND	1.0BJ

[•] ND = Not Detected, UJ= Not Detected, Estimated Value, B = Blank Contamination, R = Rejected

Table 3-13 cont. IEPA Metals Data

(All concentrations in $\mu g/I$)

			Sampling					
Address	No.	No.	Agency	DATE	Arsenic	Cadminu	Chromium	Lead
Saner	2905	525	IEPA	6/12/90	ND	ND	ND	ND
Saner	3014	634	IÈPA	6/18/90	2.0UJ	0.1UJ	10.0UJ	ND
Saner	3110	578	IEPA	6/15/90	ND	0.4BJ	ND	ND
Sawyer	319	536	IEPA	6/13/90	2.0UJ	ND	ND	3.1J
Sewell	2646	644	IEPA	6/19/90	ND	ND	ND	ND
Sewell	3135.5	593	IEPA	6/15/90	ND	ND	ND	ND
South	619	515	IEPA	6/12/90	ND	0.1B	10.0UJ	1.4B
Taft	804	629	IEPA	6/18/90	2.0UJ	, 0.1BJ	10.0UJ	1.8B

[•] ND = Not Detected, UJ= Not Detected, Estimated Value, B = Blank Contamination, R = Rejected

None of the plume maps for the metals analyzed for in the Operable Unit show a systematic distribution of contamination comparable to that observed for VOCs. Instead, the metals data collected in this study indicate localized contamination associated with several unrelated point sources.

3.4 COMPARISON TO ARARS

Applicable or Relevant and Appropriate Requirements (ARARs) are regulations, standards, or criteria that may apply to a site in a regulatory or enforcement action. CERCLA specifically limits the scope of state ARARs to regulations or requirements that have been promulgated and that are more stringent than corresponding federal standards. Section 121 of CERCLA, as reauthorized, requires that ARARs be identified on a site-by-site basis for NPL sites. USEPA's guidance document on ARARS, CERCLA Compliance with Other Laws Manual (USEPA, 1989), specifies that the state has the responsibility of identifying ARARs for a particular site. The State of Illinois has not yet formally identified ARARs for the Southeast Rockford study area, but it is likely that the state will name Safe Drinking Water Act Maximum Contaminant Levels (MCLs), Illinois' Proposed Groundwater Quality Criteria (35 IL Admin. Code 620), and other state water quality regulations as ARARs for the study area. These potential ARARs are presented in Table 3-14. This list is not intended to be exhaustive, but has been included to illustrate the numerical water quality criteria which may apply to the study area.

If a regulation could apply to a site but is not legally enforceable, it is termed a To Be Considered (TBC). Safe Drinking Water Act Secondary MCLs, which are based on aesthetic qualities of water and are not enforceable, are an example of a TBC. Table 3-14 also presents existing or proposed Maximum Contaminant Level Goals (MCLGs) for compounds that have existing or proposed MCLs. An MCLG is a non-enforceable health goal for substances that may have an adverse effect on the health of persons. The numerical value of an MCLG is set at a level at which no known or anticipated adverse effects on health occur.

TABLE 3-14
Potential Applicable or Relevant and Appropriate Requirements
(ARARs)

	ILLINOIS	SADMINISTRATIVE	CODE 35	SAFE D	RINKING WAT	Proposed Illinois Groundwater Quality Criteria		
	SUBTITLE C :		SUBTITLE F	SECTI	ON 14.2			
	General Use Water Quality Standards Section 302.208 Concentration (mg/l)†	Public and Food Processing Water Supply Standards Section 302.304 Concentration (mg/l)†	Finished Water Quality Standards Section 604.202 Concentration (mg/l)†	Primary Drinking Water Standards 40 CFR 141 Concentration (mg/l)†	Proposed Primary and Secondary Drinking Water Standards (mg/l)†	Existing or Proposed Maximum Contaminant Level Goal (MCLG) (mg/l)†	General Resource Groundwater Section 620.302 (mg/l)†	Potable Resource Groundwater Section 620.301 (mg/l)†
Inorganics								
Arsenic (Total)	1.0	0.05	0.05	0.05		0* -	0.2	0.05
Cadmium (Total)	0.05	0.01	0.01	0.01	0.005	0.005*	0.05	0.005
Chromium (Total)		0.05	0.05	0.05	0.10	0.10*	1.0	0.1
Lead (Total)	0.1	0.05	0.05	0.05	0.005	0	0.1	0.05
VOCs Trichloroethene				0.005		0	0.025	0.005
1,1,1-Trichloroethane	,			0.20		0.20	1.0	0.2
Cis-1,2-Dichloroethene					0.07	0.07*	0.2	0.07
Trans-1,2-Dichoroethene					0.1	0.1*	0.5	0.1
1,2-Dichloroethane			·	0.005		0	0.025	0.005
1,1-Dichloroethene				0.007		0.007	0.035	0.007
Tetrachlorethene					0.005	0*	0.025	0.005
Vinyl Chloride				0.002		0	0.01	0.002

 $[\]dagger$ To convert mg/l (ppm) to ug/l (ppb), multiply ppm by 1,000

^{*} Signifies a proposed MCLG

The State of Illinois is currently in the process of promulgating water quality standards that will apply to groundwater under 35 IL Admin. Code 620. These proposed regulations include two classes of groundwater:

General Resource Groundwater and Potable Resource Groundwater. Under the proposed groundwater classification system, the groundwater withdrawn for potable use in the study area would be classified as Potable Resource Groundwater, to which Potable Resource Groundwater Quality Criteria (far right column in Table 3-14) would apply. The inclusion of the State of Illinois' Groundwater Quality standards as ARARS or TBCs will depend on the timing of the promulgation of the standards.

Safe Drinking Water Act MCLs have been established for 5 of the 9 VOCs of concern in this study, and have been proposed for 3 others. Illinois Potable Resource Groundwater Quality standards have been proposed for 8 of the VOCs of concern. Numerical values for the proposed Potable Resource standards are equal in all cases to the existing or proposed MCLs for the VOCs of concern. Review of the analytical results indicate that MCLs have been exceeded in portions of the study area for TCE, 1,1,1-TCA, 1,2-DCA, 1,1-DCE, and vinyl chloride. Proposed MCLs have been exceeded for cis-1,2-DCE and PCE. No standard was exceeded for trans-1,2-DCE. No Safe Drinking Water Act MCL, proposed MCL, or Potable Resource Standard has been established for 1,1-DCA.

The numerical values of the proposed Potable Resource Groundwater Quality criteria differ from the Safe Drinking Water Act MCLs for arsenic, cadmium, and chromium. These contaminants were detected at low levels in this investigation, and did not exceed either standard at any point in the study area. The MCL and proposed Potable Resource Standard for lead are both set at 50 ppb. This limit was exceeded at two locations in the study area.

The areas where an MCL for any contaminant has been exceeded are illustrated in Figure 3-25 (for IEPA/USEPA data) and Figure 3-26 (for IDPH data), both of which are included in the map packet. These figures show a broad, west-northwest trending band with small, outlying pockets of contamination at various locations across the study area.

3.5 3-D CONTOUR PLOTS OF IEPA/USEPA DATA

Appendix C contains 3-D contour plots of IEPA/USEPA data for the nine VOCs of concern. These plots provide succinct visual summaries of VOC concentrations across the study area and they augment the information presented on the contour maps in the map packet that accompanies this report. The 3-D plots should be used as qualitative guides to contamination in the study area, whereas the plume contour maps in the map packet provide quantitative information about groundwater contamination. It should be noted that the vertical scale is variable for each 3-D plot. Hence, direct comparisons of concentration levels for the different 3-D plots are not possible. The green dots represent sample locations at which contamination was detected.

4.0 RISK ASSESSMENT

4.1 PURPOSE AND SCOPE OF RISK ASSESSMENT

The purpose of this assessment is to assist the Illinois Environmental Protection Agency (IEPA) in identifying residences within the study area which are affected by the groundwater contamination, which have not or will not be provided with alternative water as part of the USEPA's final removal action, and for which the provision of an alternative water supply through a state-led action would be prudent. To determine whether an alternative water supply is needed, IEPA will rely primarily on the final or proposed Maximum Contaminant Levels (FMCLs and PMCLs) developed under the authority of the federal Safe Drinking Water Act. For the VOCs analyzed in this investigation, the FMCLs or PMCLs are numerically equivalent to the proposed Illinois Groundwater Quality Control (35 IL Admin. Code 620) for Class I Potable Resource Groundwater (Section 620.301). The proposed Illinois Groundwater Quality criteria are more restrictive than the MCLs for arsenic and cadmium, equivalent to the MCL for lead, and less restrictive than the MCL for chromium (Table 3-14). This risk assessment compares contaminant levels detected in residential wells to available FMCLs and to PMCLs when FMCLs are not available.

In this Risk Assessment, hazard indices are used to evaluate the carcinogenic and non-carcinogenic risks associated with mixtures of contaminants at wells at which detected levels of contamination do not exceed an MCL. The hazard indices will be used as a criterion for providing alternative water at these wells.

This assessment groups the 117 sampled wells according to the following three categories and provides summary tables with information on each category:

- o wells where contamination was not detected above detection limits;
- o wells where contamination was detected at levels that exceed one or more MCLs; and
- o wells where contamination was detected above detection limits but below MCLs.

Hazard indices were calculated for the last category of wells where contamination was detected above detection limits but below the MCL. Hazard indices represent a summation of the ratios of the concentrations of chemicals detected in a particular well to the MCL for those chemicals. Separate hazard indices were calculated for both non-carcinogens and carcinogens. As instructed by IEPA, (1) all chemicals except for 1,2-dichloroethane, a stomach carcinogen, were grouped as either liver toxins or liver carcinogens; and (2) metals were excluded from the calculation of hazard indices so that the hazard indices represent the combined effects of the chlorinated solvents only. Results are presented as groups of wells where the chemical mixtures detected yield hazard indices of (1) greater than 1; (2) 0.75 to 1; (3) 0.5 to 0.74; (4) 0.25 to 0.49; and (5) 0 to 0.24.

The methodology used to categorize the 117 wells sampled and to calculate the hazard indices for wells where contamination was detected below MCLs is described in Section 4.2. The results and conclusions of this assessment are presented in Subsections 4.3 and 4.4.

4.2 METHODOLOGY

IEPA has defined two criteria with which to evaluate wells in the study area and to determine which of these wells should be provided with an alternative water supply. These criteria include (1) MCLs and (2) the target organ hazard indices. Hazard indices represent a sum of the ratios

of contaminant concentrations to their respective MCL for a mixture of contaminants believed to have the same target organ or mechanism of action. Separate hazard indices were calculated for both non-carcinogenic and carcinogenic substances. This methodology generally corresponds to the Guidelines for the Health Risk Assessment of Chemical Mixtures (FR Vol. 51, 34014-34025, 1986). The methodology used to prepare the information needed by IEPA involved data evaluation, comparison of data to MCLs, and the calculation of hazard indices for wells where contaminants were detected at concentrations below MCLs. Each of these steps is summarized below.

4.2.1 DATA EVALUATION

Data for 9 volatile organic compounds and four metals were received from the USEPA contract laboratories, as discussed in Subsection 2.3.2. Due to the low detection limits, a number of data points were qualified or flagged. Data qualifiers for VOCs are discussed in Subsection 3.1.

Wells at which all contaminant concentrations were qualified with either a "U" or a "J" were considered wells where contamination was not detected above detection limits. The detection limit for vinyl chloride was 0.25 ppb and the detection limit for all remaining VOCs was 0.50 ppb. Table 4-1 presents a list of these wells and Figure 4-1 identifies these wells on a study area map. Wells at which contaminant concentrations were not qualified or were qualified with a "B," were evaluated as to whether any MCLs were exceeded.

4.2.2 COMPARISON OF DATA TO MAXIMUM CONTAMINANT LEVELS


Once wells at which contamination was not detected were segregated from the data set, data for the remaining wells were compared to MCLs, which are listed in Table 3-14. MCLs are equivalent to the Illinois Potable Resource Criteria (35 Ill. Adm. Section 620.301).

Table 4-1

S.E. ROCKFORD OPERABLE UNIT - WELLS WHERE CONTAMINATION NOT DETECTED ABOVE DETECTION LIMITS*

ADDRESS	ADDRESS				
1737 Johnson	3329 11th				
1737 Johnson (dup)	410 Kennon - msd				
1701 Lyran	3135.5 Sewell				
3119 11th	2910 9th - msd				
202 Brooke	3302 Bildahl				
319 Sawyer	3338 Bildahl				
1812 Sandy HIW	728 Sandy HIW				
2406 Lindale	3109 Collins				
3337 8th	3045 Grant Park				
3201 8th	3117 River Blvd				
3245 Collins	3117 River Blvd (dup)				
3110 18th	3107 Grant Park				
3106 Marshall	1202 Sandy HIW				
3309 7th	810 Sandy HIW				
3230 Lapey	3110 River				
3329 Lapey	2944 Bildahl				
3110 Saner	-				

^{*} Detection limit of 0.5 ppb used for the following chemicals: 1,1 - DCE; Trans 1,2 - DCE; 1,1 - DCA; CIS - 1,2 - DCE; 1,1,1 - TCA; 1,2 - DCA; TCE, PCE



Contaminant concentrations for each well at which one or more MCLs was exceeded are presented in Table 4-2 and the wells are identified on a study area map in Figure 4-2.

4.2.3 CALCULATION OF HAZARD INDICES

Once wells at which contamination was not detected above detection limits and wells at which one or more MCLs were exceeded were identified, hazard indices were calculated for the contaminants or contaminant mixtures detected in the remaining wells where contamination was detected at concentrations below MCLs. Contaminant concentrations are presented for each of these wells in Table 4-3.

Hazard indices were calculated separately for non-carcinogens and carcinogens. TCE, PCE, 1,2-DCE, and vinyl chloride are carcinogens and 1,1-DCE, cis-1,2-DCE, trans-1,2-DCE and 1,1,1-TCA are non-carcinogens (USEPA, 1990). Though analyzed, sufficient evidence does not exist to classify 1,1-DCA as either carcinogenic or non-carcinogenic. Neither an MCL nor an Illinois Potable Resource Criteria exists for 1,1-DCA. Therefore, this contaminant was not included in the calculation of the hazard indices, as instructed by IEPA. None of the VOC contaminants considered were classified as both carcinogenic and non-carcinogenic. As directed by IEPA, all contaminants, except for 1,2-DCE, a stomach carcinogen, were considered to be either liver toxins or liver carcinogens. Spreadsheets used to calculate the non-carcinogenic and carcinogenic hazard indices are included as Appendix D. Table 4-4 groups wells into incremental hazard index categories. Figures 4-3 and 4-4 included in the map packet delineate these wells on a study area map and list the associated non-carcinogenic and carcinogenic hazard indices.

4.3 RESULTS

Contamination was not detected above detection limits in 31 of the 117 wells sampled. A list of these wells is provided in Table 4-1. Wells for

Table 4-2

S.E. ROCKFORD OPERABLE UNIT - WELLS WHERE ONE OR MORE MAXIMUM CONTAMINANT LEVELS EXCEEDED

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINANT LEVEL (ug/l)
801 Ranger	1,1 - DCE	11	7
0	TCE	21	5
2819 4th	1,1 - DCE	8	7
	TCE	17	5
2828 4th	1,1 - DCE	9	7
	TCE	18	5
619 South	TCE	18	5
3007 River	TCE	111	5
2901 4th	1,1 - DCE	25	7
	TCE		5
2820 Olsen	TCE	10	5
	PCE	127	5
827 Mattis	1,1 - DCE	20	7
	TCE	32	5
823 Brooke	TCE	15	5
823 Brooke (dup)	TCE	20	5
508 Rock River .	Vinyl Chloride	114	2
	1,1 - DCE	13	7
	Cis 1,2 - DCE	1233	70
	1,2 - DCA	13	5
	TCE	171	5
	PCE	13	5
3233 7th	PCE	7	5
2810 8th	TCE	8	5
3045 4th	TCE	36	5
	PCE	10	5
3045 4th (dup)	TCE	36	5
	PCE	10	5

Table 4-2 (CONT.)

S.E. ROCKFORD OPERABLE UNIT - WELLS WHERE ONE OR MORE MAXIMUM CONTAMINANT LEVELS EXCEEDED

ADDRESS	CONTAMINANT	CONCENTRATION	MAXIMUM CONTAMINANT LEVEL
ADDRESS	(ug/l)	(ug/1)	(ug/l)
2914 8th	PCE	15	5
123 Energy	TCE	102	5
<u> </u>	PCE	24	5
110 Brooke	TCE	126	5
1817 Harrison	1,1 - DCE	25	7
	1,1,1 - TCA	991	200
	TCE	63	5
	Pb	56	50
2613 11th	1,1 - DCE	7.9	7
	TCE	14	5
2647 8th	Vinyl Chloride	9	2
•	1,1 - DCE	110	7
	1,1,1 - TCA	528	200
	1,2 - DCA	6	5
	TCE	10	5
	PCE	10	` 5
426 Barry	Cis 1,2 - DCE	99	70
	TCE	428	5
3037 Kishwaukee	TCE	13	5
608 New Milford	TCE	14	5
621 Kennon	TCE	7	5
	PCE	545	5
707 Harrison	1,1 - DCE	34	7
	TCE	41	5
	PCE	10	5
707 Harrison (dup)	1,1 - DCE	34	7
	TCE	41	5
	PCE	10	5
1306 Sandy HIW	Pb	56	50




Table 4-3

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINAN LEVEL (ug/l)
1735 Hamilton	TCE	0.8	5
2955 11th	Cis 1,2 - DCE	11.0	70
	TCE	1.0	
1617 Lyran	PCE	1.1	5
3015 11th	1,1,1 - TCA	6.3	200
	TCE	3.3	_5
326 Brooke-msd	Cis 1,2 - DCE	14.0	70
2620 Lindale	1,1,1 - TCA	1.7	200
	TCE	1.1	5
	PCE	0.9	5
2412 Lindberg	TCE	1.6	5
2905 Saner	1,1,1 - TCA	1.8	200
	TCE	1.7	5
•	PCE ·	1.0	5
409 Brooke	1,1 - DCE	0.6	7
	1,1,1 - TCA	3.8	200
	TCE	2.4	5
	PCE	2.0	5
3301 8th	TCE	0.6	5
	PCE	0.5	5
3237 8th	TCE	1.0	5
	PCE	1.8	5
3109 20th	TCE	1.2	5
2801 Collins	1,1 - DCE	1.4	7
	Cis 1,2 - DCE	2.1	70
	1,1,1 - TCA	8.6	200
	TCE	2.0	5

Table 4-3 (CONT.)

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINAN LEVEL (ug/l)
2602 17th	1,1 - DCE	1.0	7
	CIS 1,2 - DCE	2.5	70
	1,1,1 - TCA	29.0	200
	TCE	1.1	_5
2315 Harrison	1,1 - DCE	0.8	7
	1,1,1 - TCA	10	200
2315 Harrison (dup)	1,1 - DCE	0.9	7
	1,1,1 - TCA	11	200
3310 Collins	1,1,1 - TCA	2.5	200
	TCE	0.9	5.
3120 17th	1,1,1 - TCA	2.8	200
	TCE	2.0	<u>5</u> 7
3102 16th	1,1 - DCE	1.1	7
·	CIS 1,2 - DCE	1.5	70
	1,1,1 - TCA	7.0	200
	TCE	3.1	5
_	PCE	0.7	5
430 Martin	CIS 1,2 - DCE	2.0	70
	TCE	4.8	5
	PCE	4.7	5
3110 10th	TCE	2.9	5
3110 10th (dup)	TCE	2.4	5 5 5 5
2619 Lindberg	1,1 - DCE	0.8	7
_	CIS 1,2 - DCE	1.1	70
	TCE	3.2	5
	PCE	0.6	5
3245 9th	1,1,1 - TCA	1.9	200

Table 4-3 (CONT.)

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINAN LEVEL (ug/l)
3239 Kishwaukee	PCE	1.8	5
3302 Kishwaukee	1,1,1 - TCA	2.5	200
	PCE	1.2	5
3029 Collins-msg	TCE	0.6	5
2624 5th	CIS 1,2 - DCE	14.0	70
	TCE	2.8	5
	PCE	2.1	5
3237 11th	1,1,1 - TCA	2.1	200
	TCE	0.9	5
	PCE	0.7	5
1202 Brooke	1,1,1 - TCA	4.5	200
	TCE	1.6	5
3115 7th	1,1,1 - TCA	3.0	200
	TCE	. 1.0	5
	PCE	1.3	5
3137 Marshall	1,1,1 - TCA	3.4	200
	TCE	1.8	5
1317 Brooke	CIS 1,2 - DCE	0.5	70
·	1,1,1 - TCA	4.7	200
	TCE	2.3	5
1726 Pershing	1,1,1 - TCA	4.1	200
	TCE	2.1	5
1637 Pershing	1,1,1 - TCA	3.1	200
	TCE	1.7	5
3210 9th	1,1,1 - TCA	3.2	200
	TCE.	2.0	5
	PCE	2.4	5
3129 Horton	TCE	0.8	5
3202 Kishwaukee	1,1,1 - TCA	3.4	200

Table 4-3 (CONT.)

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINANT LEVEL (ug/l)
3038 Bildahl	1,1,1 - TCA	2.9	200
	TCE	1.6	5
3141 Bildahl	1,1,1 - TCA	3.8	200
	TCE	2.2	5
	PCE	2.3	5
3213 Lapey	TCE	1.4	5
1713 Harrison	1,1 - DCE	1.5	7
	CIS 1,2 - DCE	5.8	70
	1,1,1 - TCA	33	200
	TCE	3.3	5
	PCE		5
3138 Lapey	1,1,1 - TCA	4.0	200
	TCE	2.7	5
3103 Lapey	1,1,1 - TCA	2.8	200
	TCE	1.8	5
3126 Collins	1,1,1 - TÇA	2.9	200
	TCE	2.0	5
3122 Bildahl	1,1,1 - TCA	3.9	200
	TCE	2.7	5
3122 Bildahl (dup)	1,1,1 - TCA	4.1	200
_	TCE	2.6	· 5
3206 Bildahl - msd	1,1,1 - TCA	2.7	200
	TCE	1.9	5
3101 9th	1,1,1 - TCA	3.8	200
	TCE	2.1	5
3072 8th	1,1,1 - TCA	21.0	200

Table 4-3 (CONT.)

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINANT LEVEL (ug/1)
3138 8th	1,1,1 TCA	3.9	000
3138 8th	TCE		200
	PCE	2.5	5
2100 016	1,1,1 TCA	1.0 3.3	5
3109 8th			200
1000 11 11	TCE	1.8	5
1630 Hamilton	1,1,1 TCA	3.0	200
	TCE	1.9	5
841 Roosevelt	1,1,1 TCA	2.4	200
	TCE	0.9	5
	PCE	2.4	5
804 Taft	1,1,1 TCA	1.4	200
	PCE	1.1	5
3333 Kishwaukee	1,1-DCE	0.7	7
	TCE	1.2	5
3014 Saner	1,1,1 TCA	2.0	200
	TCE	0.7	5
	PCE	2.8	5
1101 Brooke	1,1,1 TCA	2.2	200
	TCE	0.7	5
3013 Lapey	1,1,1 TCA	4.3	200
1 2	TCE	2.2	5
	PCE	0.6	5
3013 Lapey (dup)	1,1,1 TCA	4.2	200
A 0 - A-	TCE	2.2	5
2646 Sewell	1,1 - DCE	1.2	7
	1,1,1 TCA	39.0	200
	TCE	0.7	5

Table 4-3 (CONT.)

ADDRESS	CONTAMINANT (ug/l)	CONCENTRATION (ug/l)	MAXIMUM CONTAMINANT LEVEL (ug/l)
3017 Bildahl	CIS 1,2 - DCE	0.1	7
	- 1,2 - DCA	1.6	5
505 Barnum	TCE	0.5	5
3122 16th	1,1,1 - TCA	2.9	200
	TCE	1.3	5
2703 20th	1,1 - DCA	1.1*	NA

Table 4-4

ADDRESS	HAZARD INDEX	CARCINOGENIC TARGET ORGAN HAZARD INDEX	NON-CARCINOGENIC TARGET ORGAN HAZARD INDEX
	>1		
430 Martin		1.9	
,	0.75-1		
409 Brooke		0.88	
3102 16th		0.76	
2619 Lindberg		0.76	
2624 5th		0.98	
3141 Bildahl		0.90	
1713 Harrison		0.80	
3210 9th		0.88	<u> </u>
	0.5 - 0.74		
3015 11th		0.66	· · · · · · · · · · · · · · · · · · ·
2905 Saner		0.54	
3237 8th		0.56	
3110 10th		0.58	
3138 Lapey		0.54	
3122 Bildahl		- 0.52	
3138 8th		0.70	
841 Roosevelt		0.66	
3014 Saner		0.70	
3013 Lapey		0.56	

Table 4-4 (CONT.)

ADDRESS	HAZARD INDEX	CARCINOGENIC TARGET ORGAN HAZARD INDEX	NON-CARCINOGENIC TARGET ORGAN HAZARD INDEX
	0.25-0.49		
2620 Lindale		0.40	
2412 Lindberg		0.32	
2801 Collins	-	0.40	0.27
2602 17th	•		0.32
3120 17th		0.40	
3239 Kishwaukee		0.36	
3237 11th		0.32	
1202 Brooke		0.32	
3115 7th		0.46	
3137 Marshall		0.36	
1317 Brooke		0.46	÷
1726 Pershing		0.42	
1637 Pershing		0.34	
3038 Bildahl		0.32	
3213 Lapey		0.28	
1713 Harrison			0.42
3101 Lapey		0.36	
3126 Collins		0.40	
3206 Bildahl		0.38	
3101 9th		0.42	
3109 8th		0.36	
1630 Hamilton		0.38	
2646 Sewell		·	0.37
3122 16th		0.26	

Table 4-4 (CONT.)

ADDRESS	HAZARD INDEX	CARCINOGENIC TARGET ORGAN HAZARD INDEX	NON-CARCINOGENIC TARGET ORGAN HAZARD INDEX
	0.0-0.24		
1735 Hamilton		- 0.16	
2955 11th		0.20	
1617 Lyran		0.24	
3015 11th			0.03
326 Brooks		•	0.19
2620 Lindale			0.01
2905 Saner			0.01
409 Brooke			0.10
3301 8th		0.22	
3109 20th		0.24	•
2602 17th		0.22	
2315 Harrison			0.18
3310 Collins		0.18	0.01
3120 17th			0.01
3102 16th			0.21
430 Martin			0.03
2619 Lindberg			0.13
3245 9th			0.01
3302 Kishwaukee		0.24	0.01
3029 Collins		0.12	
2624 5th			0.20
3237 11th			0.01
1202 Brooke			0.02
3115 7th			0.02
3137 Marshall	·		0.02

Table 4-4 (CONT.)

ADDRESS	HAZARD INDEX	CARCINOGENIC TARGET ORGAN HAZARD INDEX	NON-CARCINOGENIC TARGET ORGAN HAZARD INDEX
,	0.0-0.24		
1317 Brooke			0.07
1726 Pershing			0.02
1637 Pershing			0.02
3210 9th			0.02
3129 Horton		0.16	
3202 Kishwaukee			0.02
3038 Bildahl			0.01
3141 Bildahl			0.02
3138 Lapey			0.02
3101 Lapey			0.01
3126 Collins			0.01
3122 Bildahl			0.02
3206 Bildahl			0.01
3101 9th	,		0.02
3022 8th	·		0.11
3138 8th		·	0.02
3109 8th			0.02
1630 Hamilton			0.02
841 Roosevelt			0.01
804 Taft		0:22	0.01*
3333 Kishwaukee	•	0.24	0.10
3014 Saner			0.01
1101 Brooke		0.14	0.01
3013 Lapey		-	0.02
2646 Sewell		0.14	
3017 Bildahl	·	0.02	0.00
505 Barnum	•		0.10
3122 16th			0.01

which duplicate samples were obtained were also listed. The distribution of these wells is illustrated in Figure 4-1. These wells are primarily located in the south central portion of the study area.

Contamination was detected above an MCL for one or more contaminants in 25 of the 117 wells sampled. A list of these wells along with the contaminants and associated concentrations detected above MCLs is presented in Table 4-2. The distribution of these wells is illustrated in Figure 4-2. All but one of these wells is located west of 11th Street. The frequency of detection above MCLs is shown below for each contaminant.

CONTAMINANT	NO. OF WELLS DETECTED ABOVE MAXIMUM CONTAMINANT LEVELS
TCE 1,1-DCE PCE	22 11 9
1,1,1-TCA 1,2-DCA	2 2
cis-1,2-DCE Vinyl Chloride	2 1
Pb	2

Contamination was detected at levels below MCLS at 60 of the 117 wells sampled. A list of these wells along with the contaminant concentrations detected are presented in Table 4-3. The distribution of these wells and the hazard indices associated with the mixtures of contaminants detected are presented in Figures 4-3 and 4-4.

It should be noted that at one well, located at 2703 20th Street, only 1,1-DCA was detected (Table 4-3). There is no MCL or Illinois Potable Resource Criterion for this compound.

The mixtures detected represent typical transformation pathways for volatile chlorinated aliphatic chemicals (Smith and Dragun, 1984). Trichloroethylene (TCE) was detected at 53 of the 60 wells where

contaminants were detected at concentrations below MCLs. In many cases TCE was detected in combination with either a possible precursor, PCE, or its breakdown products, cis 1,2-DCE or 1,1-DCE. TCE and 1,1,1-TCA, contaminants that are not associated via their transformation pathways, were also frequently detected together.

At fifteen of these wells only one contaminant was detected. In nine of these cases TCE was the sole contaminant detected although PCE, cis-1,2-DCE, and 1,1,1-TCA were also detected as sole contaminants. In many of these wells only one carcinogenic substance and one non-carcinogenic substance comprised the mixture of contaminants detected. At 22 of these wells, the mixture of contaminants consisted of TCE and 1,1,1-TCA only.

Only one well had a carcinogenic hazard index above 1. Seven wells had hazard indices between 0.75 and 1; 10 wells had hazard indices between 0.50 and 0.74; 24 wells had hazard indices between 0.25 and 0.49 and 53 wells had hazard indices between 0.0 and 0.24. There were no non-carcinogenic hazard indices above 0.42. It should be noted that wells at which both non-carcinogenic and carcinogenic contaminants were detected may appear in more than one hazard index category.

Out of 18 wells with hazard indices above 0.5 (all carcinogenic) the most frequently found contaminant mixture was TCE and PCE, found at 13 of these wells. At 8 of these wells 1,1,1-TCA was also detected, although its presence as a non-carcinogen did not contribute to the hazard index.

The relatively low hazard indices calculated for the majority of wells in the study area do not appear to indicate a significant problem with regard to contaminant mixtures detected at concentrations below MCLs. However, wells within the two highest hazard index categories, greater than 1 and 0.75 to 1 may be of concern. It is important to consider the temporal movement of the contaminant plume because the contaminant profiles evaluated in this section will likely be influenced by such movement.

4.4 CONCLUSIONS

4.4.1 COMPARISON OF DATA TO MAXIMUM CONTAMINANT LEVELS

At 25 wells within the study area, contaminant concentrations exceed MCLs. The table below presents the excess lifetime cancer risks (ELCR) associated with lifetime ingestion of drinking water contaminated at concentrations equivalent to an MCL. These risks were calculated using standard exposure assumptions and the Cancer Potency Factors listed in the table.

COMPOUND	MCL (ug/1)	CANCER POTENCY FACTORS	ASSOCIATED EXCESS LIFETIME CANCER RISK
PCE	5	5.1×10^{-2} (USEPA, 1989)	7.2×10^{-6}
TCE	5	1.1×10^{-2} (USEPA, 1989)	1.6×10^{-6}
1,2-DCE	5	9.1 x 10 ⁻² (USEPA, 1990)	1.3×10^{-5}
Vinyl Chloride	2	2.3 (USEPA, 1989)	1.3×10^{-4}

Exposure to contaminant concentrations above the MCL will be associated with cancer risks greater than the ELCRs listed above. Wells with particularly high concentrations of PCE, TCE, and vinyl chloride would be in the 1 x 10^{-4} to 1 x 10^{-3} cancer risk range. These levels are significantly higher than generally accepted cancer risk limits. It should be noted that cancer risks attributable to non-potable uses of the water (showering/bathing and other household water use), may be as high as risks attributable to ingestion of this water.

For non-carcinogens, the daily doses received as a result of ingestion of water contaminated at concentrations equivalent to MCLs and the Reference Doses (RfDS) for these contaminants are presented in the table below. An RfD represents the dose, which, if consumed for a lifetime, is not expected to result in any adverse health effects.

COMPOUND	MCL (ug/l)	DOSE/MCL (mg/kg/day)	REFERENCE DOSE (mg/kg/day)
1,1-DCE	7	2×10^{-4}	9×10^{-3} (USEPA, 1898)
trans-1,2-DCE	100	3×10^{-3}	2×10^{-2} (USEPA, 1990)
1,1,1-TCA	200	6×10^{-3}	9×10^{-2} (USEPA, 1990)
cis-1,2-DCE	70	2×10^{-3}	NA

Exposure to a concentration equivalent to an MCL would not result in a dose that exceeds any of the available RfDs. Although contaminant concentrations in a number of the study area wells are significantly higher than MCLs, it is not expected that exposures to contaminants at these concentrations would result in a dose in excess of any one RfD. However, if dose additivity is assumed, mixtures of similarly acting contaminants present in these wells may pose an unacceptable non-cancer risk. A more thorough evaluation of the non-carcinogenic risks associated with exposure to contaminant concentrations at these wells was beyond the scope of this assessment.

4.4.2 CARCINOGENIC HAZARD INDICES

Contamination was detected at concentrations below MCLs at 60 of the 117 wells. In all but 1 of these wells the carcinogenic hazard index is derived from PCE and/or TCE. A very low concentration of 1,2-DCE was detected in only one well. One of the evaluated wells had a carcinogenic hazard index greater than 1. For this well, an excess lifetime cancer risk of 8.3×10^{-6} has been calculated using standard exposure assumptions and Cancer Potency Factors of 5.1×10^{-2} and 1.1×10^{-2} for PCE and TCE respectively (USEPA, 1989).

Referring to the groundwater standards and associated cancer risks presented above, exposure to contaminant concentrations which result in a hazard index of 1 would be associated with an excess lifetime cancer risk of between approximately 7.2×10^{-6} and 1.3×10^{-4} , depending on the

components of the contaminant mixture. Because all other study area wells have carcinogenic hazard indices less than 1, the ELCR associated with exposure to drinking water at these wells will be less than 7.2×10^{-6} . Depending upon the particular regulatory framework used, these risks may or may not be considered significant.

4.4.3 NON-CARCINOGENIC HAZARD INDICES

Non-carcinogenic hazard indices did not exceed 1 for any of the wells at which contamination was detected at concentrations below MCLs. Therefore, the non-carcinogenic risks do not appear to be significant at these locations.

5.0 SUMMARY AND CONCLUSIONS

As a result of this study, the following conclusions were reached:

- 1. Based on the IEPA/USEPA data, a west-northwest trending plume of VOC contaminated groundwater extends across the study area from the vicinity of Reed Avenue and 24th Street. The contaminant plumes for TCE, 1,1,1-TCA, cis-1,2-DCE, 1,2-DCA, and 1,1-DCA have the same general features. Vinyl chloride and trans-1,2-DCE were detected at only a few locations in the study area. PCE had a distinctly shaped plume.
- 2. Based on the IDPH data, the plumes for TCE, 1,1,1-TCA, and 1,1-DCA show general features that are similar to the plumes for the IEPA/USEPA data.
- 3. Safe Drinking Water Act MCLs were exceeded for TCE, 1,1,1-TCA, cis-1,2-DCE, 1,2-DCA, 1,1-DCE, vinyl chloride, and lead, over various portions of the study area. The area where the TCE MCL is exceeded encompasses all of the other areas where any other MCL is exceeded except for a small area stretching from approximately Harrison Avenue and Kinsey Street to Wills Avenue and Marshall Street, and a single well located near 9th Street and Sandy Hollow Road (Figure 3-25).
- 4. Groundwater contamination by metals does not show a systematic distribution comparable to that observed for VOCs. Instead, localized metals contamination occurs at scattered locations across the study area, and appears to be the result of several unrelated point sources. Only two of the 117 samples collected for the Operable Unit remedial investigation exceeded an MCL for any metal.

- 5. At locations where MCLs were exceeded, levels of groundwater contamination pose both carcinogenic and non-carcinogenic health hazards. Outside the area where MCLs were exceeded, an evaluation of cumulative health risks showed that in general, Hazard Indices did not exceed 1. Non-carcinogenic health hazards in the study area do not appear to be significant. According to USEPA risk assessment guidance, a non-carcinogenic Hazard Index of less than 1 indicates that exposure to contaminants at these levels would not be associated with adverse health effects.
- 6. Contamination was detected above an MCL for one or more contaminants at 25 of the 117 wells sampled in this investigation. Excess lifetime cancer risk levels at a number of these wells are significantly greater than generally accepted cancer risk limits. Risks incurred as a result of exposure to non-carcinogenic contaminants in these wells may be significant if dose additivity is assumed.

6.0 REFERENCES

- Illinois State Geological Survey (ISGS). 1975. Handbook of Illinois Stratigraphy. By William, H.B.; E. Atherton.; T.C. Buschbach.; C. Collinson.; J.C. Frye.; M.E. Hopkins.; J.A. Lineback.; and J.A. Simon. Urbana, Illinois.
- Illinois State Water Survey (ISWS). 1988. A Regional Groundwater Quality Characterization of the Rockford Area, Winnebago County, Illinois. By Wehrmann, H.A.; T.R. Holm.; L.P. Le Seur.; and C.D. Curtis III. Champaign, Illinois.
- Illinois State Geological Survey (ISGS) and Illinois State Water Survey (ISWS). 1985. Cooperative Groundwater Report 10: Geology, Hydrology, and Water Quality of the Cambrian and Ordivician Systems in Northern Illinois. By Visocky, A.P.; M.G. Sherrill.; and K. Cartwright. Champaign, Illinois.
- Smith, L.R., and J. Dragun. 1984. <u>Degradation of Volatile Chlorinated</u>
 <u>Aliphatic Priority Pollutants in Groundwater</u>. <u>Environment International</u>
 10 (4): 291-298.
- United States Environmental Protection Agency (USEPA). Office of Health and Environmental Assessment (OHEA). 1986. Guidelines for Health Risk Assessment of Chemical Mixtures. FR Vol. 51 34014-34025.
- United States Environmental Protection Agency (USEPA). Data Review Work Group. 1988. Laboratory Data Validation: Functional Guidelines for Evaluating Organics Analyses.
- United States Environmental Protection Agency (USEPA). Data Review Work Group. 1988. Laboratory Data Validation: Functional Guidelines for Evaluating Inorganics Analyses.
- United States Environmental Protection Agency (USEPA). Office of Drinking Water. 1989. Proposed Requirements for 38 Inorganic and Organic Drinking Water Contaminants. Washington, D.C.
- United States Environmental Protection Agency (USEPA). Office of Health and Environmental Assessment. 1989. Health Effects Assessment Summary Tables Fourth Quarter. Fy 1989. Washington, D.C.
- United States Environmental Protection Agency (USEPA). Office of Solid Waste and Emergency Response. 1989. CERCLA Compliance with Other Laws Manual: Part II. Clean Air Act and Other Environmental Statutes and State Requirements. Washington, D.C.
- United States Environmental Protection Agency (USEPA). Environmental Criteria and Assessment Office. 1990. Integrated Risk Information System. Cincinnati, Ohio.

APPENDIX A

SAMPLE COLLECTION SHEETS

Address: 2819 S 4th Steet	Sample No:	
Resident's Name: Ester Bace ley	Samplers: Bob Hank	
Date:	Sample Time: 1603	
Start Purge: \SS	Est. Flow Rate: 27 seconds	
End Purge: 603	1 gai.	
Stabilization Parameters:		
Trial Time pH Conductivity 1 1601 7.01 630 2 1603 7.03 630 3 1603 7.03 630 4	within these ranges: emp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.	
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
NA A		
Other Comments:	•	

Address: 2828 5.4th Steet	Sample No:	
Resident's Name: Mone Brown	Samplers: Rob Hank Robin Dorby	
Date: 6/11	Sample Time: 1525	
Start Purge: 1509	Est. Flow Rate: 38 Seconds	
End Purge: 1525	1 9011	
Stabilization Parameters:		
Trial Time pH Conductivity 1 1519 6.98 630 2 1522 7.02 730 3 1524 7.07 730 4 1525 7.07 730 5	77° = 77° =	
Comments:	•	
Location of sample point: Kitchen Sink		
Water Softener or other treatment? No U	verter Sofke	
Aerator on sample point spigot? O ocd	batone Scupling	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)	
apport 32-33 year old we	-11	
Other Comments: Single handle	Frencet	
hard to determine exact cold waster		
position		

Address: Loslie & Martha Wilson	Sample No:
Resident's Name: <u>2901</u> 5 Fourth	Samplers: Sent Hodge / Robin Noun
Date: 6/12/90	Sample Time: /3:53_
Start Purge: <u>L:39</u>	Est. Flow Rate: 1 gallon 25 second
End Purge:	
Stabilization Parameters:	
Trial Time pH Conductivity = ± 50 µmhos/cm,	fall within these ranges:
Comments: Location of sample point: Outdoor sp A Long Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, dat	e drilled, static water level, etc.)
Other Comments:	
	

Address: 3045 1 4 14	Sample No:
Resident's Name: Douglas Brown	Samplers: NORTH Butler
Date: $6/14/40$	Sample Time:
Start Purge: 11 24	Est. Flow Rate: 1 gt in 7 Sec.
End Purge: 1/38	0
Stabilization Parameters:	
Trial Time pH Conductivity 1 135 4.57 760 2 11 36 4.55 740 3 11:37 4.57 740 4 11:38 4.51 720 5 6 7 Purge is adequate if three consecutive readings fall w pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	CLO F CL
Comments: Location of sample point: Outside spige of house	st, south side
Water Softener or other treatment?	
Aerator on sample point spigot?	ed, static water level, etc.)
Other Comments:	

Address: a624 5 Fifth	Sample No:	
Resident's Name: MARIN PUCZYNSKY	Samplers: Butler/ Morton	
Date: 6/14/90	Sample Time: 15.10	
Start Purge: 14:47	Est. Flow Rate:	
End Purge: 15:09		
Stabilization Parameters:		
Trial Time pH Conductivity 1 1457 3.46 600 2 1458 3.71 596 3 1457 3.69 570 4 15.00 407 590 5 15.05 4.14 550 6 1508 590 7 Purge is adequate if three consecutive readings fall of the pH = ± 0.25, conductivity = ± 50 \text{ µmhos/cm, and the comments:} Location of sample point: Outside Africa.	(3.5) (3.5) (3.5) (3.5) (3.5) within these ranges:	
Water Softener or other treatment?		
Aerator on sample point spigot? γ_b		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
Other Comments:	•	

Address: 3/15 5 F	Sample No:
Resident's Name: Am aro Villalohas	Samplers: Butler / Parton
Date: 6/14/90	Sample Time: 16:05
Start Purge:	Est. Flow Rate: 1 th. in 55cc.
End Purge: 16:04	V
Stabilization Parameters:	
Trial Time pH Conductivity 1 1200 3.51 850 2 1203 3.57 800 3 1204 3.70 7790 4 5 6 7 Purge is adequate if three consecutive readings fall wpH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point:	$\frac{59 \circ F}{59 \circ F}$ $\frac{58 \circ F}{58 \circ F}$ within these ranges: $emp. = \pm 0.5 \circ C (\pm 2 \circ F).$
Water Softener or other treatment? You Han	e was a filter, but
Water Softener or other treatment? Jos Han	Sompling.
Aerator on sample point spigot?	<i>U</i>
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Other Comments:	

Address: 3233 74	Sample No:		
Resident's Name: Mary Higder	Samplers: Buc	be/Morh	
Date: # 6/13/90	Sample Time:	1\$:54	
Start Purge: 14:30	Est. Flow Rate:	I quart in Edico	
End Purge: 15-54	• •	•	
Stabilization Parameters:		•	
Trial Time pH Conductivity 1 $\cancel{14.40}$ 5.86 $\cancel{070}$ 2 $\cancel{14.45}$ 5.67 $\cancel{050}$ 3 $\cancel{14.40}$ 5.37 $\cancel{010}$ 4 $\cancel{14.47}$ 5.38 $\cancel{010}$ 5 $\cancel{14.51}$ 5.62 $\cancel{0.50}$ 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments: Location of sample point: Outlide Aprigo	$\frac{60}{60}$ $\frac{60}{60}$ $\frac{60}{60}$ within these ranges: $\frac{1}{2} = \pm 0.5 \text{ °C (4)}$	<u>-</u> 2°F).	
Water Softener or other treatment? \(\square \text{\square} \)			
Aerator on sample point spigot?			
Other Comments: Well only used for water	or water;	Láma,	

Address: 3309 9th 14	Sample No:		
Resident's Name: Buth Stuckland	Samplers:	the Morton	
Date: 6/14/90	Sample Time: _	923	
Start Purge: 9.04	Est. Flow Rate:	1	Su
End Purge: 922			
Stabilization Parameters:			
Trial Time pH Conductivity 1 9:15 3.56 700 2 9:16 3.75 720 3 9:17 4.30 690 4 9:19 4.16 700 5 9:20 4.58 690 6 9:21 4.59 670 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and to Comments: Location of sample point: Gastack sparse	$\frac{(6)^{\circ}F}{(60)^{\circ}F}$ $\frac{(60)^{\circ}F}{(60)^{\circ}F}$ $\frac{(60)^{\circ}F}{(60)^{\circ}F}$ $\frac{(60)^{\circ}F}{(60)^{\circ}F}$ $\frac{(60)^{\circ}F}{(60)^{\circ}F}$ within these ranges emp. = ± 0.5 °C (60)	<u>+</u> 2°F).	
Water Softener or other treatment?			
Aerator on sample point spigot?			
Well Construction: (depth, PVC, stainless, date drille	ed, static water le	vel, etc.)	- · · · · · · · · · · · · · · · · · · ·
Other Comments:			
•			
			·

Address: 2810 5. 8th Street	Sample No:		
Resident's Name: Lloyd: Tommie Minnick	Samplers: Buthe (Mouton		
Date: 6/13/10	Sample Time: 17:08		
Start Purge: 16:56	Est. Flow Rate: 1 gallon 20 second		
End Purge: 17:07	\mathcal{G}		
Stabilization Parameters:			
Trial Time pH Conductivity 1 17 04 496 60 2 17 05 505 60 3 17:07 7 20 610 4 5 6 7 Purge is adequate if three consecutive readings fall wpH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point:	$\frac{60.5}{57.5}$ $\frac{57.5}{}$ within these ranges: $emp. = \pm 0.5 ^{\circ}C (\pm 2^{\circ}F).$		
Water Softener or other treatment?			
	·		
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drill	•		
Other Comments:			

Address: A914 gth St	Sample No:
Resident's Name: Onne Trese	Samplers: Butter / Horton
Date: 6/14/70 ·	Sample Time: 12130
Start Purge: 12 17	Est. Flow Rate: / quart in le second
End Purge: (d:29	V
Stabilization Parameters:	
Trial Time pH Conductivity 1 1227 459 710 2 1238 453 690 3 1239 454 750 4 — — 5 — — 6 — — 7 — — Purge is adequate if three consecutive readings fall we pH = ± 0.25, conductivity = ± 50 μmhos/cm, and to	\(\frac{6}{6}\) \(\frac{6}{6}\) \(\frac{1}{6}\) \(\frac{1}{6}
Comments: Location of sample point: Outside Aprigate of house Water Softener or other treatment? Yo	t ir shel west sich
Aerator on sample point spigot?	ed, static water level, etc.)
Other Comments:	
•	•

Address: 3022 8 =	Sample No:		
Resident's Name: Anna Abbott	Samplers: Lour 2 Rhaget		
Date: 6/17	Sample Time: /325		
Start Purge: 1254	Est. Flow Rate: 15-pl in 63 spc		
End Purge: _/3 ZZ			
Stabilization Parameters:			
Trial Time pH Conductivity 1 1317 $\pm \%$ $\pm \%$ 2 1318 $\pm \%$ $\pm \%$ 3 1319 $\pm \%$ $\pm \%$ 4 1319 $\pm \%$ $\pm \%$ Purge is adequate if three consecutive readings fall w pH = ± 0.25 , conductivity = $\pm \%$ pmhos/cm, and to	$\frac{59^{\circ}F}{58}$ $\frac{58}{58}$ $\frac{58}{58}$ within these ranges:		
Comments: Location of sample point: Ourside apiget	Noveleast side of brouse		
Water Softener or other treatment? No liketur	subsever or other treatment		
Aerator on sample point spigot? <u>Kh</u> Well Construction: (depth, PVC, stainless, date drill 2" Steel castny, Well has s	led, static water level, etc.)		
Other Comments: Well is localed in out 5 to most pipes one golisius zed	basement, line steading to		

Address: 3109 8 5	Sample No:		
Resident's Name: Phillip Jacob son	Samplers: Lout Z/Blocat		
Date: 6/17	Sample Time: _/555		
Start Purge: 15 26	Est. Flow Rate: 2.5 gal in 2 min 5		
End Purge:	(125 50		
Stabilization Parameters:			
Trial Time pH Conductivity 1 1547 7.25 750 mhss 2 1548 7.23 150 3 1549 7.24 760 4	56 56 —————————————————————————————————		
Location of sample point: <u>Kitchen Sink</u>	No outside faccet.		
Water Softener or other treatment? No Works	- Sofrerer		
Aerator on sample point spigot? No - rahsu	At before sampling		
Well Construction: (depth, PVC, stainless, date drille	ed, static water level, etc.)		
Well is about 37' deep - driven. 2'	" steel well, Hit water at		
ewand 26'			
Other Comments: All papes leading	up to sample point are		
gatranized steel	, ,		
	,		
	· · · · · · · · · · · · · · · · · · ·		

Address: 3/38 8 5 S	Sample No:		
Resident's Name: Robert Olomon S	Samplers: Laur = / Shagat		
Date: $6/2$ S	Sample Time: 1515		
Start Purge: 1646 E	est. Flow Rate: 2.5 gal in 35 sec		
End Purge: 1512			
Stabilization Parameters:	. ·		
3 1509 $\frac{7.27}{7-26}$ $\frac{950}{950}$ 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and tem Comments:	$\frac{55.5}{55}$ $\frac{55}{55}$ hin these ranges: $p. = \pm 0.5 \text{ °C } (\pm 2 \text{°F}).$		
Location of sample point: District Spigat Water Softener or other treatment? No little So Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled All nelso property out to sample 73 years old of 1 "negaling ted Other Comments: Sight Signal Sampless.	d, static water level, etc.)		

Address: 3201 5. 877 5T.	Sample No:		
Resident's Name: Mv. Gollegos	Samplers: Butter / Mortes		
Date: 4/13/90	Sample Time:		
Start Purge: 10:47	Est. Flow Rate: Sallon in 20 Sec		
End Purge: 11.03			
Stabilization Parameters:			
Trial Time pH Conductivity 1 $0:57$ 5- 01 5 0 2 $0:57$ 5- 01 5 0 3 $0:57$ 5- 01 5 0 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to	62°F 40°F 40°F 40°F within these ranges:		
Comments:			
Water Softener or other treatment? 26	west see.		
A			
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)		
Other Comments:	· · · · · · · · · · · · · · · · · · ·		

Address: 3237 8 # 5	Sample No:		
Resident's Name: James Handern	Samplers: Buller / Morton		
Date: $6-13$	Sample Time: _		
Start Purge: 9:57	Est. Flow Rate:	1 gallor lu	20.sec.
End Purge: 1025		. ~	
Stabilization Parameters:			
Trial Time pH Conductivity 1 0.07 6.35 790 2 0.13 26 790 3 15.15 6.38 790 4	Leo F Leo F Lo I o F		
Location of sample point: Outsile Aprigo	f west s	ede of Gove	<u></u>
Water Softener or other treatment?/c			
Aerator on sample point spigot?	ed, static water le	vel, etc.)	
Other Comments: Bring fairt. Affin w/ so buthles attempted wing & Reportal attempts still results buthles	erail diffe	they swarf	rites.

Address: \(\frac{7}{3301}\) Sample No:
Resident's Name: Mrs Iva Ebel Samplers: Butle / Horton
Date: $4/3/90$ Sample Time: $9:44$
Start Purge: 9:31 Est. Flow Rate: 2.5 gal us 50 S
End Purge: 9.44
Stabilization Parameters:
Trial Time pH Conductivity Temp. 1 9:42 6-54 830 61°F 2 9:43 6-51 810 62°F 4
Water Softener or other treatment?
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)
Other Comments:

Address: 3337 8 +4	Sample No:
Resident's Name: MARVETA Ellenburger	Samplers: Butler / Norta
Date: $\frac{\zeta/(3/90)}{}$	Sample Time: 9:15
Start Purge: 9:47	Est. Flow Rate: 1 grad in 20 Accords
End Purge: 9:14	•
Stabilization Parameters:	PU ENU T
Trial Time pH Conductivity 1 8 57 5 82 720 2 9 00 5 65 700 3 9 01 5 80 490 4 9 03 6 14 700 6 9 13 6 48 690 7 9 14 6 90 Purge is adequate if three consecutive readings fall when the pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: μ	(7°) 4'15 6.50 690 6 (2°) E (1°) E (1°) E (1°) E (2°) E
Water Softener or other treatment? 70	
Aerator on sample point spigot?	led, static water level, etc.)
Other Comments: <u>Pressure</u> pump tu of failed. Will take 3 more temperature tests;	erned on-lead to two

Address: Q910 9+4 Jf	Sample No:
Resident's Name: Crunwell & Consy Fultz	Samplers: Menta Butter
Date: 6/15/90.	Sample Time:
Start Purge: 15.36	Est. Flow Rate: Igellan 19 sur
End Purge: 15:51	/
Stabilization Parameters:	C 75tx 4
Trial Time pH Conductivity 1 547 9.24 000 2 548 9.24 000 3 1550 9.32 000 4 1551 9.40 590 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25, conductivity = ± 50 µmhos/cm, and to Comments: Location of sample point: ontloor Apricate	$\frac{100F}{610F}$ $\frac{1}{610F}$ $\frac{1}{610F}$ $\frac{1}{610F}$ $\frac{1}{6100F}$ \frac
Water Softener or other treatment? No	
Aerator on sample point spigot? Mc	
Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.)
Birdent doesn't know a	nighting short He will
	/ V
Other Comments:	

Address: 3101 9 42 S	ample No:
Resident's Name: Charlotte Thompsons	amplers: 1225
Date: 6/17 Sunday S	ample Time: Lautz / Phagat
Start Purge:	ist. Flow Rate: Iliser in 10 sec.
End Purge: 1223	•
Stabilization Parameters:	
Trial Time pH Conductivity 1 1218 7.26 670 unhas 2 1219 7.31 670 3 1220 7.36 670 4 1221 7.33 670 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25, conductivity = ± 50 µmhos/cm, and term Comments: Location of sample point: Kitchen Suick	- · · · · · · · · · · · · · · · · · · ·
Water Softener or other treatment? No Water S	Asener or other realment
Aerator on sample point spigot? No - token Well Construction: (depth, PVC, stainless, date drilled Well is at least 15 years old	l, static water level, etc.)
Other Comments:	

Address: 3210 9th St	Sample No:	
Resident's Name: Garly Amith	Samplers: Butler/ Morton	
Date: 4/15/40	Sample Time:	
Start Purge: 10:59	Est. Flow Rate: 1 gellens 36 seconds.	
End Purge:		
Stabilization Parameters:		
Trial Time pH Conductivity 1 11:09 5-98 600 2 11:11 5-99 600 3 11:11 5-99 600 4 5-99 600 4 5-99 600 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm, and to Comments:}}}	G(-5 G2 G2 G2 Within these ranges:	
Water Softener or other treatment? Hot Area, but we rampled from outside spegot. RN for No. No Wale Infine.		
Aerator on sample point spigot? Y/Q		
Well Construction: (depth, PVC, stainless, date drill	<u>.</u>	
Nell more of metal paper. No other info. Other Comments: Falfar was asleep, but told chellen to let us souple when we arrived. Son did not Coll cround likepen, Man con		
ant lita	· (

Address: 3245 9 ^{+h} 14	Sample No:	
Resident's Name: Judy Bennett	Samplers: North Buch	
Date: 6/15/98 6/14/90	Sample Time: 9:44	
Start Purge: <u>17.44 9:30</u>	Est. Flow Rate: 1 gunt in Accord	
End Purge: 4.43	i	
Stabilization Parameters:	2 Holling	
Trial Time pH Conductivity 1 9:41 4:66 720 2 9:42 4.73 720 3 9:43 4.73 730 4	6 (C) E	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	-	
Comments: Location of sample point: Augustus Water Softener or other treatment?	rigot or west side of	
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
Other Comments: 1st must 6/13/90	On to formale to	
try singler a seron	time on 6/14/90.	

Address: 3110 10th 5t	Sample No:
Resident's Name: William Ponnell	Samplers: Butland Vanha
Date: $\frac{6\sqrt{3}/90}{}$	Sample Time: 18.22
Start Purge: 6016.03/8.03	Est. Flow Rate: in (second
End Purge: 18.2/	C
Stabilization Parameters:	
Trial Time pH Conductivity 1 18:14 5.40 7/0 2 18:7 6.57 700 3 18:7 7.20 69:0 4 18:3) NA 700 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments:	$\frac{60}{60}$ $\frac{60}{60}$ within these ranges: $emp. = \pm 0.5 \text{ °C } (\pm 2^{\circ}\text{F}).$
Location of sample point: Orthole spige	A south seil of home
Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Other Comments:	•

Address: 3102 16 4 5t.	Sample No:	
Resident's Name: Tammie Balos	Samplers: Lant 2/ Rys	
Date: 6/13	Sample Time: 14:41	
Start Purge: 14 22	Est. Flow Rate: 1/2 gol in 11 sec.	
End Purge: 14:41	I measured from Milk	
Stabilization Parameters:		
Trial Time pH Conductivity 1 14136 3.37 540 2 14137 3.31 540 3 1439 7.33 530 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: $\frac{5\rho \cos t}{2}$ on $\frac{1}{2}$	$\frac{57^{\circ}F}{55^{\circ}F}$ $\frac{56^{\circ}F}{56^{\circ}F}$ within these ranges: $emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F).$	
Water Softener or other treatment? No Water Aerator on sample point spigot? No		
	lad attatic water level atta	
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Nesident doesn't know details.		
Other Comments: Well is visible in Lors of rast particle	yard SW of house	
	·	

Address: 3/22 16 -	Sample No:
Resident's Name: <u>Lobest Jones</u>	Samplers: Lout = /Ry<
Date: _6/13	Sample Time:
Start Purge: 14:56 Bage waruged	Est. Flow Rate: Igal in 8 sec.
End Purge: /5 26	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1521 7.37 530	Temp.
2 1522 7.31 520	5-4
3 <u>1524</u> 7.32 <u>520</u>	54
4 1525 1.36 510	54
5	
6	 *
7	iskin shann mann
Purge is adequate if three consecutive readings fall w $pH = \pm 0.25$, conductivity = $\pm 50 \mu mhos/cm$, and to	
Comments:	
Location of sample point: Outside spigat	real porce on wes
side of House	
Water Softener or other treatment? No wolf	a softener or other treatment
Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date drill-	ed, static water level, etc.)
Other Comments: well is visible in well was worked on approx	bushes on west side of lone
well was worked on approx	10 days ago, resident doesist
know what work was done	
<u> </u>	

Address: 312017 St.	Sample No:
Resident's Name: Roser Schultz	Samplers: Can+ 2/Ryce
Date: <u>6/13</u>	
Start Purge: 12:22	Est. Flow Rate: 2.5 gpl in 33 sec.
End Purge: 12:40	
Stabilization Parameters:	
Trial Time pH Conductivity 1 /235 7.37 505 2 /230 7.35 500 3 /237 7.36 500 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and the Comments: Location of sample point: μ	$\frac{55^{\circ}F}{55^{\circ}F}$ $\frac{55^{\circ}F}{55^{\circ}F}$ within these ranges: $emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F).$
	led, static water level, etc.)

Address: 3110 18 -	Sample No:	
Resident's Name: <u>Teff Dobbs</u>	Samplers: Lautz/Rys	
Date: 6/13	Sample Time:	
Start Purge: 18:10	Est. Flow Rate: 1 sol in 11 sec	
End Purge: 18:3/		
Stabilization Parameters:		
Trial Time pH Conductivity 1 1826 7.31 550 2 1827 7.31 550 3 1828 7.31 650 4 550 4 550 Purge is adequate if three consecutive readings fall wpH = ± 0.25, conductivity = ± 50 µmhos/cm, and to Comments: Location of sample point: Outside Spigor	$\frac{570F}{550F} = 2050F$ $\frac{550F}{550F} = 2050F$ within these ranges: $emp. = \pm 0.5 \text{ °C } (\pm 2^{\circ}F).$	
Water Softener or other treatment? No Wester	sofunde or other realment	
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.)	
Well duitled pre-1965		
Other Comments: Well is visible in		
	Here. Was Difficult to obtain	
4 GOOD VOC SAMPLE 2 bal	bles were an excessive problem	
<u> </u>		

Address: 2703 20 2	Sample No:
Resident's Name: Shoval 1 thto	Samplers: Lante/Blaget
Date: 6/17	Sample Time: <u>/6 30</u>
Start Purge:	Est. Flow Rate: 2.5 3 d in 24 sec
End Purge: 16 26	"
Stabilization Parameters:	
Trial Time pH Conductivity 1 1622 7.23 465 1165 2 1623 7.23 465 3 1624 7.33 466 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm, and to Comments:}}} Location of sample point: Cutside Synger	$\frac{56^{\circ}F}{56}$ $\frac{56}{56}$ within these ranges: $emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F).$
Water Softener or other treatment? In trading cell solding to residual Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drill Candon del del man del Other Comments:	led, static water level, etc.)

Address: 3109 20 1/2	Sample No:	
Resident's Name: Robert Williams	Samplers: Lantz/Rys	
Date: 6/13	Sample Time:	
Start Purge: 10.36	Est. Flow Rate: 25 second	
End Purge: 10:55		
Stabilization Parameters:		
Trial Time pH Conductivity 1 1046 7.25 490 2 1050 7.31 477 3 1051 7.30 472 4 1052 7.31 472 5 1053 7.31 471 6 7 Purge is adequate if three consecutive readings fall wpH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: Outside Spiso (600.55)	$\frac{58\%}{57\%}$ $\frac{57\%}{57\%}$ $\frac{55\%}{55\%}$ $\frac{55\%}{55\%}$ within these ranges: $emp. = \pm 0.5\% C (\pm 2\%).$	
Water Softener or other treatment? No Wolfs	Sofrance or other treatment	
Aerator on sample point spigot? No		
Well Construction: (depth, PVC, stainless, date drill		
Well was dvilled in ~1900, extended to suprox. 150' in ~1980.		
6" disincter steel casing.		
Other Comments: Well is an 5W side of house		
	<u> </u>	
· · · · · · · · · · · · · · · · · · ·		
	<u> </u>	

Address: 505 Barreum Roi.	Sample No:
Resident's Name: Len Olszewski	Samplers: Lant 2/Black
Date: 6/19	Sample Time: 1805
Start Purge:	Est. Flow Rate: 2.5 gal. in 30 sec
End Purge: 1803	•
Stabilization Parameters:	
Trial Time pH Conductivity 1 1800 7.12 750 and the second secon	57.5°F 57 57 54 within these ranges:
Location of sample point: Cutside Spiger	t, Southcast side of house
Water Softener or other treatment? Filmstein Spect by passes film. Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date drill will is 60 lest deep, stell fixe	
Other Comments:	

Address:_ Sample No: _ Colordater Samplers: North Knoth Resident's Name: 7/20. Sample Time: 160/ Date: gillor 25 secons Est. Flow Rate: Start Purge: End Purge: Stabilization Parameters: Conductivity Trial рH Temp. 710 1 2 700 3 5 6 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Location of sample point: (Intern spift) north rich Water Softener or other treatment? Y/L Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)

Address: 3019 Bildafl	Sample No:	
Resident's Name Gover Nelson	Samplers: Butley Nodge	
Date: 6/19/90	Sample Time: 2150	
Start Purge: 2:35	Est. Flow Rate: 2.5 Sal in 40 Sec	
End Purge: 2,50		
Stabilization Parameters:		
Trial Time pH Conductivity 1 $\frac{2:45}{2:44}$ $\frac{7.34}{7.39}$ $\frac{7/9}{7/2}$ 3 $\frac{3:47}{2:48}$ $\frac{7.34}{7.34}$ $\frac{7/9}{7/9}$ 4 $\frac{2:48}{7.34}$ $\frac{7.79}{7.34}$ Purge is adequate if three consecutive readings fall w pH = ± 0.25, conductivity = ± 50 µmhos/cm, and to	_	
Comments:		
Location of sample point: Southwest conv.	n of house - spiget.	
Water Softener or other treatment? \(\frac{1}{2} \to \)		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drille	ed, static water level, etc.)	
aco - approx. 40 - 45 yrs. De:		
Sotto & sol, Johnson Point; 25 source tons		
Other Comments:	· · · · · · · · · · · · · · · · · · ·	
	·	
	·	
·		

Address: 3038 Bildsell	Sample No:	
Resident's Name: Mrs Margaret Kan Vorken	Samplers: 7	orten/Bertler
Date: 6/15/50	Sample Time: _	• •
Start Purge: 12:02	Est. Flow Rate:	Igallon in 40 secon
End Purge: 12:23	•	J
Stabilization Parameters:		
Trial Time pH Conductivity	Temp.	
1 (21) 8.71 From	<u> </u>	
2 12:13 8.61 650	63	
3 12:14 8.19 690	<u>63</u> .	
4 12.14 <u>7.62</u> 690	63	
5 12 15 7.37 790	<u>63</u>	
6 12:19 7.05 750	<u>63</u>	•
7 12:22 7.01 750	<u>63</u>	•
Purge is adequate if three consecutive readings fall w	•	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	emp. = ± 0.5 °C (\pm	₋ 2°F).
Comments:		
Location of sample point: Ktchen spigot.		
		,
- 20		
Water Softener or other treatment?		
		
Aerator on sample point spigot?		·
	ad centic syntage las	ral atc.)
Residut Sudat here ony in	/- /-	/
Freder dedot here ony in	Coloration or	· Not
well.		<u> </u>
Other Comments:		
		•

Address: 3/22 Bildahl Sa	mple No:	
Resident's Name: Delos Kewish San	mplers: <u>loustz/Bhacat</u>	
Date: 6/16 Sa	mple Time: 1445	
and the second s	t. Flow Rate: 25 golin 38 soc	
End Purge: 1438		
Stabilization Parameters:		
Trial Time pH Conductivity 1 1433 $\frac{7.15}{7.15}$ $\frac{753}{733}$ 2 1435 $\frac{7.15}{7.15}$ $\frac{733}{7.30}$ 3 1436 $\frac{7.15}{7.14}$ $\frac{7.20}{7.20}$ 5 $\frac{6}{7}$ Purge is adequate if three consecutive readings fall within pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp	•	
Location of sample point: Dutside sproof toother side of house Sample sproof changed after lading at well of flumbing Water Softener or other treatment? Water Softener inside house, but Dutside top by passas softener Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Notice to the special languary of well construction, well Ladi probably duilled pro-pro Other Comments: Well is occasiod in hasamount of house Dutside att sample taken here. Rain censed prices of topics. Language Sand present in well water (reddish colic)		

Address: Galine 3141 Bildahl Sample No:
Resident's Name: Onlar Belluss Samplers: Buller Month
Date: 6/15/40 Sample Time: (2.50
Start Purge: 4:37 Est. Flow Rate: Ligables in 36 so
End Purge: 149
Stabilization Parameters:
Trial Time pH Conductivity Temp. 1 1247 7-5 10 760 62°F 2 1348 7-68 750 CeO°F 3 1349 7-52 740 (eo°F 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F).
Location of sample point: Ontsele speget west sele of home Water Softener or other treatment?
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)
Other Comments: Mrs. Bellan was arrow that we would be
corring to single Howers, stream ont (will 9-organ) at the time the proposition allowed as to simple

Address: 3206 Bildahl	Sample No:	
Resident's Name: Linda Kesley	Samplers: Lintz/Bliagat	
Date: 6/16	Sample Time: 1530	
Start Purge: 1503	Est. Flow Rate: 2.5 gal in 37 soc	
End Purge: 1526		
Stabilization Parameters:	· ·	
Trial Time pH Conductivity 1 $\frac{5.22}{5.23}$ $\frac{7.04}{7.09}$ $\frac{722}{710}$ 2 $\frac{5.24}{7.09}$ $\frac{7.09}{7.01}$ $\frac{710}{710}$ 4 $\frac{525}{7.01}$ $\frac{7.09}{7.01}$ $\frac{710}{710}$ Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments: Location of sample point: $\frac{0.73}{20}$ $\frac{3.42}{30}$	$\frac{59.8^{\circ}F}{58.9}$ $\frac{58.7}{58.7}$ $\frac{58.7}{58.7}$ within these ranges: $emp. = \pm 0.5 ^{\circ}C (\pm 2^{\circ}F).$	
Water Softener or other treatment? Water Softeness is by passed by outside		
Aerator on sample point spigot? No		
Well Construction: (depth, PVC, stainless, date drill		
2" still n3er jige, well is at least 17 years old Well depth		
is approximately to feet,		
Other Comments: Like powhing to found is PUC. Well is Iccoled		
in taxable of hour Martin Spite Sample Talon have		

Address: 3302 Beldel Sample No:		
Resident's Name: <u>Irvin Miller</u> Samplers: <u>Horton</u> /Butler		
Date: 6/5/90 Sample Time: 1476		
Start Purge: 14-07 Est. Flow Rate: 1921lon and 8 Hezon		
End Purge: 14:25		
Stabilization Parameters:		
Trial Time pH Conductivity Temp. 1 14.17 8.85 $7/0$ 6.3.5 2 14.20 8.33 $7/0$ 6.3.5 3 14.24 8.33 $7/0$ 6.3 4 14.25 8.34 $7/0$ 6.3 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Noth Adl Location of sample point: Settle A.7 In Section 7 In Section 8 In		
Water Softener or other treatment? NO		
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Well is = to yes all is = 60 ft less. Well to plumbing in how is noted, but prime leading to outlook well are in the Comments:		

Address: 3338 Bildall	Sample No:	
Resident's Name: Walter Corey	Samplers: <u>Novem/Buttle</u>	
Date: 6-15-90	Sample Time: /5-00	
Start Purge: <u>14:45</u>	Est. Flow Rate: Lyllen Hours	
End Purge: 14.59		
Stabilization Parameters:		
Trial Time pH Conductivity Temp. 1 (455 8.14 690 00 F 2 (457 8.07 650 59°F 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ± 0.25, conductivity = ± 50 \mumbhr/mhos/cm, and temp. = ± 0.5°C (±2°F). Comments: Location of sample point: Outlood Aprox.		
Water Softener or other treatment? (fis, but	not harled upto	
Aerator on sample point spigot? \mathcal{N}_{\bullet}		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) He sendent had no information short the well.		
Other Comments:	•	
· · · · · · · · · · · · · · · · · · ·		

Address: 10 Brooke Sample No:		
Resident's Name: Ray Mc-Elyea Samplers: Almanzi / Holge		
Date: 6-17-90 Sample Time: 1440		
Start Purge: 1421 Est. Flow Rate: 2.5 991 / 17 5ec		
End Purge: 1439		
Stabilization Parameters:		
Trial Time pH Conductivity Temp.		
1 1436 7.27 827 4Mho 71.4°		
2 1437 7.28 782 4alo 65.50		
3 1438 7.28 7751Aho 65.5°		
4 1439 7.29 7749Alo 64.4°		
5		
6		
7		
Purge is adequate if three consecutive readings fall within these ranges:		
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F).		
Comments:		
Location of sample point: West side of house (spigof)		
A >		
Water Softener or other treatment?		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) ~ 40 1/5		
old, Stoel Const.		
Other Comments: None (Tefles tape on ARigot)		

Address: 202 Brooks	Sample No:	
Resident's Name: John Kacque	Samplers: Bob Hand Roken Hoof	
Date: 6/12/90 V	Sample Time: I guart in 15 Accor	
Start Purge: 1641	Est. Flow Rate: 1655	
End Purge: 1655		
Stabilization Parameters:		
Trial Time pH Conductivity 1 1052 7.15 600 2 1053 7.15 600 3 1055 7.28 600 4 5 6 7 Purge is adequate if three consecutive readings fall w pH = ± 0.25 , conductivity = ± 50 μ mhos/cm, and to	59 60 59 vithin these ranges:	
Comments: Location of sample point:		
Water Softener or other treatment?		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 37/4 deep Well make of mothly bonessoner thinks its iron.		
Other Comments:		

Address: 326 Brooke	Sample No:	
Resident's Name: Juseph Conti	Samplers: Bob Hank / Robin Non	
Date: 6/12/90	Sample Time: 16: 23	
Start Purge: /4-04	Est. Flow Rate: 1 gallon 25 second	
End Purge: 16. 31	$m{y}$	
Stabilization Parameters:		
Trial Time pH Conductivity 1 166 7.30 400 2 169 7.40 400 3 1622 7.40 405 4 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25, conductivity = ± 50 µmhos/cm, and to Comments: Location of sample point: Oxford Aprigate	vithin these ranges:	
Water Softener or other treatment?		
Aerator on sample point spigot? 70		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
-	Uput in Gyens ago In that	
Will just 2 feet away Other Comments:		

Address: 409 Bruke	Sample No:
Resident's Name: Debbre Gardner	Samplers: Rober Worten Bb Hank
Date: 6/12/90	Sample Time:
Start Purge: ドラント	Est. Flow Rate: guart at 10 xxxx
End Purge: 15:31	V
Stabilization Parameters:	
Trial Time pH Conductivity 1 15:32 7.44 700 2 15:34 7.47 700 3 15:35 7.47 700 4 5 6 7 Purge is adequate if three consecutive readings for pH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and Comments: Location of sample point: Author spin	$\frac{6+}{6+}$ $6+$
Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date	drilled, static water level, etc.)
Other Comments:	
· -	

Address: 823 Brooks	Sample No:
Resident's Name: <u>Betty</u> Bloom	Samplers: Lantz/Butler
	Sample Time: _/6 Z2
Start Purge: 15:57	Est. Flow Rate: 2.5 gol en 1:15 S
End Purge: 16-22	
Stabilization Parameters:	
Trial Time pH Conductivity 1 16/5 7.05 700 2 16/7 7.05 690 3 16/9 7.04 690 4 5 6 7 Purge is adequate if three consecutive readings fall worth pH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm, and to Comments:}}} Location of sample point: \(\$\text{\$\	$\frac{58^{\circ}F}{58^{\circ}F}$ $\frac{58^{\circ}F}{58^{\circ}F}$ within these ranges: $emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F).$
Water Softener or other treatment? No water	sofrerer or reatment
Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date drill well is probably about D years of	
Other Comments: Duplicate taken Le	280;

Address: 1202 Brooke	Sample No:
Resident's Name: Oscar Cronquist	Samplers: Butter (NORtor)
Date: 6/14/90	Sample Time: <u>435</u>
Start Purge: 1620	Est. Flow Rate: 1 gustin 12 se
End Purge: 1634	Ö
Stabilization Parameters:	
Trial Time pH Conductivity 1 1631 4.66 800 2 1633 4.74 800 4 5 6 7 Purge is adequate if three consecutive readings fall when the phase of the p	Within these ranges:
Water Softener or other treatment? No	
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date dril	lled, static water level, etc.)
Other Comments:	

Address: 1317 Brucke	Sample No:	
Resident's Name: Monica Hinkle	Samplers: Butter / Monton	
Date: 6/14/10	Sample Time: 1744	
Start Purge:	Est. Flow Rate: frank in Exerc	
End Purge: 1739	V	
Stabilization Parameters:	79	
Trial Time pH Conductivity 1 /733	Temp. 59°F 59°F 59°F 58°P within these ranges:	
Comments:	;	
Location of sample point: Detrick spigot ent sele		
Water Softener or other treatment? \(\frac{1}{2} \)		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
	4	
Other Comments:		

	Sample No:	
Resident's Name: Hower King	Samplers: Lantz/Rys	
Date: 6/13	Sample Time: 16.29	
Start Purge: 16:08	Est. Flow Rate: 1gal in 10 sec.	
End Purge: 1628		
Stabilization Parameters:		
Trial Time pH Conductivity 1 /623	$\frac{56^{\circ} F}{56^{\circ} F}$ $\frac{56^{\circ} F}{56^{\circ} F}$ ithin these ranges: $mp. = \pm 0.5^{\circ} C (\pm 2^{\circ} F).$	
Water Softener or other treatment? No Water Softener or other treatment		
Aerator on sample point spigot? No		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
Well was driven 2 415 950, 50 feet deep, 2" steel pipe		
Other Comments: Collected MATZIT Spile DuplicaTe		
·		

Address: 3029 Colling	Sample No:
Resident's Name: Bill Cofield	Samplers: Butter/Norton
Date: 6/14/90	Sample Time: 14:35
Start Purge: 14.19	Est. Flow Rate: 1 quad in 6 Acco
End Purge: 14.34	V
Stabilization Parameters:	
Trial Time pH Conductivity 1 1429 4.08 750 2 1431 4.02 710 3 1433 4.58 710 4 1434 4.01 710 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and the consecutive readings.	62°F 62°F 62°F COZ°F
Location of sample point: Outside A	bugut south side
Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date dril	led, static water level, etc.)
Other Comments:	
·	(

Address: 3126 Collins	Sample No:
Resident's Name: Mack Boyd	Samplers: Lant = / Bliaget
Date: 6/16/90	Sample Time: (215
Start Purge: 11:53	Est. Flow Rate: 2.5 gal in 40 =
End Purge: 12/3	
Stabilization Parameters:	en e
Trial Time pH Conductivity 1 1209 7.39 650 μm 2 1210 7.40 640 3 1211 7.41 650 4 5 6 7 Purge is adequate if three consecutive readings fall of pH = ± 0.25, conductivity = ± 50 μmhos/cm, and the pH = ± 0.25, conductivity = ± 0.25, co	bs 56°F 56 56 56 within these ranges:
Comments: Location of sample point: Outside spige South Scale of house Water Softener or other treatment? No water	
Aerator on sample point spigot?	
Other Comments: Sample point of	s prosected hours rain

Address: 3245 Collins	Sample No:	
Resident's Name: John Bare field	Samplers: Lantz/Rys	
Date: 6/13	Sample Time: <u>17:10</u>	
Start Purge:	Est. Flow Rate: 19d in 15 sec	
End Purge: 17:09		
Stabilization Parameters:		
Trial Time pH Conductivity 1 17.03 7.22 6/0 2 17:05 7.24 590 3 17:06 7.24 580 4 17:07 7.26 580 5	Temp. 860° F 570 F 570 F	
Purge is adequate if three consecutive readings fall within these ranges: $pH = \pm 0.25$, conductivity = $\pm 50 \mu \text{mhos/cm}$, and temp. = $\pm 0.5 ^{\circ}\text{C}$ ($\pm 2^{\circ}\text{F}$). Comments: Location of sample point: $Dutside Seise Measure Mea$		
Water Softener or other treatment? Water Softener by passed on outside top. Aerator on sample point spigot? No. Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Drilled before 1950, Regident doesn't know or his debails. Other Comments: Will is in basement		
	·	

Address: 330 Collins San	nple No:
Resident's Name: Jon Flyng & San	nplers: Noton/Butlac
	nple Time:
Start Purge: 11-17 Est	Flow Rate: 1 spelon in 17 we
End Purge: // 32	,
Stabilization Parameters:	
2 11:29 5.77 (200 5 3 11:30 5.71 (200 5	
Comments: Location of sample point: Outside Spegot Water Softener or other treatment?	south sels of house
Aerator on sample point spigot?	static water level, etc.)
Other Comments:	

Address: 3045 Great Peric Blod Sample No:		
Resident's Name: Robert Housek Samplers: Almanes / Hoolge		
Date: 6-16-90 Sample Time: 1214		
Start Purge: 1146 Est. Flow Rate: 1 at 14 Sec.		
End Purge: 1212		
Stabilization Parameters:		
Trial Time pH Conductivity Temp. 1 1204 7.24 495 4 Mac 65.2 2 1208 7.29 480 4 Mac 62.6 3 1210 1.33 476 4 Mac 62 4 1211 7.32 414 4 Mac 62 5		
Location of sample point: N. W. Side of House		
Water Softener or other treatment? None		
Aerator on sample point spigot? No (spigot)		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 5 + c = 1, 5 (a) 10 w, ~ (760		
Other Comments: NONE (Field Blank Molketed gt this location) (Sample Time 1216)		

Address: 3107 Grant Parice Bluck.	_ Sample No:		
Resident's Name: Oroille Morris	Samplers: Almans Hedge		
Date: 6-17-92	Sample Time:		
Start Purge: 1255	Est. Flow Rate: 2.5 9-1 /9/ Sec -		
End Purge: 1313			
Stabilization Parameters:			
Trial Time pH Conductivit	y Temp.		
1 1308 7.12 656 9AGO			
2 1309 7.13 6374440			
3 1310 7-13 6334Mho	1 0		
4 1311 7.11 6304ALO	•		
5 1312 7.13 6264Mbo			
6			
7			
7	· · · · · · · · · · · · · · · · · · ·		
Purge is adequate if three consecutive readings fall			
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and	temp. = ± 0.5 °C (± 2 °F).		
Comments:			
Location of sample point: Kitchen 5	c ~ K		
Water Softener or other treatment? <u>Cold</u> u	vater is Not Softened.		
Aerator on sample point spigot? $\sqrt{e \leq B}$	Let Removed.		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) ∼ 36 ++			
Deep. Galvanized Steel,			
Other Comments: Hot water 1	s softenel Cold is		
Not.			
	1		

//	
Address: 1630 Hinth	Sample No:
Resident's Name: Liley Maralette	Samplers: Muston Butle
Date: 6/18/90	Sample Time:
Start Purge: 10 34	Est. Flow Rate: 1 gellor 48 de
End Purge:	
Stabilization Parameters:	
Trial Time pH Conductivity 1 10:50 7:27 67660	61.5
2 <u>10.574</u> <u>7.30</u> <u>156</u> 3 <u>10.55</u> <u>7.31</u> <u>550</u>	<u>595</u> 59 5
4	
5	
6	
7	
Purge is adequate if three consecutive readings fall w $pH = \pm 0.25$, conductivity = $\pm 50 \mu mhos/cm$, and to	
Comments:	•
Location of sample point: Bathroom spin	7 06.
Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.) <u>Mall</u>
is about 40 years old. To	
is analyte.	
Other Comments: Aone superday	l Artal
(2) 2 7 T	
	/
• • • • • • • • • • • • • • • • • • • •	

Address: 1735 Hamilton	Sample No:
Address: 1735 Hamilton Resident's Name: Kaven Chester	Samplers: Lauty, Butter
Date: 6/11/90	
Start Purge: 1: 56	Est. Flow Rate: 2.5 gol in 25 s
End Purge: 2: 13	,
Stabilization Parameters:	
Trial Time pH Conductivity 1 $\frac{2:07}{2:08}$ $\frac{7.28}{1.25}$ $\frac{610}{000}$ 2 $\frac{2:09}{3:25}$ $\frac{7.25}{7.24}$ $\frac{600}{000}$ 4 $\frac{2:11}{7.24}$ $\frac{7.24}{0.00}$ Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and comments: Location of sample point: $\frac{0.015ide}{0.00}$ $\frac{500}{0.00}$	$\frac{\cancel{64}^{\circ} \cancel{F}}{\cancel{59}^{\circ} \cancel{F}}$ $\frac{\cancel{59}^{\circ} \cancel{F}}{\cancel{59}^{\circ} \cancel{5}^{\circ}}$ within these ranges: temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
Water Softener or other treatment?	
Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date dril	lled, static water level, etc.)
Other Comments: <u>Recenth installed</u> Well is visition we Steel construction	1 side of house

Address: 17/3 How vi som	Sample No:
Resident's Name: George Kitchinger	Samplers: Lant 2/ Alman zer-
Date: <u>6/15</u>	Sample Time:
Start Purge: <u>/4/55</u>	Est. Flow Rate: 2.5 gcl in 45 see
End Purge: 15 10	
Stabilization Parameters:	
Trial Time pH Conductivity	
1 1314 7.14 640 water	56.50
2 1516 7.15 63c 4/16	
3 1516 7.15 630 9.44c	<u>56°</u>
. 4	-
5	•
6	•
7	
Purge is adequate if three consecutive readings fall w	vithin these ranges:
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	emp. = ± 0.5 °C (± 2 °F).
Comments:	
	was interested to
Location of sample point: Outside roup of	west side of house
Water Softener or other treatment? No water	sofeen or filters.
	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	ed. static water level. etc.)
-	
well is us' deep, 2" Steel can	ung - FOC runnites to fump
Other Comments: Well is located in	bosement
<u></u>	\

Address: 1817 How/1302 Sample No:	
Resident's Name: Prenda Boynton Samplers: Lout 2/A/man 2a	
Date: <u>6/18</u> Sample Time:	
Start Purge: 1053 Est. Flow Rate: Lites in 5500	
End Purge: 11/8	
Stabilization Parameters:	•
Trial Time pH Conductivity Temp.	
1 1113 7.20 709 58.40=	
2 1114 7.20 B700 57.8° F	
3 1115 7.21 700 58.0°F	
4 1116 7-20 696 58.0°=	
5	
6 ·	
7	
Purge is adequate if three consecutive readings fall within these ranges:	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F).	
Comments:	
Location of sample point: Outsile spicot, South side of House	
• • • • • • • • • • • • • • • • • • • •	
	<u> </u>
Water Softener or other treatment?	
Water Softener or other treatment?	
Water Softener or other treatment? 7 Aerator on sample point spigot? No	
Water Softener or other treatment?	
Water Softener or other treatment? 7 Aerator on sample point spigot? No	
Water Softener or other treatment? 7 Aerator on sample point spigot? No	
Water Softener or other treatment? Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)	
Water Softener or other treatment? Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Landaut Not Home	
Water Softener or other treatment? Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Landart Not Home Making Spile duplicate rature have	
Water Softener or other treatment? Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Landart Not Home Making Spile duplicate rature have	
Water Softener or other treatment? Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Landaut Not Home	

VICTORY Tap		
Address: 2315 Harrison	Sample No:	
Resident's Name: Counte Besimude 2	Samplers: Lourt/Rys	
Date: 6/13	Sample Time: 11 90	
Start Purge:	Est. Flow Rate: 2.5 gal in 25 coc	
End Purge: 11-57		
Stabilization Parameters:		
Trial Time pH Conductivity	y Temp.	
1 11:51 7:14 640	56°	
2 <u>11:53</u> <u>7:13</u> <u>640</u>	570	
3 11:54 7.13 640	<u> 570 PL 550</u>	
4 11:55 7.14 640	<u>55°</u>	
5 11:56 7.14 640	550	
6		
7	· · · · · · · · · · · · · · · · · · ·	
Purge is adequate if three consecutive readings fall	within these ranges:	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and	temp. = ± 0.5 °C (± 2 °F).	
Comments:		
Location of comple point: Right Spices	rear door on S. Side of Bids	
Location of sample point. Brass spriger	rem mor on 3, not of Boy	
Water Softener or other treatment? <u>Unite</u> 50	frence is weed, but sample is	
definitely not estrened.	· · ·	
Aerator on sample point spigot? ν_{σ}		
Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.)		
Manager does not know any details about well.		
*Counie		
Other Comments: <u>Augie Proven Zan</u>	o is owner of 6/dg.	
Well is located in concret	to well house on 5 and	
of building, Duplicates Sample TAICEN Here.		
Purce water is cloudy.	(

Address:3.(29 Horron		Sample No:	
Resident's Nam	e: David R	enk	Samplers: <u></u>	autz / Alumanya
Date: 6/15			Sample Time:	11:50
Start Purge: //	E4 .	•	Est. Flow Rate	: Approx 1 gal in 155
End Purge:	YO 11:42			(can't measure accurates
Stabilization Par	rameters:			because krices is at
Trial Tic	, -	Conductivity	Temp.	
1 <u>H3</u>	6 7.32	<u>550 yuch</u>	55.5	
2 113	1 1.31	510 4MOL		
3 <u>//3</u>	7.28	5504mol		•
4 1140	2.30	550 4,40h	556	
5			 	
6				
7		. ———		*
Purge is adequa	te if three consecutive	readings fall w	ithin these range	es:
$pH = \pm 0.25$, co	onductivity = \pm 50 μ m	nhos/cm, and to	emp. = ± 0.5 °C	(±2°F).
Comments:				
	,		F 10.00 1 0 1	vace at front (E)
Location of san	nple point: <u>Outs</u>	य स्माद्	e rear coa	vage at that CE F
side of	hous	·		
Water Softener	or other treatment? _	Pin 60/1.	uot:	•
		<u> </u>		
Aerator on sam	ple point spigot? 📈	2		
Well Construct	ion: (depth, PVC, stai	nless, date drill	ed, static water l	level, etc.)
well is a	of least 134	ears do	1 resided	ut elossit luca
	tails of will			
Other Commen	is: Well is vis	ible in 1	ur aid past	of house new knew
Other Comments: Well is visible in your past of house new kines Legident is pretty sure abe doesn't jay water all				
* Duplizate Sample tohon have.				
x Duglical	is sample to	show have	<u>-</u> ·	
		1		
			·	

Address: 1737 Johnson	Sample No:
Resident's Name: Lauvi Edwards	Samplers: Lantt, Butler
Date: 6/11/90	Sample Time: 2:52
Start Purge: 2:35	Est. Flow Rate: 2.5 gel un 29 Sur
End Purge: 2:52	
Stabilization Parameters:	
Trial Time pH Conductivity 1 2:46 7-94 629 2 2:48 7-03 625 3 2:49 7-01 620 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	56° F 55.5° F 55° F within these ranges:
Comments: Location of sample point: 5W corner of	House; outside Spigot
Water Softener or other treatment? No Water	Lotina.
Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date drill frohably installed in 1940's	
Other Comments: House is on Well to be taken here	wolls; Duplicate sample

Address: Bill Hoppur Sample No:
Resident's Name: 410 Kinnon Samplers: Bruthe / Norton
Date: 4/19/90 Sample Time: ## Pmb 4:12
Start Purge: 4:00 Est. Flow Rate: 2.5 Sal in 14
End Purge: 4:12 and 50
Stabilization Parameters:
Trial Time pH Conductivity Temp. 1 $\frac{4:08}{0.08}$ $\frac{7.31}{7.29}$ $\frac{7.4}{0.08}$ $\frac{5.6}{0.08}$ $\frac{7.29}{0.08}$ $\frac{6.4}{0.08}$ $\frac{7.29}{0.08}$ 7
Water Softener or other treatment?
Aerator on sample point spigot? TW Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) <u>dessint</u> Chow any 9 about - Other Comments: <u>Water Lested by 100H approx. 5 menths</u> 4 ying lay passes hading Lank; will do MSD here.

Address: U21 Konnon	Sample No:
Resident's Name: Robert: Merianne darre	Samplers: Mortin Butler
Date: 4/18/40	Sample Time: 10.29
Start Purge: 16 15	Est. Flow Rate: Lapelon 20 per onle
End Purge: 16.28	1
Stabilization Parameters:	
Trial Time pH Conductivity 1 / $\frac{2}{6}$ 7-29 7($\frac{2}{6}$) 2 / $\frac{5}{27}$ 1.32 720 3 / $\frac{6}{28}$ 7.34 720 4	$\frac{60.10F}{59.50F}$ $\frac{59.50F}{50.50F}$ within these ranges: $emp. = \pm 0.5 \text{ °C } (\pm 2 \text{°F}).$
youre.	
Water Softener or other treatment?	
Aerator on sample point spigot? 70	
Well Construction: (depth, PVC, stainless, date drill	·
Other Comments:	

Address: 3037 kishwantee Sa	mple No:
Resident's Name: Filowich Sa	mplers: Laurz Humanze
Date: <u>6/14</u> Sa	mple Time: 1955
Start Purge: 1925 Es	t. Flow Rate: 2.5 gal in 55 sec.
End Purge: (1950	•
Stabilization Parameters:	
Trial Tune pH Conductivity 1 1953 7.24 813 2 1951 7.26 813	can be bypassed by
Aerator on sample point spigot? No	·
Well Construction: (depth, PVC, stainless, date drilled, fesidlet doeslit want to to	
Other Comments: Will is located in Co	marete pit nout of house

Address: 3202 195hwauker	Sample No:
Resident's Name: Llora Ohnstad	Samplers: Butla / Moch
Date: 6/15/40	Sample Time:
	Est. Flow Rate: 1978 in 221
End Purge:	\mathcal{G} . The second of \mathcal{G} is the second of \mathcal{G} . The second of \mathcal{G}
Stabilization Parameters:	•
Trial Time pH Conductivity 1 1/37 4.74 6(0) 2 1/38 6.62 6.6 3 1/39 6.55 4(0) 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and tental Comments:	•
Location of sample point: Litchen splgor	t
Water Softener or other treatment?	••
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drilled Ohnstorl at the Sold not have the well. Other Comments: This site well to	on engthery shoul
	·

Address: 3d 39 Rishwaukee	Sample No:
Resident's Name: Larry Phillis	Samplers: Belle Burton
Date: 6/14/90	Sample Time: 10.13
Start Purge: 9:58	Est. Flow Rate: 1 quant in 7 second
End Purge: 10:i)	
Stabilization Parameters:	
	T
<u>Trial Time pH Conductivity</u> 1 10:08 4.44 670	Z Temp.
1 10:08 4.64 670 2 10:09 4.64 670	61
3 10:10 461 760	61_
4 10:11 4.56 720	61
5 10:12 4.54 710	<u></u>
6	
7	
Purge is adequate if three consecutive readings fall v	_
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and t	temp. = ± 0.5 °C (± 2 °F).
Comments:	<i>*</i>
Location of sample point: Catal spis	not west side house
)
W	
Water Softener or other treatment?	
	·
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date dril	led, static water level, etc.)
- A To - A - A - A - A - A - A - A - A - A -	
- 1 2 1 - R	
Other Comments: instead of 615 80	îwryt •
	,
	·

Address: 3302 Kishwankee	Sample No:
Resident's Name: Thomas Badoles	Samplers: Nonzon Bultar
Date: 6/14/90	Sample Time: 10:44
Start Purge: 10 28	Est. Flow Rate: 1 gt in Second
End Purge: 10 - 43	\mathcal{V}
Stabilization Parameters:	
Trial Time pH Conductivity 1 /0 39 $\frac{465}{465}$ 500 2 /0 41 $\frac{4.42}{4.39}$ 690 4 /0 43 $\frac{4.39}{4.32}$ 696 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments: Location of sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point: Outside $5 pigat$, expressions of the sample point of the samp	$\frac{60.5}{60}$ $\frac{60.5}{60}$ $\frac{60.5}{60}$ $\frac{60}{60}$ $\frac{60.5}{60}$ $\frac{60}{60}$ $\frac{60.5}{60}$ $\frac{60}{60}$ $\frac{60.5}{60}$ $\frac{60}{60}$ $\frac{60.5}{60}$ $\frac{60.5}{$
Water Softener or other treatment? No	
Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.)
Other Comments:	

Address: 3013 Lapur	Sample No:
Resident's Name laris Wincapaw	Samplers: Butler/Hodge-
Date: $\frac{0}{19}/\frac{9}{9}$	Sample Time: #====================================
Start Purge: 11:20	Est. Flow Rate: 2.5 Gpl in Inix
End Purge: 11:35 11:45	U
Stabilization Parameters:	
Trial Time pH Conductivity 1 1/:37 7.35 868 2 1/:38 7.25 849 3 11:39 7.24 837 4 1:40 7.25 851 5 11:41 7.25 857 6 11:42 7.24 822 Purge is adequate if three consecutive readings fall w pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments:	(21.8°) F 9. 11:43 7.24 825 (21.8°) F 9. 11: 14 7.25 825 (21.5°) F (2.4°) F (2.4
Location of sample point: West Sices 1	have-
Water Softener or other treatment? A U	· .
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill 120-30 ft. de 14 shallow; dues not on wul-	led, static water level, etc.) <u>risident</u> ep) know any other info
Other Comments: Dupi late taken	leri-
	<u></u>

Resident's Name: 14 Real Standard Samplers: Lant 2 Bhazat Date: U Trice 1990 Sample Time: 1025 Start Purge: 1021 State Purge: 1021 Stabilization Parameters: Trial Time pH Conductivity Temp. 1 1017 7.47 680 55.5 3 109 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ±50 \text{ µmhos/cm, and temp. = ±0.5°C (±2°F).} Comments: Location of sample point: 0 utside spicot undure ath awains over (pch parch - 5W side of lower Water Softener or other treatment? Haveld days laws water softener, but Sample Point bypasses softener Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Swell carry Well construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Swell carry Well was duilled awarned 1950, support 30 feet days, sand print well was duilled awarned 1950, support 30 feet days, sand print well was duilled awarned 20-22 ket. Other Comments: Line from well to spigat is PVC pipe Ramus outside, but sample collocial under awains on Social foul.	Address: 3101 LAPEY	Sample No:
Date: 16 June 1990 Sample Time: 1025 Start Purge: 1021 Stabilization Parameters: Trial Time pH Conductivity Temp. 1 1017 7.47 690 und 55°F 2 1018 7.49 680 55.5 3 10 M 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ±50 µmhos/cm, and temp. = ±0.5°C (±2°F). Comments: Location of sample point: 0utside spicot underworth auruing over (pc/h pg/ch - 5W side of house Water Softener or other treatment? Haveld does have not softener but Sample four by passes to there Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel Carrier Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel Carrier Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel Carrier Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel Carrier Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel Carrier Well was drilled wayned 1950, appear 30 het deep, sand prior well Water is appear 20 - 22 het Other Comments: Line from well to spiget is PVC pipe. Raman	Resident's Name: 1400 SeeDen	Samplers: Lantz/Bhagat
End Purge: 102 Stabilization Parameters: Trial Time pH Conductivity Temp. 1 1917 7.47 690 under 55°F 2 1018 7.49 680 55.5 3 104 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ±50 \text{ \text{umbnos/cm}}, and temp. = ±0.5°C (±2°F). Comments: Location of sample point: Outside Spiret underworth awaire over (pch polich - 5W side of locate) Water Softener or other treatment? Haveld deep locate software but Sample focust begasses software Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Skel carrier Well was drilled mound 1950, approx 30 feet deep, sand print well . Watto is approx 20 - 22 ket Other Comments: Like from well to Syigot is PVC pipe Ramice	Date: 16 JUNE 1990	— •
Stabilization Parameters: Trial Time pH Conductivity Temp. 1 1017 7.47 690 under 55°F 2 1018 7.49 680 55.5 3 109 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ± 50 \text{ µmhos/cm, and temp. = ±0.5°C (+2°F).}} Comments: Location of sample point: Outside Spicot underweath awaing over (pch polich - 5W sull of house Water Softener or other treatment? Hawld day leave woth softwar, but Sample fount by presses softwar Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Swel caring well was duilled awaind 1950, approx 30 feet day, sand price well. Wath is approx 20 - 22 kg. Other Comments: Line from well to Spigot is 800 pipe Raming	Start Purge: 1058-120458	Est. Flow Rate: 275 gal in 25 sec
Trial Time pH Conductivity Temp. 1 1017 7.47 690 untr 55° F 2 1018 7.49 680 55.5 3 1019 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ±50 \text{ µmhos/cm, and temp.} = ±0.5°C (±2°F). Comments: Location of sample point: Outside spicot induve at h aunities over (pch polich - 5W side of house Water Softener or other treatment? Haveld does have water softener, but Sample fount by passes softwar Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Sheel carring Well was drilled avointed 1950, approx 30 but deep, sand price well. Water is approx 20 - 22 but Other Comments: Live from well to Spigot is PVC pipe. Ranning	End Purge: 1021	
1 1017 7.47 690 more 55°F 2 1018 7.49 680 55.5 3 10 M 7.49 680 55.5 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ±0.25, conductivity = ±50 μmhos/cm, and temp. = ±0.5°C (±2°F). Comments: Location of sample point: Outside spigot undure at a numing over (pch polich - SW side of beaux Water Softener or other treatment? Haveld dats leave water softener, but Sample point byposses softener Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" 5 well carry Well was drilled avoind 1950, approx 30 feet dasp, sand point well. Water is approx 20 - 22 kg. Other Comments: Line from well to spigot is 9VC pipe. Raming	Stabilization Parameters:	
Comments: Location of sample point: Outside spicot underweath anning over (pch forch - SW side of house Water Softener or other treatment? Havold does here hoth softener but Sample fourt bypasses softener Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Steel caring Well was drilled award 1950, approx 30 feet dap, sand point well. Water is approx 20 - 22 feet. Other Comments: Line from well to spigot is PVC pipe. Raining	1 1017 7.47 690 under 2 1018 7.49 680 3 1019 7.49 680 4	55°F 55.5 55.5
Location of sample point: Outside Spigot underseath awaine over (pch poich - SW side of house Water Softener or other treatment? Havold loss house work softener, but Sample point bypasses softener Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Steel carrier Well was drilled avoined 1950, approx 30 feet day, sand point well. Water is approx 20 - 22 feet. Other Comments: Line from well to spigot is PVC pipe. Raining	pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	emp. = ± 0.5 °C (± 2 °F).
Water Softener or other treatment? Havold block lower water softener, but Sample point bypasses softener Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Steel carrier Well was drilled award 1950, approx 30 test deep, sand point well. Water is approx 20 - 12 feet Other Comments: Line from well to spigot is PVC pipe. Raming	,	
Water Softener or other treatment? Havold dees lieus water softener, but Sample fount bypasses softener Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Skeel caring Well was drilled avoing 1950, approx 30 feet deep, sand point well. Water is approx 20 - 22 feet. Other Comments: Line from well to spigot is PVC pipe. Raming	, ,	induventh awaing over
Sample point by prises so there Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Steel Carring Well was drilled avoind 1950, approx 30 test dap, sand point well. Water is approx 20-22 test Other Comments: Line from well to spigot is PVC pipe. Raining	tack porch - SW sull of house	
Aerator on sample point spigot? <u>No</u> Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) <u>z'' 5 keel Caring</u> <u>Well was duilled answerd 1950</u> , approx 30 keet dasp, sand point <u>well. Water is approx 20 - 22 kee</u> Other Comments: <u>Line from well to spigot is PVC pipe</u> . Raining	Water Softener or other treatment? Havold Use	& here note sofrener but
Well construction: (depth, PVC, stainless, date drilled, static water level, etc.) 2" Steel carring Well was drilled avoing 1950, approx 30 feet deep, sand point well. Water is approx 20-22 feet. Other Comments: Line from well to spiget is PVC pipe. Raining	sample point bypasses sofrera	·
Well was drilled avound 1950, approx 30 test deep, sand point well. Water is approx 20-22 test. Other Comments: Line from well to spigest is PUC pipe. Raining	Aerator on sample point spigot? 100	
Well was drilled avound 1950, approx 30 test deep, sand point well. Water is approx 20-22 test. Other Comments: Line from well to spigest is PUC pipe. Raining	Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.) 2" Steel casing
Other Comments: Line from well to spigest is PUC pipe. Raining	Well was drilled around 1950,	suprox 30 test deep sand point
Other Comments: Line from well to spignet is PUC pipe. Raining		• •
· · · · · · · · · · · · · · · · · · ·		
\cdot		· · · · · · · · · · · · · · · · · · ·

Address: 3/38 La pen	Sample No:
Resident's Name: Pablo Reyes	Samplers: Lantz/Alugunza
Date: <u>6/15</u>	Sample Time: 1715
Start Purge: 16:46	Est. Flow Rate: 22.5 gal in 70 se
End Purge: <u>1715</u>	
Stabilization Parameters:	
Trial Time pH Conductivity 1 /708 7.31 660 2 /7/0 7.31 670 3 /7// 2.31 670 4 /7/2 7.30 670 5 6 7 Purge is adequate if three consecutive readings fall wpH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: $\Delta a \approx ids + tap = 0$	$\frac{62^{\circ}F}{60.5^{\circ}/F}$ $\frac{67^{\circ}F}{67^{\circ}}$ $\frac{67^{\circ}F}{67^{\circ}}$ within these ranges: $\exp P = \pm 0.5^{\circ}C (\pm 2^{\circ}F).$
Water Softener or other treatment? No water	<u> </u>
Aerator on sample point spigot? 16	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
well is at least 17 years old -	No other de fails known
2" steel casing	
Well is at least 17 years old - 2" Heel Casing Other Comments: Well is outside on	South side of house.
	

Address: 3329 La pay Sample No:		
Resident's Name: Name: Name: Name: Samplers: Lautz/Ryz		
Date: 6/13 Sample Time: 16 43		
Start Purge: 10:21 Est. Flow Rate: 15al in 46 sec.		
End Purge: 10:43		
Stabilization Parameters:		
Trial Time pH Conductivity Temp. a few weeks, but 1 1037 3.19 200 60°F would should still 2 1037 3.15 700 60 be forwarded. 3 1040 3.25 700 60 4 5 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Location of sample point: Australy Sylvy on east scale of linears Water Softener or other treatment? No water so four or other treatment?		
Aerator on sample point spigot? No. Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Ne Geliut closuit know details of well construction Other Comments: No other residents connected to thus well Well is in basement		

Address: 2406 Lindale Road Sample No:
Resident's Name: Glen Thompson Samplers: Lant 2/Butler.
Date: 6/12/90 Tuesday Sample Time: 18 39
Start Purge: 18:16 Est. Flow Rate: 2.5 gal in 28 Se
End Purge: 18:39
Stabilization Parameters:
Trial Time pH Conductivity Temp. 1 1832 7-21 510 55°F 2 1833 7-21 510 55°F 3 1835 7-16 510 55°F 4 1826 7-14 505 55°F 5 1838 7-10 505 55°F 6 7 Purge is adequate if three consecutive readings fall within these ranges: pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and temp. = ± 0.5 °C (± 2 °F). Comments: Location of sample point: Outside spiger behind western bushes on 5 .
Water Softener or other treatment? Water Softener in house, but not on
water sortener or other treatment? Which sortener in thouse, but not on
Aerator on sample point spigot?
Well was dvilled in 1960, So' deep, Aistot well first, 6' seel
Other Comments: Sand appears on bottom of pitchers Where
2 strong for pH, cond. + temp. Lots of my buddles in
purge water but none in VCC samples.

Address: Mp 2610 Lindale Dr.	Sample No:	
Resident's Name: Madeline Tours	Samplers: Lant 7/ Butler.	
Date: 6/12	Sample Time: 15:16	
Start Purge: 14:5%	Est. Flow Rate: 2.5 gal in U5 que.	
End Purge: 15:16	· · · · · · · · · · · · · · · · · · ·	
Stabilization Parameters:		
3 $\frac{15:14}{4}$ $\frac{4\cdot34}{520}$ $\frac{520}{4}$ $\frac{520}{5}$ $\frac{6}{7}$ Purge is adequate if three consecutive readings fall w pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments:	57.5°F 57.5°F ————————————————————————————————————	
Water Softener or other treatment? No Water	Sofrew or Filter.	
Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Well dvilled about 1968, 144' deep, water at 104' wetal gipe		
Other Comments: Well is visible in yard NE of house Every volotile sample taken had numerous butbles; impossible to conset an air buttle fire sample loke - Buchet of		
Joy 5 min.	of after sitting undisturbed	

Address: ZUIZ Lindberg	Sample No:
Resident's Name: John Wood Ford	Samplers: Lant 2/Butler
Date: 6/17	Sample Time: 2.5 920 in 35 500
Start Purge: 13:56	Est. Flow Rate: 14:30
End Purge: 14:26	
Stabilization Parameters:	
Trial Time 1 2 14 19 7.23 460 2 14 20 7.23 455 4 14 21 7.26 455 5 6 7 Purge is adequate if three consecutive readings fall with the pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments:	emp. = ± 0.5 °C (± 2 °F).
Location of sample point: 5 proget (OUTS)	de) on SE ride of hour
Water Softener or other treatment? No Soften	
Aerator on sample point spigot?	·
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Well is go teet deep well	duitled pre- 1990, well is
bout 4"-6" netal size	
Other Comments: Purg With appe	curs cloudy
	•

Sample No:
Samplers: <u>lautz/Rys</u>
Sample Time: 18.00
Est. Flow Rate: 1 cal in 9 sec
•
Y Temp. 55.5 54.5 54.5 54.5 within these ranges:
so fever or rectinent
lled, static water level, etc.)

Address: 1617 Lyran	Sample No:	
Resident's Name: <u>Gav 7a</u>	Samplers: Lantz / Butler	
Date: 6/11/90	Sample Time:/6 10	
Start Purge: <u>153:37</u>	Est. Flow Rate: 25 Sal In 2:	
End Purge: 16:10		
Stabilization Parameters:		
Trial Time pH Conductivity 1 4:03 (.95 730 2 4:05 6.95 730 3 4:07 4.95 720 4 5 6 7 Purge is adequate if three consecutive readings fall pH = ± 0.25, conductivity = ± 50 µmhos/cm, and Comments: Location of sample point: Othsile Spigot,	within these ranges: temp. = ± 0.5 °C (± 2 °F).	
Water Softener or other treatment? No with sohere -		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date dri	lled, static water level, etc.)	
Don't know - was in when	current residents moved in	
well was protably inst	talled prior to 1950	
Don't know - was in when Well was protably in so Other Comments: Field Blanch Tax Slow flow rate.	Les here. Unusually	

Address: 1701 Lyran	Sample No:	
Resident's Name: Lowell Davidson	Samplers: Lanta/Butler.	
Date: 6/12/90 - Tuckky	Sample Time: 10:16	
Start Purge: <u>69:48</u>	Est. Flow Rate: 2.5 gol in 1 min 20	
End Purge: 10:16	·	
Stabilization Parameters:	,	
Trial Time pH Conductivity 1 $0:11$ $7:26$ 610 2 $10:12$ $7:27$ 610 3 $10:13$ $7:27$ 600 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = ± 50 μ mhos/cm, and to Comments: Location of sample point: μ	$\frac{55^{\circ}F}{54.5^{\circ}F}$ $\frac{54.5^{\circ}F}{54.5^{\circ}F}$ $\frac{1}{54.5^{\circ}F}$ within these ranges: $\frac{1}{55^{\circ}F}$ emp. = $\pm 0.5^{\circ}C$ ($\pm 2^{\circ}F$).	
Water Softener or other treatment? <u>No Works</u>	Sofuely or treatingat	
Aerator on sample point spigot? No.	lad static water level at a)	
Well Construction: (depth, PVC, stainless, date drill		
pump night be PUC.		
Other Comments: <u>Sampled</u> and of	avect.	
	<u> </u>	

Address: 3106 Mar Loll	Sample No:
Resident's Name: Avuola McLoan	Samplers: [autz/Rys 194
Date: 6/14 McClain	Sample Time: 9.28 30
Start Purge: 9:08	Est. Flow Rate: 1501/8 securios
End Purge: 9.28	
Stabilization Parameters:	
Trial Time pH Conductivity	
1 9:22 7.23 428	5557
$\frac{2}{3} \frac{9.24}{9.25} \frac{7.24}{716} \frac{425}{425}$	55°F
7 7.24	<u>55.5%</u>
	55,5°F
5	
6	
Purge is adequate if three consecutive readings fall w	rithin these mages
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	
Comments: Location of sample point: Outside tap or	n South side of house
Water Softener or other treatment? House his	softener, outside rap bypasse
Water Sofrener	
Aerator on sample point spigot?	· · · · · · · · · · · · · · · · · · ·
Well Construction: (depth, PVC, stainless, date drill	ed. static water level, etc.)
6" stell casing, Approx. 80'	
Drilled avound 190,	soft - (super of flows)
Other Comments: Niechowca of hwh	id sellowish water whom
Other Comments: Discharge of two his tap was hist turned an , clean	ed up within I minute
Well is visible near deck on	5 sick of hours
	·

Address: 3/37 Marshall	Sample No:
Resident's Name: Caul Drake	Samplers: Lant 2 / Almange
Date: 6/14	Sample Time: 17/7
Start Purge: 16 56	Est. Flow Rate: 2.5 gal un 555
End Purge: /7:/7	•
Stabilization Parameters:	
Trial Time pH Conductivity 1 17/2 7.13 5/0 4/264 2 17/3 7.15 5/0 4/264 3 17/4 7.15 5/0 4/264 4 17/5 7.15 5/0 4/264 5	$\frac{57.5^{\circ}}{57^{\circ}}$ $\frac{57^{\circ}}{57^{\circ}}$ $\frac{57^{\circ}}{57^{\circ}}$ within these ranges: $\frac{1}{57^{\circ}}$ emp. = ± 0.5 °C (±2°F).
Water Softener or other treatment? Notation house but not in line with Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drill Well was probably drilled 30 - Other Comments: Well is located in	ed, static water level, etc.)
· · · · · · · · · · · · · · · · · · ·	

Address: 430 Mortin	Sample No:		· · · · · · · · · · · · · · · · · · ·
Resident's Name: Mrs Velma Beck	Samplers: Br	the / Borks	<u>~</u>
Date: 6/13/90	Sample Time:	16:00	5
Start Purge: 15:44	Est. Flow Rate:	Igselon in	35 Auco
End Purge: 15:59		0	
Stabilization Parameters:		* 4	,
Trial Time pH Conductivity 1 1555 5.44 510 2 1556 5.64 500 3 1557 5.73 490 4 1559 5.81 490 5	vithin these ranges: emp. = ± 0.5 °C (± 0.5)	-2°F).	477 47 47 47 47 47 47 47 47 47 47 47 47
home			
Water Softener or other treatment? 74			
	,		
Aerator on sample point spigot?		· · · · · · · · · · · · · · · · · ·	
Well Construction: (depth, PVC, stainless, date dril	led, static water le	vel, etc.)	
·			
Other Comments:			
·		· · · · · · · · · · · · · · · · · · ·	
			·
·	·		

Address: 827 Mathis	Sample No:
Resident's Name: Ken Burker	Samplers: Rubin Morten / Bb Home
Date: 4/14/90	Sample Time: 1445
Start Purge: /4:27	Est. Flow Rate: 7 / quart it 6 secon
End Purge: 13:37	
Stabilization Parameters:	
1 1438 7.48 5	s fall within these ranges: and temp. = ± 0.5 °C (± 2 °F).
Water Softener or other treatment? Yes	but not hocked up
Aerator on sample point spigot?	te drilled, static water level, etc.)

Address: 608 New Miltord Ave	Sample No:
Resident's Name: Dan Sunth	Samplers: Cautz/4/icanya
Date: 6/18	Sample Time:
Start Purge: <u>1543</u>	Est. Flow Rate: 2.5 gal / 40 Sec.
End Purge:	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1554 715 877 2 1535 709 865 3 1537 7.09 863 4 1537 7.09 860 5 1558 7.09 960 6 1559 7.09 859 7 Purge is adequate if three consecutive readings fall wpH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: μ	$ \frac{62.0^{\circ}F}{61.3^{\circ}F} $ $ \frac{61.0^{\circ}F}{60.7^{\circ}F} $ $ \frac{60.5^{\circ}F}{60.5^{\circ}F} $ within these ranges: $ emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F). $
Water Softener or other treatment? Wo water	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Well is probably 25 years old,	2" Steel pill, piping is all
steel.	
Other Comments:	•
	•

Address: 1726 Parellu-	Sample No:
Resident's Name: Elma Shirk	Samplers: Lantz/Rys
Date: 6/14	Sample Time: <u>iSOO</u>
Start Purge: 17 38	Est. Flow Rate: igal in 30 sec
End Purge: 17:52	
Stabilization Parameters:	
Trial Time pH Conductivity 1 $\frac{135}{1755}$ $\frac{7.12}{7.12}$ $\frac{530}{50}$ 2 $\frac{1755}{2}$ $\frac{7.12}{5.12}$ $\frac{530}{50}$ 3 $\frac{1757}{2}$ $\frac{7.12}{7.11}$ $\frac{530}{530}$ 4 $\frac{1757}{7}$ $\frac{7.11}{530}$ 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and to Comments: Location of sample point: Outside Spice	$\frac{52\%}{56}$ $\frac{55}{55}$ $\frac{55}{55}$ $\frac{55}{55}$ $\frac{5}{55}$ $\frac{5}{5}$ $\frac{5}{$
Water Softener or other treatment? No Witte	Sofrener or file
Aerator on sample point spigot? <u>No</u>	
Well Construction: (depth, PVC, stainless, date drill Well was drilled after weeder	•
10.70	
Other Comments: Well pit is visibility House west door (1730) is con	roytheast gide of house
	·

Address: 801 Ranger	Sample No:
Resident's Name: Orval Bailey	Samplers: Lange Butler.
Date: 6/11/90	Sample Time: 408
Start Purge: 186:38	Est. Flow Rate: 25 gallars in 40
End Purge: 7:08	\mathcal{O}_{i}
Stabilization Parameters:	
Trial Time pH Conductivity 1 $\frac{6.58}{5.00}$ $\frac{7.81}{7.81}$ $\frac{6.00}{10.00}$ 2 $\frac{7.03}{7.01}$ $\frac{7.01}{7.01}$ $\frac{6.00}{5.00}$ 4	59°F 54.5°F 57.5°F
Comments:	
Location of sample point: <u>Kitchen Sinh</u>	- bypasses sottenes.
Water Softener or other treatment? Itas water found by passes so frener.	, so brevier but sample
Aerator on sample point spigot? Taken off	for purse of sample
Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.)
well is 65 to 85' Leep - dr	illed approx 10 yours upo
PVC pipe goes into the well	<u> </u>
Other Comments:	
•	

Address: 3007 River Brulevard	Sample No:	
Resident's Name: Mvs. Simmons	Samplers: Robin North / Scott Hodge	
Date: 6/12/90	Sample Time: 10-20	
Start Purge: 9 53	Est. Flow Rate: 1 gallon in 300	
End Purge: /0.03	7	
Stabilization Parameters:		
Trial Time pH Conductivity	Temp.	
1 10:09 7.14 500	<u> 59° F</u>	
2 18.41 - 1.41	100° i	
3 10314 7.47 600	60°E	
4 10:16 7. 39 600	609=	
6		
7	• •	
Purge is adequate if three consecutive readings fall w	within these ranges:	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	_	
Comments:		
	t one. The At Ne of	
Location of sample point:	e ere wat aux	
of Aone		
Water Softener or other treatment?		
Aerator on sample point spigot?		
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)	
Williast last 30 years old	. Well minds if steel af	
Pro line.		
Other Comments: Spigot Societal	very close to Cho	
mound mora a bedit -	Wents the owner calls	
Other Comments: Spigot located very class to Che ground among a bedy plants who owner calls "I how on the Mountains" Owner sometimes sprays them 1/weed hills		
sprop Stem 2/wed hille		
<i>y</i> /		

Address: 3110 Rover Blood	Sample No:
Resident's Name: Mr Wheeler	Samplers: North Butly
Date: 6/15/90.	Sample Time: 14139
Start Purge: 18:14	Est. Flow Rate: 1- 18 Secon
End Purge: 18 27	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1894 237 570 2 1835 2.19 500 3 18.17 2.19 500 4 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and to Comments: Location of sample point: $2.16 \mu \text{mhos/cm}$	$\frac{59}{59}$ $\frac{1}{59}$
home	0
Water Softener or other treatment?	
Aerator on sample point spigot? Nu	
Well Construction: (depth, PVC, stainless, date drill	ed, static water level, etc.)
Other Comments:	

Address: 3117 River Sa	ample No:
Resident's Name: Fred Swavborg Sa	amplers: Almanza / Hodge
4 1 1 2	ample Time: 1233
Start Purge: 1203 Es	st. Flow Rate: 2.59-1 / 42 5-
End Purge: 1232	
Stabilization Parameters:	
Trial Time pH Conductivity	Temp.
1 1226 7.06 900 4 mbo	71.40
	66.80
	65.5°
	63. 7°
	63-10
6 1232 7.09 812 4mbo	63.50
7	•
Purge is adequate if three consecutive readings fall withi	in these ranges:
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp	•
	2 00 0 (22 1).
Comments:	
Location of sample point: 5 Pigot & N	J. Side of House.
	·
W	
Water Softener or other treatment? None	<u> </u>
Aerator on sample point spigot?	
Well Construction: (death DVC stainless data drilled	ctorio vinter level etc.)
Well Construction: (depth, PVC, stainless, date drilled,	
25 Ft Deep, N 1935-4	0
Other Comments: Duplicate 59 mple	collected here
,	•

Address: 508 Roch River	Sample No:
Resident's Name: Alma Mr. Lead	Samplers: Laut Z/Burler
Date: 6/12	Sample Time: 17:10
Start Purge: 16:50	Est. Flow Rate: 7-5 gol in 60 se
End Purge: 17:10	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1705 6.65 810 2 1707 6.64 810 4 810 4 810 Purge is adequate if three consecutive readings fall with the pH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm, and to Comments:}} Location of sample point: \text{\text{K17Class 6.746}}	$\frac{58.5^{\circ} F}{58^{\circ} F}$ $\frac{58^{\circ} F}{58^{\circ} F}$ within these ranges: $emp. = \pm 0.5^{\circ} C (\pm 2^{\circ} F).$
Water Softener or other treatment? No water	softenes or other rectinant
Aerator on sample point spigot?	<u>; </u>
Well Construction: (depth, PVC, stainless, date drill	led. static water level. etc.)
well was probably duilled pre-195	•
Other Comments: Well is located in	·

Address: 841 Founds	Sample No:
Resident's Name: Mr Mr Jem Milanne	Samplers: Montan / Butler
Date: 6/18/90	Sample Time: 12729
Start Purge: /) / (Est. Flow Rate: Lyllan 57 rum
End Purge: 12/28	J
Stabilization Parameters:	
Trial Time pH Conductivity 1 2210 7.12 (50) 2 227 (50) 3 (228) (50) 4 (50) 4 (50) Purge is adequate if three consecutive readings fall w pH = ± 0.25 , conductivity = ± 50 µmhos/cm, and to	vithin these ranges:
Comments: Location of sample point: Ortsele ship Journe Water Softener or other treatment? Mo.	gd nath side
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	
is = 18 ys old + = 75 ft he	ep trudent me so
Other Comments: Alterative for &	43 Pman 11
	43 Forend
6 plestic (prc?)	y Drawen

Address: 728 Sandy Hallow	Sample No:
Resident's Name: Pour Win	Samplers: Anton Butler
Date: 6/15/90	Sample Time: /705
Start Purge: /6.5/	Est. Flow Rate: 1 gellen Brecen
End Purge: 17.04	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1701 7.57 ± 0 2 1702 7.68 ± 400 3 1704 ± 77 ± 0 4 5 6 7 Purge is adequate if three consecutive readings fall wpH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments: Location of sample point: Orbital Approximately	within these ranges: $emp. = \pm 0.5 ^{\circ}C (\pm 2^{\circ}F).$
Water Softener or other treatment?	
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drill doend for my inform	ed, static water level, etc. Pend. 1
Other Comments:	

Address: 810 Acrely Hollow	Sample No:
Resident's Name: Lingo Valare a	Samplers: Morkey Butle
Date:	Sample Time: //:40
Start Purge: (1) 27	Est. Flow Rate: I gallon is 60 tec
End Purge: 11:37	,
Stabilization Parameters:	
Trial Time pH Conductivity 1 11:37 408 410 2 11:38 7.71 400 3 11:39 7.70 400 4	65 63.5 64 within these ranges:
Location of sample point: Onthow spr ye	A mother was
Water Softener or other treatment? Aut his	skr.
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill didn't speak anglish	
Other Comments:	•
	,

Address: 1202 Sandy Hollan	Sample No:
Resident's Name: Patricia Wolstield	Samplers: Lautz / Blugget
Date: 6/17	Sample Time: /725
Start Purge: 170Z	Est. Flow Rate: 2.5 gal in 35 see
End Purge: 1727	
Stabilization Parameters:	
Trial Time pH Conductivity 1 1417 7.91 700 mhs 2 1418 7.90 680 3 1419 7.89 680 4 1720 7.89 670 5 1421 7.89 670 6 7 Purge is adequate if three consecutive readings fall w pH = ± 0.25, conductivity = ± 50 µmhos/cm, and to Comments: Location of sample point: Outside Sping House	$ \frac{59^{\circ}F}{58} $ $ \frac{57}{57} $ $ \frac{57}{57} $ within these ranges: $ emp. = \pm 0.5 ^{\circ}C (\pm 2^{\circ}F). $
Water Softener or other treatment? <u>Vor Water</u>	r 50 Henry
Aerator on sample point spigot? N_{c}^{2}	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Exident doesn't know detail	of well construction
Other Comments:	
	·

Address: 1306 Sandy Hollow	Sample No:
Resident's Name: Jami Desonia	Samplers: Morten Burt lac
Date: $6/13/90$	Sample Time: 3.46
Start Purge: 13:34	Est. Flow Rate: I quest in 9 second
End Purge: 13:46	U
Stabilization Parameters:	
Trial Time pH Conductivity 1 13: $\frac{1}{4}$ 6-02 $\frac{1}{3}$ 0 2 13: $\frac{1}{4}$ 5 $\frac{1}{5}$ 95 $\frac{1}{7}$ 00 3 13: $\frac{1}{4}$ 6 $\frac{1}{5}$ 700 4 5 6 7 Purge is adequate if three consecutive readings fall w pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: $\frac{1}{4}$ 6 $\frac{1}{5}$ 6 $\frac{1}{5}$ 6	<u> </u>
	\
Water Softener or other treatment?	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drille	ed, static water level, etc.)
Other Comments: as wither wis burg	puisso, a susty Woring was

Address: 1812 Soundy Hollow	Sample No:		
Resident's Name: <u>Helen Shloka</u>			
Date:6//2	Sample Time: 17:54		
Start Purge: 17:35	Est. Flow Rate: 2.5 gol in 55 goc		
End Purge:			
Stabilization Parameters:			
Trial Time pH Conductivity 1 / 149 7.10 (21) 2 / 75 f 7.13 (205) 3 / 752 7.13 (210) 4	57° F 56° F 56° F ————————————————————————————————————		
Comments: Location of sample point: <u>putsible</u> Spigot on SW side of house			
Water Softener or other treatment? No Water Softener or other treatment			
Aerator on sample point spigot?			
Well Construction: (depth, PVC, stainless, date dril	led, static water level, etc.)		
House is ~ 50 years old No	other details known		
Other Comments: Alternate for 1920	sandy Hollow, which is vacant		

Address: 3905 Saner Sample No:
Resident's Name: Kerr Teresa Bolen Samplers: Bub Hank / Ribin Ninza
Date: 5/14/98 Sample Time: 15:09
Start Purge: 14.52 Est. Flow Rate: 1916 in 25 Acc
End Purge: 15:01
Stabilization Parameters:
Trial Time pH Conductivity Temp. 1 15.02 1.50 600 64 2 15.03 7.32 600 64 3 15.05 7.35 605 64 4
Water Softener or other treatment?
Aerator on sample point spigot?
Other Comments:

Address: <u>4301</u>	4 Sanes		Sample No:	*	
Resident's Name:	Fene Wee	den	Samplers: Lan	+ 2 /A/man	ya_
Date: 6/18	•		Sample Time:		<i>y</i>
Start Purge: 10	28 UL 183	7	Est. Flow Rate:	2.5 gal is	29 es p
End Purge:/	859			•	49 52
Stabilization Parame	ters:				
Trial Time	рH	Conductivity		•	
1 1855	7.12.	629	59.0°F		·
2 1856	7.11	624	58.8° =		
3 <u>1857</u>	7.11	623	58.6° F	-	
4 1858	7.12	622	58.3°F	•	
5 1859	7.12	623	5.8.3°F		V.
6				•	
7					
Purge is adequate if	three consecutive	e readings fall w	vithin these ranges:		
$pH = \pm 0.25$, conduction		•			
pt 0.20, 00.1000	, <u> </u>			/·	
Comments:					
Location of sample	point: <u>Outse</u>	de spice	t east sc	de et hou	10_
		10		0	
Water Softener or ot	her treatment?	No Wate	Sotrener		
,					
Aerator on sample p	oint spigot?	Vo			
Well Construction: (depth, PVC, sta	inless, date drill	ed, static water lev	vel, etc.)	
Resident de	resist know	delails	of well con	struction	
Well in	h" etal	Casia, A	U rises on	bound and	ahal
Other Comments:	2/	y , A	- i	rance are	/ 1
Other Comments: _	Bluish Cry	sty mates	Vist on s	P1901 & B4	ughed
of to to	le extent	passible.	well is	ocated in b	asoment
	Blank tak				·
		•		•	·
					<u>. </u>
		1			

Address: 3110 Saner	Sample No:
Resident's Name: Knoty whitman	_ Samplers: <u>Notton / Outler</u>
Date: 4/14/90	Sample Time:
Start Purge: 5:57 PN 16:57	Est. Flow Rate: 1 quart in 10.
End Purge:	
Stabilization Parameters:	
Trial Time pH Conductivity 1 /707 4.88 740 2 /708 4.84 720 3 /709 4.64 720 4 5 6 7 Purge is adequate if three consecutive readings fall pH = ± 0.25, conductivity = ± 50 µmhos/cm, and Comments: Location of sample point: Outlier 1.50	$\frac{59 \circ F}{200 \circ F}$ $\frac{59 \circ F}{590 \circ F}$ I within these ranges: $\frac{1}{1} \times \frac{1}{1} \times$
- Green	0
Water Softener or other treatment?	
Aerator on sample point spigot?	
	illad assis was lavel at a
Well Construction: (depth, PVC, stainless, date dr	inied, static water level, etc.)
	•
Other Comments:	•

Address: 319 Lawyer	Sample No:
Resident's Name: Clarence Miller	Samplers: Bob Hink Poken Forts
Date: 6/11/90.	Sample Time: (7.50
Start Purge: 17.38	Est. Flow Rate: 19t in 17 second
End Purge: 17:50	
Stabilization Parameters:	
Trial Time pH Conductivity 1 17.48 7.46 (25) 2 17.49 7.30 (23) 3 17.50 7.30 (23) 4 5 6 7 Purge is adequate if three consecutive readings fall with the pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and the Comments:	within these ranges: temp. = ± 0.5 °C (± 2 °F).
Location of sample point: Outside sprant Water Softener or other treatment? 4	on south me yours
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date dril 65-70 feet deep	led, static water level, etc.) Will is
Other Comments:	

Date: $\frac{1 \cdot 19 \cdot 90}{1 \cdot 25}$ Sample Time: $\frac{1 \cdot 40}{1 \cdot 40}$ Start Purge: $\frac{1 \cdot 25}{1 \cdot 40}$ Est. Flow Rate: $\frac{25}{20}$ gal miles. End Purge: $\frac{1 \cdot 40}{1 \cdot 40}$	Address: 2646 Sewell Resident's Name: Luther Gast Sow	Sample No:
Start Purge: 1:25 Est. Flow Rate: 25 xal		* ,
End Purge: 1:40 Stabilization Parameters: Trial Time pH Conductivity Temp. 1 1:35 7.12 797 43.6°F 2 1:36 7.10 778 61.3°F 3 1:37 7.11 764 40.7°F 4 1:38 7.11 769 (10.5°F 5 1:39 7.11 767 (10.4°F) 6 7 Purge is adequate if three consecutive readings fall within these ranges:	Date: (x (19 / 90.	
Stabilization Parameters: Trial Time pH Conductivity Temp. 1 /:35 7.12 797 43.6°F 2 1:36 7.10 778 61.3°F 3 /:37 7.1/ 764 60.7°F 4 /:38 7.1/ 769 60.5°F 5 /:39 7.1/ 767 40.4°F 6 7 Purge is adequate if three consecutive readings fall within these ranges:	Start Purge: 1:25	Est. Flow Rate: 25 zal wellm
Trial Time pH Conductivity Temp. 1 $\frac{1:35}{36}$ $\frac{7.12}{7.10}$ $\frac{797}{178}$ $\frac{1.30}{1.30}$ F 2 $\frac{1:36}{37}$ $\frac{7.11}{7.11}$ $\frac{764}{169}$ $\frac{1.30}{10.50}$ F 4 $\frac{1:38}{39}$ $\frac{7.11}{11}$ $\frac{769}{10.7}$ $\frac{1.11}{10.7}$ $\frac{1.11}{10.7}$ Purge is adequate if three consecutive readings fall within these ranges:	End Purge: 1:40	
1 1:35 7.12 797 43.6°F 2 1:36 7.10 778 61.3°F 3 1:37 7.11 769 40.7°F 4 1:38 7.11 769 40.5°F 5 1:39 7.11 767 40.4°F 6 7 Purge is adequate if three consecutive readings fall within these ranges:	Stabilization Parameters:	
Comments:	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	43.6° F 61.3° F 60.7° F (10.5° F
	Purge is adequate if three consecutive readings $pH = \pm 0.25$, conductivity = $\pm 50 \mu mhos/cm$,	and temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
Location of sample point: 150 - Nous fatter	Purge is adequate if three consecutive readings $pH = \pm 0.25$, conductivity = $\pm 50 \mu mhos/cm$,	and temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 μmhos/cm, Comments: Location of sample point: — house	and temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
	Purge is adequate if three consecutive readings $pH = \pm 0.25$, conductivity = $\pm 50 \mu mhos/cm$,	and temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 μmhos/cm, Comments: Location of sample point: — house	and temp. = $\pm 0.5 ^{\circ}\text{C} (\pm 2^{\circ}\text{F})$.
Water Softener or other treatment? Wo Aerator on sample point spigot? W	Purge is adequate if three consecutive readings $pH = \pm 0.25$, conductivity $= \pm 50 \mu mhos/cm$, Comments: Location of sample point: Water Softener or other treatment? Aerator on sample point spigot?	and temp. = ± 0.5 °C (±2°F).
Water Softener or other treatment? Wo Aerator on sample point spigot? Wo Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Acres 40	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm,}} Comments: Location of sample point: \text{\$\tex{	and temp. = ± 0.5 °C (±2°F).
Water Softener or other treatment? Wo Aerator on sample point spigot? W	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 \text{ \text{µmhos/cm,}} Comments: Location of sample point: \text{\$\tex{	and temp. = ± 0.5 °C (±2°F).
Water Softener or other treatment? <u>No</u> Aerator on sample point spigot? <u>No</u> Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) <u>chart Go</u> when kepp at least 40 years;	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 µmhos/cm, Comments: Location of sample point:	and temp. = ± 0.5 °C (±2°F). faunct e drilled, static water level, etc.) about 40
Water Softener or other treatment? <u>No</u> Aerator on sample point spigot? <u>No</u> Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) <u>chart Go</u> when kepp at least 40 years;	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 µmhos/cm, Comments: Location of sample point:	and temp. = ± 0.5 °C (±2°F). faunct e drilled, static water level, etc.) about 40
Water Softener or other treatment? Wo Aerator on sample point spigot? Wo Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Acres 40	Purge is adequate if three consecutive readings pH = ± 0.25, conductivity = ± 50 µmhos/cm, Comments: Location of sample point:	and temp. = ± 0.5 °C (±2°F). faunct e drilled, static water level, etc.) about 40

Address: 3135 1/2 Sewell	Sample No:		
Resident's Name: Bill Files	Samplers: Lanral Almanya		
Date: _6/15	Sample Time: /225		
Start Purge: /2:0/	Est. Flow Rate: 2.5 gal in 20 soc		
End Purge: /221			
Stabilization Parameters:			
Trial Time pH Conductivity 1 2/6 7.27 400 y μ/ω 2 2/17 7.3/ 400 y μ/ω 3 2/9 7.32 370 y μ/ω 4 /220 7.31 390 y μ/ω 5	56° 56° 56° 56° Stoo		
Comments: Location of sample point: Location of sample	<u> </u>		
Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Well is located between 3133 and 3135 Swell, but is used by all 3 houses Power water smalls 1/62 51/fer.			
	;		

Address: 19 forth	Sample No:
Resident's Name: Carol Fatin	Samplers: Robin Wonten Scott &
Date: 6/12/90	Sample Time: 136 am
Start Purge: 11 9	Est. Flow Rate: 1 gallon / 57 second
End Purge: 11 29	, ,
Stabilization Parameters:	
Trial Time pH Conductivity 1 (1:30 7.93 700 2 11:31 1.98 (660 3 1/33 7.99 (640 4 11:34 8.4 (640 5 6 7 Purge is adequate if three consecutive readings fall w pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: Artchin spigat	$ \begin{array}{c} $
Water Softener or other treatment?	
Aerator on sample point spigot? Well Construction: (depth, PVC, stainless, date drille	ed, static water level, etc.)
Other Comments:	

Address: 804 Taft	Sample No:
Resident's Name: Jim Strawfordge	Samplers: Horton / Baller
Date: 6/18/db.	Sample Time: /2 53
Start Purge: /2:38	Est. Flow Rate: 1 gullon 53
End Purge: 12 51	
Stabilization Parameters:	
Trial Time pH Conductivity 1 12.49 7.11 190 2 12.50 7.39 100 4 12.51 7.30 100 5 6 7 Purge is adequate if three consecutive readings fall w pH = ± 0.25 , conductivity = $\pm 50 \mu \text{mhos/cm}$, and to Comments: Location of sample point: Cuts of April	$ \frac{60.5}{59.5} $ $ \frac{59.5}{60} $ within these ranges: $ emp. = \pm 0.5 ^{\circ}C (\pm 2^{\circ}F). $
Water Softener or other treatment? If hat had ap to outdoor spage	water softner not
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Other Comments:	

Southeast Rockford Sample Collection Sheet Industrial Well - Estuina Mountacturing Address: 2647 849 Sample No: Resident's Name: Paul Devers Samplers: Lantz/Almany Date: <u>6/18</u> Sample Time: 1425 1358 Start Purge: Est. Flow Rate: 2 5 gal m 15 soc 1423 End Purge: Stabilization Parameters: Trial Time DΗ Conductivity Temp. 929 63.8°F 14/4 7.00 1 62.7° F 925 1415 701 417 61.80F 7.02 1416 3 Temp weadwants 61.801= 1417 914 7.02 61.60 F 913 1418 702 5 61.50F 1419 7.02 914 913 61.101= 1420 7.02 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Location of sample point: Toup near middle of west side of plant Right vest to well Water Softener or other treatment? No water preatment Aerator on sample point spigot? No Water Soffener - Water is not for potable use Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Well is 82' deep - dvilled in 1940's sumps approx. 1500 gal see day, 8" Steel casing - Water is get 40" Other Comments: Water is process water - Cooping of annului Estuine molos hammers

Nochford Cylinder Gas	
Address: 16/3 //*	Sample No:
Resident's Name: Deumis Henryckson	Samplers: Lantz / A/manya
Date: 6/19	Sample Time: 12/5
Start Purge: 1/37	Est. Flow Rate: 1 lite in 30 sec
End Purge: 12/2	1 lite in 25 sec
Stabilization Parameters:	<i>:</i>
Trial Time pH Conductivity 1 1201 7-707-07 975 2 1204 7-08 967 3 1205 7-08 962 4 1206 7-09 962 5 1706 7-09 980 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: Faucet in Western	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
Location of sample point: Patter at the	Mem Cannessor
Water Softener or other treatment? No Worto	where or other treatment
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date dril	
Employee doesn't know details	of well construction
	(
Other Comments: <u>Pure</u> through 2 6	athum baccels

Tussing Tile & Flooring	
Address: 2955 // =	Sample No:
Resident's Name: Clwis Schaaf	Samplers: Lant 7 / Butler
Date: 6/11/90	Sample Time: <u>/7:34</u>
Start Purge: 75:00	Est. Flow Rate: 3202 4 10 526.
End Purge: 5/7:34	
Stabilization Parameters:	
Trial Time pH Conductivity 1 /7 22 7 0/ 730 2 /7 29 6 95 750 3 /7 33 7 00 730 4 5 6 7 Purge is adequate if three consecutive readings fall when the pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to	58° F 59° F
Comments:	
Location of sample point: Sample taken	from sample spigot right outside
~ 35 get pressure rank.	
Water Softener or other treatment? No hiles	
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	led, stanc water level, etc.)
Other Comments: Well is in basemen	, , , , , , , , , , , , , , , , , , , ,
up stours bathroom sinh full t	
commercial establishment to	hat sells floor tiling. Well
Huns on periodically Matrix	Spile Duplicate taken liene
Simples willive from bross of	

Smith Auro Repair		
Address: 3015 // =	Sample No:	
Resident's Name: Budette Sun, be	Samplers: Lan+z/Buther	
Date: 6/12/90	Sample Time: 2-5 gol in /min 20 sa	
Start Purge: 10.51	Est. Flow Rate: 11 27	
End Purge: 11: 27	•	
Stabilization Parameters:		
Trial Time pH Conductivity 1 11 18 7.20 (2/0) 2 11 19 7.20 (10) 3 11:20 7.28 (21) -4	$\frac{58.5 \circ F}{58.6 F}$ $\frac{58.5 \circ F}{58.6 F}$ within these ranges: $temp. = \pm 0.5 \circ C (\pm 2^{\circ}F).$	
Water Softener or other treatment? No Water Softener or other treatment or other treatment or other treatment or other treatment or other treatment? No Water Softener or other treatment or other treatmen	lled, static water level, etc.)	
Other Comments: House next doon -	3017 5.11 the is on some well	

Good year) The Co.	
Address: 3/19 1/4 54.	Sample No:
Resident's Name: Bill Czerny - Man	Samplers: Lant 7 Butter
Date: 6/12/90	Sample Time: 1233
Start Purge: 12:09	Est. Flow Rate: 2.5 gailors in 19 Sec
End Purge: 12:33	J
Stabilization Parameters:	·
Trial Time pH Conductivity 1 12: 26 7.32 420 2 12: 29 7.33 420 3 13: 31 7.33 720 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and to Comments: Location of sample point: Dutstale Rwass	$ \frac{57^{\circ}F}{565^{\circ}F} $ $ \frac{565^{\circ}F}{565^{\circ}F} $ within these ranges: $ emp. = \pm 0.5^{\circ}C (\pm 2^{\circ}F). $
0	
Water Softener or other treatment? No me	clinear No Water Stronger
Aerator on sample point spigot? No	
Well Construction: (depth, PVC, stainless, date drill	,
Well is approx 4 years old	
details of well construction	
Other Comments: Strup Smalls 1/16	e tires, sample point
is next to 3 auti freeze divi	us - Not lealing, no odors
* (1/2) Somer, black prodice	eles were wotal in water_
No municipal water	· · · · · · · · · · · · · · · · · · ·

Mic Donalds	
Address: 3237 11 The	Sample No:
Resident's Name: Dave Steuberg	Samplers: Lantt / Almany
Date: 6/14	Sample Time: 1545
Start Purge:	Est. Flow Rate: 2.5 gal in 19 se
End Purge: 1531 EVD 1545	
Stabilization Parameters:	
Trial Time pH Conductivity 1 $\frac{1541}{1543}$ $\frac{7.22}{1543}$ $\frac{560}{1528}$ 2 $\frac{1543}{1544}$ $\frac{7.28}{1548}$ $\frac{560}{1540}$ 4 $\frac{1545}{1545}$ $\frac{7.28}{1540}$ $\frac{560}{1540}$ 5 $\frac{5}{1540}$ Purge is adequate if three consecutive readings fall with pH = ± 0.25 , conductivity = $\pm 50 \mu$ mhos/cm, and to Comments: Location of sample point: $\frac{1540}{1540}$ 154	$\frac{57.6}{55.5}$ $\frac{55.5}{55.0}$ $\frac{55.0}{55.0}$ within these ranges: $emp. = \pm 0.5 \text{ °C } (\pm 2^{\circ}\text{F}).$
Water Softener or other treatment? <u>Po</u> <u>Water</u>	softener or weathered
Aerator on sample point spigot? Lb Well Construction: (depth, PVC, stainless, date dril Ruslaurant Manager doesn't	
Other Comments:	
· · · · · · · · · · · · · · · · · · ·	

Pizza Hat	
Address: 3329 // 1/4	Sample No:
Resident's Name: Jan Hevely.	Samplers: Lantz/Almanya
Date: <u>6/14</u>	Sample Time:
Start Purge:	Est. Flow Rate: 2.5 gol in 21 sec.
End Purge: 1609	,
Stabilization Parameters:	
Trial Time pH Conductivity 1 1604 7.09 600 2 1605 7.09 600 3 1606 7.09 600 4 5 6 7 Purge is adequate if three consecutive readings fall when the pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and the Comments: Location of sample point: $\frac{5\rho \cos t}{2} = \frac{1}{2} = $	$\frac{57^{\circ} I^{=}}{56^{\circ} F}$ $\frac{56^{\circ} F}{56^{\circ} F}$ within these ranges: $emp. = \pm 0.5^{\circ} C (\pm 2^{\circ} F).$
Water Softener or other treatment? <u>Yes</u> but	comple point by passes sofrera.
Aerator on sample point spigot?	
Well Construction: (depth, PVC, stainless, date drill	led, static water level, etc.)
Manager doesn't know well a	sustruction details
Other Comments: Tested sofued w	ola - conductivity = 700 unliss
out of how conductivity	= 6/0 mmbos sample
collected directly from Fac	oth - Conductivity = 700 mm/105 = 610 mmbos sample
I .	· · · · · · · · · · · · · · · · · · ·

Frat Rockford Collision Center Address: 2602 5 17th St Sample No: Resident's Name: Russell Vavour Samplers: Lautz/Rus Sample Time: 10.02 Est. Flow Rate: 2.5 gol in 35 sec. Z fawcets lunning of the 9:26 Start Purge: 10:02 End Purge: Stabilization Parameters: Trial Conductivity Temp. Time <u>Hq</u> 7.10 0942 2 (4) 0945 3 (4) 0448 4(2) 0951 7.29 5 (4) 0955 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Location of sample point: 5 ruhs in bathroom on Northern see Shop Water Softener or other treatment? No woter softener or other weather Aerator on sample point spigot? 3. No Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Will is probably 90 text deep, dvilled me-1965 Other Comments: Workers down to both led water Show Solvent swell in shop arece Field Blank taken have

· · · · · · · · · · · · · · · · · · ·	Samplers: Budler/Hodge
Date: <u>6/19/90</u>	Sample Time: 10:28
Start Purge: 10-24	Est. Flow Rate:
End Purge:	. ·
Stabilization Parameters:	
Trial Time pH Conduct 1 $10:29$ 7.02 649 2 $10:30$ 7.17 625 3 $10:31$ 1.20 622 4 $10:31$ 1.20 1.20 5 $10:32$ 1.20 1.20 6 7 Purge is adequate if three consecutive readings to $H = \pm 0.25$, conductivity $= \pm 50 \mu \text{mhos/cm}$, a Comments:	(10.7° F 58.7° F 58.2° F 57.8° F 58.0° F Tall within these ranges:
Water Softener or other treatment? M	paygrew d -
Aerator on sample point spigot?	· · · · · · · · · · · · · · · · · · ·
Well Construction: (depth, PVC, stainless, date NULL Shallow well (214 AL FINE)	drilled, static water level, etc.) in dustrial shed in limestone; starntess steel; coased phosphote injection 93
	Lepre 3:30 for Jurahu ino-
Other Comments: Call Milk Falzone In past, head in justual priose	1/ 1/2

Kincaldes Service

Address: 1101 Barrolle San	mple No:
Resident's Name: Kobert McCurcheon San	mplers: Lantz/Almanza
Date: 6/18 Sai	mple Time:
Start Purge: 1624 Est	t. Flow Rate: 25 gal in 45 se
End Purge: <u>1648</u>	
Stabilization Parameters:	
Trial Time pH Conductivity	Temp.
1 1643 700 539	60.4PF
2 1644 7.0% 530	59.2°/=
3 1645 7.09 527	56.8° F
4 1646 7.10 526	58.7°F
5 1647 7.10 526	58-70/=
6	
7	
Purge is adequate if three consecutive readings fall within	n these ranges:
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp	_
Comments:	
Location of sample point: <u>Juside top ou</u>	east side of gavage
	, , , , , , , , , , , , , , , , , , ,
	. (
Water Softener or other treatment? No water S	offerer -
Aerator on sample point spigot? No	· · · · · · · · · · · · · · · · · · ·
Well Construction: (depth, PVC, stainless, date drilled,	ctatic water level atc \
Manager doesn't know dotails of	well construction
·	
Other Comments: Well in located in	amot lot souther
Other Comments: Well is located in	334900
Tation	
-	

Corcoran's Haly shop	
Address: 3109 Collins	Sample No:
Resident's Name: <u>Dave Corcoran</u>	Samplers: Lant 2/ Bhasat
Date: 6/15	Sample Time: _//3 5
Start Purge: ///3	Est. Flow Rate: 2.5 gg/ in 13 gk loutable horse)
End Purge: 1134	loutable horse)
Stabilization Parameters:	
Trial Time pH Conductivity 1 1130 7.43 495 μμ 2 1131 7.44 495 3 1132 7.44 491 4	vithin these ranges:
	, , , , , , , , , , , , , , , , , , ,
Comments:	
Location of sample point: Bathrooma Scientific Scientif	4 in their arec
Water Softener or other treatment? No Water 6athroom sink in the shape Aerator on sample point spigot? No Well Construction: (depth, PVC, stainless, date drill Well is 90 keer, 5" star casing Well was drilled approx 1985, Other Comments: Sampled wiscle Ran both bothroom sink and Adequate pures sink pures.	led, static water level, etc.) - Well is risch pipe is 2" PUC Depth to water = 50-60 feet. because of heavy rain outside foucet to get
(

Southeast Rockford Sample Collection Sheet Industrial Wolf Commonwealth Edizon Address: 123 Eveny Drive Sample No: Samplers: Lant z / A/manya Resident's Name: Craig Reed Date: 6-14-90 Est. Flow Rate: 2 x 2.5 gal in 40 sec Start Purge: 14:20 14: 42 End Purge: Stabilization Parameters: Trial Conductivity Time рH Temp. 1437 7.35 590 grah 1 1438 7.33 570 4mol 2 7.31 1439 5904moh 1440 7.30 590 9AOL 5 Purge is adequate if three consecutive readings fall within these ranges: pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, and temp. = \pm 0.5 °C (\pm 2°F). Comments: Location of sample point: Bathwoom Sinh in feather's Mauramance Blog Water Softener or other treatment? No treatment Aerator on sample point spigot? No - removed Well Construction: (depth, PVC, stainless, date drilled, static water level, etc.) Other Comments: Nell is located no behind building SE of bend in road running near the two hung diesel trules

Rochford FL 60109

send regules to Crain Reed

Industrial Well

Address: 707 HARRISON	Sample No:
Resident's Name: ROCKFORD PREDI	ACTS Samplers: LANTE/BHAGAT
Resident's Name: ROCKFORD PROVINCE. Date: 6-19-90	Sample Time: 12 1420 - 1440
Start Purge: Purgol 11 gallous;	Sample Time: 12 1420 - 1440. Est. Flow Rate: Well pumps 24 hrs /day are or a continuous of 60 soc of 60 soc of the char 57°F to the continuous of the cont
End Purge:	· wat per pet continuously
Stabilization Parameters:	Well pumps 24 hos loday amon a
<u>Output a granters.</u>	60 sec on 60 sec of
Trial Time pH Condu	rivity Temp.
1 1408 7.50 7102	
2 1411 1.15 400	<u>3+.5.</u> 8
3 1414 7.73 700	
4 1417 7.35 710	<u>57</u> 11
5	
6	
Purge is adequate if three consecutive readings	
pH = \pm 0.25, conductivity = \pm 50 μ mhos/cm, Comments: Location of sample point: No 1 well	
Water Softener or other treatment?	
Aerator on sample point spigot? No.	
Well Construction: (depth, PVC, stainless, date	
Will sweened at 150 - 182	Let, fungs 750 gpm conthionsly
3" diameter stell caring	
Other Comments: Field Bloud +]	Juplicate when here.
Lots of Oil of grase in v	
	(

Hoch Fern Rollanston his med	
Address: 3333 France Sa	
Resident's Name: Mc Guhard Eick Sa	amplers: Morton/Butla
Date: $\frac{L/s/40}{}$	ample Time: 14.26
Start Purge: 14.14 Es	st. Flow Rate: pump rate 1000 5
End Purge: 14.26	st. Flow Rate: pump vote 1000 5. per second. somple vote = 65
Stabilization Parameters:	~ 65 ADCORDS
Trial Time pH Conductivity 1 $\frac{14.14}{14.25}$ $\frac{7.31}{7.14}$ $\frac{4.00}{570}$ 2 $\frac{14.25}{14.25}$ $\frac{7.14}{1.21}$ $\frac{570}{570}$ 3 $\frac{14.36}{14.36}$ $\frac{7.21}{1.21}$ $\frac{570}{570}$ 4 5 6 7 Purge is adequate if three consecutive readings fall with pH = ± 0.25, conductivity = ± 50 µmhos/cm, and temp	•
Comments: Location of sample point: Andreal well #) - Ne mon home to
Excauon of sample point.	a proof tool
Water Softener or other treatment? $\frac{\gamma}{2}$	
Aerator on sample point spigot? 70	
Well Construction: (depth, PVC, stainless, date drilled,	, static water level, etc. 5215 fl des
below flooding is to could state	
sufu; down dam is 12 fed	
Other Comments: They have 2 describere	y wells of prospect
with wells. We sample well	#2
.:	

APPENDIX B

FIELD NOTEBOOKS

SOUTHEAST ROCKFORD

FIELD NOTEBOOK #1

JUNE 1990

SE Rock ford Project Sample Team /

Property of Rik Courtz

· Camp Dresser of Mclee

Address 200 W. Adams Ste 1600

Chicago IL 60606

Telephone (3/2) 786 - /3/3

Project # 1681

This Book is manufactured of a High Grade 50% Rag Ledger Paper having a Water Resistant Surface, and is sewed with Nylon Waterproof Thread.

INDEX

Trailer # 399	-8303		
		<u></u>	
			
			·
		1	
· · · · · · · · · · · · · · · · · · ·			

6/11/90 Houlan 9 or Arme at Tracker, set up 100 Calibrate pH & conder my meters Constructions meter used by Sample Team I calibrated at 8750 unles in 10,000 unto belation. 1:55 1735 Hamilton Durge lasins 13:56 Sumple Colation · SE corner of house · outside spirat 1:25 1735 Hamilton Sample Collected 2:35 avriue at 1731 Johnson - 235 - Begin purce - Sangle location - SW corner of house · Auplitate vous le vollected. . 2:52 end perse 3:05 Sample to Hected at 1737 Johnson 3:45 frepring to rate sample and Field Clark at 1617 Lyoun.

Kunder 6527 16:50 Avvice at 508 Rock River for. 508 Rod River Sample Collection. 19:30 Leave Trailin for Hotel +7:54 End Page RL 17:30 Annu ct 1812 Sandy Hollow 17:35 Bajun Purge-17:54 End Purge 18:00 Sample 1812 South /tolow Colkilad. 18:05 stopped at 2619 Lindberg- Not Home Arrive at 2406 Lindale Begin Punge 18:16 18.39 End Purge, recieve acture regarding squirely 18:50 Leave THOCLinable, Sample Collected Lots of small bulbles in prince water but wore in VOC camples. Stopped at 3141 5 175 twoll Could says well was recently hit by lighting and well pring was replaced on Saturday, so did not rake sample! 3 samples in Cooler for agent 319 Savyer, 2406 Kindale 1812 Sanity Hollow - All 3 metas samples preserved Looles sealed with castory seed

6/13/90 wal 10:55 End Huce 8:00 Neter OOTER calibrates at 970 11:00 Sample 3109 20 5 called. in 1000 unles/cut fluid 1134: ARRIVED AT 2315 HARRISON 8 15 Break custody seal on Cooler 1136 SIARI PURGE (VICTORY TOP) Containing 3 samples from last 1045: DuplicaTE Sample TAkon AT 2315/AR Mefit 1st stop & Church of GOU AT 11:57: ENO DIRGE 1917 1200 Samples NEW at 2315 Harrison. Suspected location: 2022 5. 19th + Duplicate. No one here - will have to 12:15 Stopped at 3110 5.18 4. come back on sunday? 200 SAP 2602 S. Thistat Electro No our House. 1220 Styred AT 3120 17th Collisian Certa Spoke w/ Kass START pire 12 40 ENDPARGE VERMA (OWNEL) 1232 Milkab With OWNER - SAMPLE POINT : GAMRIOM SINK 1245 Grangle collected at 3120 5 17th on Nai4BAST just from to sparrot Thunders rown - NO HO Topac a sofrener 14.00 : STupped AT 26 19 LNOSAG NO ONE - 45 No boTTles Water - 1912/c 7416 : 35 xc/2556 11-20 Arnue at 3102 16th STAT DORGE 09.28 cm 14:22 Began Pinge 10:02 End Pince Sample 2602 17 51 Collected. 1441 End Parce 10.10 14:US Sample 3102 16th Sr. Collected. Field Blank at 1602 17 collected. 10.15 STYPPED AT 2713 10th: VACINT 14 50 Arrive at 3122 16 5 st. 10:31 10.56 Start Purces. AND OVER - RY ARRIVED AT BIOG 20th 1511 Parge interapted & STARTED AT 103**5** 51777 page: 10:34

END PURGE 19:15 samples 37.45 Collies, 2810 8th, 1574 Stopped 1 2801 3110 18th, 3110 18th Field Blank, 1600 Pollis 3110 10 E, 3110 10 thy, 2619 1600 smenso puraje END PAZGE 1628 Lindberg sealed in cooks. sample collection Along W/ 1632 Custody Sear Noumber 6531. marrin spike DupligaTE 19:25 Pack up and leave tories ARRIVED 3245 Collis Tvailor. Thoma You. TA/ked 10 owner : John Bruted 1649 START punge End Park. 17:09 6/13/890 Sumple 3245 Colline Collosted Stopped at 26/9 Lindberg Not House 1930 ARRIVED A 2619-1737 SMATER Beige 17:57 End Penge. Residents danstille, arrived as we were sulling out 18:05 Arrive at 3110 18'7 Begin Rung - Will collect field 18:10 black love IND BURGE 1831 sampling Nell have spises 1831 WATER WAS retholour bubbly hours 3110 18 collected 1845 Return to tracker

6/14/50 0/14/90 9:00 Amue at Nayler, Scott H lo calibration instimments. 946: Steppes of 1926 Pechel y no one 4.10 Break Kustody seal on cooler. was home 952 STOTYLEON 3215 11th & NO SALK Virginia Wood wrongsels. 8:30 00928 califoration 950 in Number 04/575. 1018 Stepped AT Clepanolds ADJACON TE 1000 sunto alibration third. 3215 L. TAKED W/ SINE MIT pH meta calsovated of. Supposed of 3/35 HORRA: Residentes will term to sough AT live 5175 Well is in same same system # 1013 : sugged AT 13290 Pres Hai make us as 3/31 8-3183 NOT BANGEU sopped to 3/25 Bire hall DUT IN SOWIM Telow 4+ HTM DIO NOT Man Access to well, Salo Nell Was chocked percents 1018: supped to 3329 hopes 1021: STHET puge 101/3: END BIZE & SANJELD 3324 LAPRES a WAS NOT INTELESTED IN hour 10 5 Amgoles tico Reliver to raises 3106 MARShall 114: Arravel AT 3230 hape, TAlked up From towel) asver Russel Bross STAZT PARCO End luxes. Sintelled faccets because 1117 STATE PURGE Cach faucet an close to well. 1130 EXTRATED FIELD BLANKS Sangle Men (3106 Mass soll) 5'3U 1141 Sample 3730, Laprey Collecter. Field blank also collected at 3/34 sever sryged & NO 3230 Laply. Aprily present - will return do 11 50 Stopped of 3213 la pay - Not Home. lager Fine 1737 Formy : styped but Norme

signed of 3137 lapa, worm suppresent to bypics softenen. man value on 60 w thent of home Belause of doubt, in sample SO WENT ACROSS TO PIBE KAPES taken. 15:30 frive at Mc Loudor's - 3237 11th AND NO ONE love - Nent to 3/34 15:31 Begin Purge haper to once igan no one is 15 41 End Punce Sryped @ 3013 (grey No or (15 45 Sample Collected 3237 11th 1204 1550 Anneal Pizze Her - 3327 1/5 5 Rped @ 2026 104 1210 1551 Begin large - Queston about & ND and water sotherier jupporss - will next with conductivity instern as ad 1210-1240 Made address may. 1550 Avoive at Comm Ed to take Last ora. 1609 End Purge Industrial all sumples 16/5 Sample 3329 11th collected. spoke a James Freeman 14:20 Start Parce Keturn to tracken 14:42 End fund 1640 Arove at 3137 Kai shall 14:45 Com 14 Ed-123 Everzy Dr. 1603 Start Purcec sample collected No water - Check laucet in Caseman 14:55 Stopped at 7800 Falind 1656 Hart Purge again Shurdon Tucking couldn't varty 1717 End Pange that sample point by passed 1720 Sample 3137 Marshall collected. sotener, so vested conditionts 733 STOPPER AT 3137 Sevelly NO ADI AS of wall, known to be so pried -1738: STARS pay at 1726 Parsling. 1100 rambos - same an finge 1756 , End purg. water from spigot which is

+115/90 Friday Samples West 1226 Pesting 1800 4 to Arrive at tracker, break such Stagged AT 3139 Swell St. W 1811 on cooler with last night's sungles Stapped AT 1637 bousting be over samples. 1814 START punge " 30 Calibrating weter - Conductivety wite 00928 calibrales at 810 unless in 1837 End Purge 1840 Sample 1637 Parshir & 1000 untie Hust 19:15 Samples 1776 Pershing, 16:37 Parshall " teams to make addings map 1:15 Arrive at 3/29 Horrow 1317 Burole, 2624 5th, 3/1574 4.18 Bagin Purge will collect days 3237 115, 1202 Broke, 3329 here 11the sealed in cooler - custody 9:42 End Prince seal 6538. 11:50 Sample 3129 Horon + Dig collectical Leave cooler & mailer Note: Because of position of force t, we could only All mitals workers 1/2 hell, so we used a third initials 60 H/E and 10 H/K the routemed i'c 1/14/90 remainder. 312 Pottle was hen disearchist -11 or Stopped at 3137 sewell get agin parcets are not home went vest door to 3/35/2 Sewell 12:01 Began surge. 1.4 End Pence 1230 Sample 3135/2 Sever collected, Ham buch to Trader

bunch Arrive 3213 Capey 1430 stopped at 2703 20th for expountment 1150 Start Purch Not lone Field Blank collected st 3213 Lagran 1135 Stopped at 3101 lopen - Not browne 1420 End Punge 1440 Stopped at 3/3? Lapen - New resident Collected Gruyle 3213 Lagran says that they have brooked up Stopped at 3137 Laply - Net Home 14:40 to cety waites 14:45 Stopped at 301 lappy - Not Home. 1005 Stopped 3/38 Kapen 1450 1446 Bagan place. Stopped at 30/3 Capey - Not four Stopped Arnhe at 17/3 Hourson -14:55 1713 End Pinge Bogin Pinge 1715 Sermele 3/38 Capey Collected End Russ. 1740 Closed Cooler Line samples 15:20 11575 Sample 1713 Harrison Collected from 728 standy Hallow and 3138 laper (Custaly sen! 1550 Stepped at 1817 Havison . Not Home Worker at 2007 Harshall says 16127 Nimber 6545 site wed to be a dump for Foundary 1 other last installies Ashid up and clow 2000 1610 Elech of sewell and Marchall-No water wells on this Wail 1615 Stopped at 2400 2646 sewell-Lither Jackson says well does it work will my again liter mit next well ofth he has a chance to get a plumber to tix the (Light dries well

1110 Arrive at 3109 Collies - Corcovan Brown at to willy, Book carlos, sent on contin with yesterday's Auto Body 1113 Begin France Samples. 6: 30 Calibrate Conductively water 1134 End purge. 11:35 Sample 3109 Collins collected. 00928 - 8500 mmbers in 10,000 11:45 Arrive 3126 Collins Colibation Mich. 11:53 Start proje Sropped at 2622 19 - Church of 9.30 1213 End pringe God - Nor Home 1215 Sample 3126 Collins Collection, Stopped of 2703 4 20th Not ten 9:35 Steady rain since 8a. 0802 1240 Limeh. 9:40 Stopped et 1817 Harrison Not 1330 Stoper 2703 20 - Not beans. homp. stell numer (stoucht, Stopped at 2635 10th si 9:50 1340 stop at disservely of God elect an city water NO one Home \$622 19th Stopped at 2626 10th St. Not 1345 Stop at 317 Horrison - Lot from 1405 Stop at 3138 8th - Net Lome. nome-1410 livine at 3122 Biblald Stopped at 3101 Capey 955 958 1415 Begin fung - Dup will be rate, have Begin Parce 1136 End Pinge 1071 Encl lung 1445 sample 3122 B Wall + Digg. Sample 3101 Lapey Collected. 1025 Stoffed at 30.2 94 - Not House collected hive 1055 Stopped at 3101 9m + Not Wome. 1500 Arrive ex 3206 Bildahl. 1100 stopped at 2927 9th - Ciny touto 1505 Begin 58 1105 Stapped at 2910 9th - Alverdy 1503 Begin Pulge 1/10 -1526 End pringe Sampled but not marked on my 1530 Sunge 3206 8 SB

6/17/90 Similar 1530 Simple 3206 Bildahl and Matrix 8:30 from at truler discuss days Spike taken. activities 9:00 Begin maling address may 1545 Return to waiter for sample pachaging 110 Peter to reader, Calibrate 16 45 leave ricular for Hotel (5). unstruments. Conductivity weter 00928 reads 8800 in 1000 umbo colibration fluid pH wite. OK 6/16/90 11:30 Stop at 1817 Harrison - Not home 1:35 Stopped at 2703 20th Not house 1150 Stopped at 3102 4 51. - Northouse 1155 Stopped at 3101 9th -1157 Began huge. 1223 End Purg 1240 Stopped at 2622 5 19th - Not home. 1250 Stopped at 2009 9 the side of claims they are on city water 1256 Begin Curge 1322 End lung 1325 Sample 3022 8th Collected 1400 Lunch 1445 Give at 3138 8th 1500 Field blank taken at 3138 8th.

End Purge 15/12 6555 used to scal coolers. 1515 Jumple 3138 8th Collected. 1820 Correction 3109 9th should be 1525 Arrive at 3109 8th 3101 9th. Break Courtaly seul 1526 Bosin purge on with so mile some bottles 1551 End purge 8th taken 1555 Sample 3709 8th taken are labelled projectly - They are. Neserol with custady seal 6556. 1603 Arrive at 2703 Roth 1825 leave for inflit Begin purge 1605 End pulige. 1626 sample 2703 20th collected 6/12/90 1630 Arrive at 1202 Sandy Hollow 1700 Start Purse 1702 1772 End Finge 1725 Gample 1202 foundy Holow of Ested Stopped at Church of Good 1740 on City water according to patter Stop it 1817 Harrison Not some 1745 1805 Return to trailer. 1815 Samples 1202 Sound Hollow 31019 6, 3107 Grant Park Bird, 3022 8th (3109 9th) 110 Brocke, 3117 Piver Bird + Dip, 2703 20th 3138 8th + Field Blank sealed in rue coolers with 1015 % We Gustody Sects 6554 1

Break custods seal on two 1840 trave at Estaring, meet with Paul Deveus sample coolers. Calibrate 1358 Bagin Aurge instruments. Conductivity south 00928 read 900 ambos in 1423 Earl Purce -1000 califorto Much Note: Sample 1425 Sample Collection Sample was collected right next to heat wolve for overances also continued Trip bland, but blank now not treatment machinery - May have causal difficulty with semperature labeled plt wells calibrated. Begin habing address kup Stabilization. 7647 8- - Industrial 850 Stop at 7613 # 11 = Eurployers 1030 don't know where well is will 1515 Stopped at 1001 Harrison - on stop both citi water Stop of 1817 Hawison - Abt home 1525 Stopped at ZA13 hishwachen -1050 again - will take sample. ligeour Club - Not House, but Begin purge 1053 weighter has well. Erd Pury 1540 Aver at 608 New Miltord 1118 Sample 1817 Havrison + Matrix 1543 Begin purge 1125 1559 End luce Sylva Sample roles, have 1600 Sample 608 New Milford . -Arrive at 2013 114. 1135 1015 Stopped at BAIT auto 2979 8th, 1137 Begin purso . -End Parce 1212 Facility at 914 Brown has no well Problems with stabilization, but but we could get a sample at readings fall within prescorted variges, so will rate sample. 1620 Stopped Kincades Service out Sample 7613 Not collected. (101 Browne

1624 Begin Frugt Plumbing looks Vila outside spigot 1648 End Awig can bypuss water soften with 1650 sample 110/ Brode collected. shutoff value - Check TDS (conductivity) Keturn to mailer, discuss 1700 of rap water ve outside spece. sample points Top water is higher by 150 muchos, Stop at 2624 9th - No Each Arembar 1745 30 OK 10 sample. Stopat 3007 7th Cry Water 1925 Begin purg. 1800 30012 7th - City Water, 3008 7th 1950 End Purge 1955 Sample 3037 Kishwanier collecter not home, but neighbor at 2010 Samples 3014 Somer + Field Blank, 3010 says they're on city water Stopped at \$330 7 16- Not Home 3037 Kishwanke, 3110 River Blood 1815 Stopped at 3011 Sance - Nor Home 1820 621 Konnon, 1101 Broche, 608 New Across street at 2014 Sapar Milhord sealed in Cooler Custode they have well so we will Seal 13272 rale Sample 2015 Leave wailer for day Begin Purgs - Will rule held blank here Begin Purge again - Hose was 6/18/40 Krishell Field Blank collected @ 3014 Same End Pange 1859 Collect 3014 Sover 1900 Stopped at 805 Barryon - City with 1915 Stagged at 3037 kishnaulier -1920 Chech water softened by pass -

6/19/90 Tan Brue at trailer - Custody seal on cooler intact Bogin Addinoss Mayos Return to trailer colidate interments for Manicipal Well Sauges. Yam & Rober will sauge Prepare to discuss sampling ponets w. Dave. Dave Dolling arriver at raciler. Discuss 39 points where we do not have samples yet. Leave railer for reach. 1300 Return to tracter. 1325 Arrive at Ros Rod ford Products. Arrive at site of purp - No way 1345 to purge sample point - can't discharge water, and any hose would be in partical of forthe 1185, will pence several oudsto lamp runs couthacusty 24 lus per day 7 days per wed! Address - 707 Harrison. Flow vate or pump is 750 golfmente according to lay dons, plant, toreility manager - Will take Held

Wante hero. 1350 Field Blank taken at 707 Hawison. 1420-1440 Collected Rockford Producto (707 Haverson) + Dup. Lots of dithealties - constrit pury via hose so purged II gal with builet. Lots of truy bubbles in water couldn't get voc sawyle without bubbles - too much back pressure. small bubbles in all vocs (total of & VOC be Hos) well is sixuated rest to had ment, area, so very hot lots of oil of greass around sample spigot and unuschale area 1452 Arrive at 27/17 Zoth - abandonal house for past cleren (11) years swording to neighbor at 2711 20th. 1tas well, but not not king, (electrical uning 2711 20th has city water, unhooked) 1502 Stopped at 2646 Sevell - pteriory sampled by Butter/Itodge -. 1975 Feturn to tracker. 1500 - After talking with DD - Kead to

Collius is see if we can take

with which is too sale additional samples. 1830 Stopped at 3387 7th. City Water Cleck Non oversanders to survey: 1840 Seal Sample 505 Bavanin in 2818 Ciny Water cooler with Custody sols 1003 2825 Cety Water and 1004. 2831 City Water 1845 Talk about Samples with Done 2833 City Water D.D. says we've covered the 2841 Not Home 2905 City Water servitory, Go Home. 2907 City Water (According to very liter) 29/7 Not Hone 6/19/90 2935 City Water Stopped at 2917 Collins - City Water stopped at 2011 Collins . Not Home Avoive at 50% Barnum 1740 1743 Begin Purge 1803 End lenge. Sample 80 505 Barreum collected 1805 Stopped at 401 Sawyer - Not Home 1810 406 Sauger - City Vato 407 Sanyar - City Water 418 Sawyer - Coty litato 412 Sawyer - City Water 4 RL 505 Sawyer - Not Home 1820 1825 Scoppard at 3324 7th - Cirylath 3325 is a facant house

6/20/90 (Wed) Anne at raile, begin packing up traile. Stopped at 505 Sawyer - Cit Wat 915 Baçin Mapping Check Conclude Mapping - Check Traile, leave site. 930 1230 6/20/90

SOUTHEAST ROCKFORD

FIELD NOTEBOOK #2

JUNE 1990

Sample Team 2

Property of Bob Hunk CDM

Camp Dresser & McKee

Address 200 W Adams St 1600

Chicago D 60606

Telephone 312-786-1313

project 1681-003-CG-GEAD

Trail # # 399-8303

This Book is manufactured of a High Grade 50% Rag Ledger Paper having a Water Resistant Surface, and is sewed with Nylon Water-proof Thread.

INDEX

	,		
 		 ·	
		 	· · · ·
 <u> </u>		 ·	

calibrated and gas no pH meter 00930 calibration Ex 1755 Hamilton Surge Begin at 13:56 Armyle Season: ontoide Aprigot SE corner Arme PN @ 14\$S 12905 Suner No One Home My € 1453 2819 Saper Does not 2820 Survey Dock not M

. 1

@ 1454 2823 Sint 1545 original Sample Site 28055-4th Street does PN + sixs ton. up to che water 1st 28175.4 th street PAI @ 2520 4th Street on city water still using but out to hook people ere on cfty + saple due to c 1505 location in basenest 2828 4th Sheet 2012 2819 \$4th Steet PAN Supla talan From Kitchen water Spigot Hart Burge 15:51 ... Outfor location - west sed Inside PN of Gonze Start purche 1509 Start moosurement 15/-1 End somplery 16:10 End purge 1525 RN Applied Forton Sample was talentoise PN RN

w/12/10 Acto: The found that stores 8:00 & forth down west the Site is a place of kurinen. Sire an alterative was sompled, this sile villant be sampled. RIN Conductority mito # 02079 is talibertal at 9000. 3007 Fire Boulavard Begin punge 9.53 am 6/2/20 Spirat - Cratef outsile on west Side of forme. End pringe 10:03 Songle time Regen 10:20 10:55 605 South A does not exist. Che altourate: 519 FAT EN Sunds Sheet is one uty water . Ho one wan Some it altornate 1527 south tt. Cd4 South St 11:19 End pura 11:36. 2820 Oleson. mo Junes. Begin Junge 12:15 Fred pury 12:35 Begin Sampling

Come 2901 S. Forth Cheple of time Regin purge 12.59 Erd punge 12 49. Sample time 12:52 This was on alternate for 2917 S. 4th 3011 L'm - you cel. I tried Oltunia. Ho seecen. 5037 4th zon or city roaler 3010 was not of Home 826 Brooks was not at forme. 1425 anne 827 Matte Tomb, at home Begin purge #27. End Junge 14 37 Amplin time begins 14:45 14:52 2905 Sanor Begin purge 14:52. He one at 4 one. End purge 15 0 Begin sompling 15:22 409 Brooke Debbie Standard at some. Reger Purge 15:22 End purge 15:34 Street sampling 15:37 16.04 326 Brooke. Aurge 16:06 begin. End purge 16:16. Sumpling

16:21. beau Begin Sompling). Oriere 3301 St 8+4 H. Mis arive 202 Grooke Jamily athema Foul simple from 9:31 hidden. Begin purge 1641d Epstle rot at home Bages End pluge 1655, Honpling 9:44 begins 1655. PM 1655. End punge. Begin Dompling. 9:57 arire 3337 5. 8th. Handeron anne 319 Hawayer Begin 17:38 Eld surge punge 17:3% at Some Regio Penge 17:00 Begin Songling 17:50. Over 3201 2 8th A. 10:15 John Worton 10:47 6/12/90 Mr Stillegor at home. Beggi 6/13/90 End penge Begin sompling. Conductionly Mete Coliberation 11:03 Angthetion Fictor 1000/990 acces 3310 Collins. 11:17 Children at home. Begin punge appointment list: 3337 8th Marntk Ellenberge 11 31 End purge Buyer sompling 1300 Sordy Hollow. no. (aft) 1306 Sondy Hollow Jamis Deroin 13:34 3233 7th Mary Godon extens Desorie was of home. Boger 615 Savyer - tey a get it. purge. Noted that the water Cerine 3337 8th St. Marvette is very ruf Word-almost. Ellanberger at from. Afrit Perge. Present purp 13:46 End purg! Begin sorpling! 14:30 tuned on. Had to tun water Curre 3598 7th Street of after 3 from resumed. Tornado het aua to minutes sealen. Degin 9:14 Erd purge

14. 54 End pres . Begin Monpling. 15.10 3234 Kladicantee northerinty at Well so barakmonon Teel to raify that they're not on city 15:44 ann 480 Martin No one home. Begin jurge. End purge Beger myreng 2805 Gollers. Rigdog. Magis. 2822 Celler Elast. - Congwater auer 2810 \$ 8th People at home Buyin pury ,70% End Junge" 17:40 Bigin Sompler 17:40 ann 3:05 8th 19 0 KN Gordel for 3305 8th H. To such orlower. 17:44 anin 3045 9th S. July Bennett of home Bogas physica We conout of note. No electricity to run Jump due to Vornold, Wet in hor fote 18 03 / Cent 311 & 1019. Mr

Turnelles af home. By pregents of the Tuble in with pH miles gist manural did it register pt End a RM. 1831 End Junge 1833 N. Junge 1822 Regir simple 19:09 Endy day Rober of Morton 6/14/90 Calibration water . 020 To 830pH meter Sound number: 00931 Calibration at 940 conductivity factor 1000/940 applinament UST 3115 7th Amaro Willaton 3:35-6:36 3110 Same Kristy Whitmen often 400 3009 Bildell Kondy + Thous John ofter 5:30 / 9.04 arine 3309 & 7th Resident did not anwer door. Begin purge. 9:22 End ynige 9:23 Begin Sampling 9:30 arive 3245 9th St Roudent at have. Begin purge. This is a smooth meit due

End purge to a 4 torn & subsequent 14.35 Begir sompling power outage 6/13/90 End purge 14:47 Union 2024 S. Fifth Stant 9:43 Resident not at home. Begin Begin sampling frage purge 9:58 arrive 3239 Keshwanker. 15:09 Renderly at lone. Digi purg. End purge 15:10 Beger sumpling 15:51 arrive 3115 S. Fth. Resulvale 10:12 al tome. Begin purge. Begir bampling Arrive 3300 Fishwakec 10:13 There was a filer, but it Begun purge Resident of home. "his removed price to End Gurge Begin Sampling Ampling. 15:20 arrive 120 Brooks. Residenta arline 3045 4th Resident at home. Dogin purge. at home. Begin purge. End purge 1634 End purge 1435 Begin sompling. 11:38 Curice 2914 8th St. 11:39 16:57 arine 3/10 Xorler Residents at home Begin purge 12:17 Biside t at forme. Begin 17:09 End purge Burn purge. 17:10 Beaux songeling End purge, Begin Sampling. Others. arrive 1317 Broke arident 17-23 12:29 not at some Bogin flunge 12:30 1739 End purge 1741 Resident arine as we Begin sympling. 18:06 Column Joog Boldakh begon purge Degen purge

Lozator la lat hora. Obsident. are on city wales, bil clad sand folder left menege to soliple. Begin purge. Rose well. Will call Will End pilery Jerry Brown, the lastlest 11:11 Regin somplen all 1 393-4284 to rerify Father come odd : gon Begin Junge. is as The formac other into 13 14 Begin simpling 11:26 anie 3282 Keskerber. Can do Owner wel is of 19:12 Call Mrs Buy Goun. She mil 300 win on city house. This location was et one time a ges setetion. water only, and the well his to longer dry in took of Ogen purge 11 39 End frage. up to the hand. Samples arrie 3038 Bildall. Penlort 11:35 your dechough. 1d 102 Relience Forton is I tome Begin punge. 6/14/80 12 22 End purge 6/15/90 Calibration meta: 02079 12: 23 Bagin rolyeling. Colinulal et 9:50 pm. 1a:37 PH Meta. 00930 Course 3141 Bildall. Resident not it home, but letter appointments alland into somple. Degin - 32 0 9th Lung An 14 Any frange 3dola Kishwarter Mr. ahostad 11:30 12:49 agio 9th Codwell Condy feely arise 10:59 3210 910 12:50 13:55 Cum 2710 9th Resilut Jesidents of home but not it have Will souple forther was asleep. To (elow.

anni 31da Blacker Rinder velide spiget spetilige not all home. The was the second attigut. (Androl to rote sifter. Didn't might 16 13 anies stol dapay. Mor round ender ettent bulay). And retronjet chome lift not roughle. 16:15 ann 3/13, 2 pg. Mo Coming 3204 Bildel Forder one force Didnet cool of home. Ky frist Somple. anile 300 Lopey. Paulons 16:19 En perge Bildall-Rendertathon. at home 16:20 This sile has been wonfled 14:25 14 26 Begit samply 16:25 arin 33 8 Bledoll Resident already. End purge. Did 14:45 End perge judg mit muli 16:49 anine 928 Ar, Ly Hollow anin 290 9th H Resident End punge 16 51 17.04 15:35 17105 Begen scripling. Lt Love. Begin Junge Grand Hoder 15:57 End Hunge 6/15/0 Cum 306 841 16.10 m Barray not analytical for touse Not get hose uncommela. Question est whole

6-17-90 6-16-90 1200 Arrived 8+ 3117 RIVER Weather - Rain outress to Midstarted purge 1203 1232 end putye 1145 5t-port at 3015 Grant 1233 Sample dollected (DUP) Paris Blud - Resider said KA well is steel and installed 1249 Arrival at 3107 Grant N1960 and is Shallow PAIR Blud 1146 Begin purge, outside 1255 Start-1 Porge Spigot on NW Side End Purge 1313 of House 1314 Collected Sample Standed Stabilation Tests 1156 end purge 1212 1414 Arrived at 106 Brooks 1214 Collection, sample No Body Home west 1216 Collection Field Blank Sample. Next Door to 108 Brooke Scott Craix do paper work No one home there-eiter in traile for to rest of the day. 1420 AICILA at 110 Brooke 2 doors down from 106 6/16/90 1421 Bayan Porge End purple 1439 Collect Strapte 1440

Arrived at |825 Barren 6/18/90 resident Stated howas Conductorly netwo 00928 Culimitalto to 900 kg in 1000 calmenter on City water Pul Wete # 02363 10:39 anie 1630 Hamilton Resident at home. Single taker in the bathroom. 10: 55 End purge 10 & Begin forgeting, notel some Duyrirdal solds in 1100 arrive 810 Sandy Hollin Ike. Sordy Hollow. Me Valuein was at tom. She doesn't Speak englat - spenishonly. Ift a note for her herball o tread to freighbor. 11:37 Begin purge 11:40 Begir Donplers. 12:15 anin 841 Fourtel Ilis is an atternative for

843 Journa A. Rundonton at home. Begin grange: 11 Motical Host conduit 12:16 101 20 surring from well cep was & block plante. End puge 17.98 Besen songeling. 12:39 When 204 left. This is 12:38 or alterale fre oci faft which does tril. 800 does not exist wither. Rindert home at 804 Ans Degen pugl. 12:53 Begin surpting. 14 00 arive Kord Kerer Relovation Estadard Met MI- Richard Erch. Those are Two portes wells. We will some well Beger purge End purge. 14:25 H: 26 Bagin or milery

Mile: a denotion well : 2 polise well in sie the surper 1 poteste weie (#2). 14.50 aning 3305 7th foras 300 eppl. Soul that prings And been het by elightened during ATAM & Show his no willed and Cold No songelwere taken. 15:d5 arise 333 9 14 St. No one home. Dod not Somple. 15:30 arin 505 Barnum. Ils was the second ottompl. Inst attempt rose on 6/14/90. Its Letent does tot oppear to be logged. 15:37 arine 604 tawyer. No one some. This is on elterre for 611 vistich is in isty roter. No souples the 15:40 Curing 604 Barmen No one rome so somples the citizent for Will Burnen.

arrive 420 Barry. 18:51 Rune 315 Anny altarotifor 415 Stanin. Rondertat love. Begin On on water 15.48 Dege purge 11:53 active 505 Autoger. Erd Surge 14:00 no one home. Did relaces 18:57 anire 809 Danipe. Begin bampling. aries 621 Ferron Mo one home. anne 815 Sawya 16:15 Friday at home. Cegin 19:00 Resident Days her or purq. End peurge city voter. 14:28 Begen sompling. Circa od Harry 19:02 Ofmichal sup helder city arrive 527 South St. 18:00 18:10 anie 310 4 100 orghome Did of surple with 17:05 arrive 619 Fitch. M. ore 11:12 auni 31094 Resident refund at home . 19:08 occen Does not wet Souple. Course 613 FILCH- No ore al lone 18:13 aren 31/0 Rive Blod Con line 19:10 anin 505 Barnin at home no one of home. 18:14 Begin purge 18:29 Egen somplerg. 19:13 arrive 604 Barmen. Roudall My he's in city 18:47 ann 405 Lawren. willin Curie 604 Arrya Riders 19:19 On city with Did not Supertis on city water France 1911 11:49 arrive 401 Lawrey arion gus Barnum. 74 one Love. The one of home.

arrived 410 Hearon. Fat sac ldog that Adre somple. 19:32 aried to Kennon. Cleridate say they in on conjunter. Frank of Mount 10.00 4/19/90 Colhestra mela # 02255 Colhester forda: gff mila # 10:15 2944 Bildall South enex of the planground. Industrial so for into on well construction 10:28 Bisin this wife is 11:15 Curius at 3013 Laprey 11:20 en Big in pungle Mars End purget 11:35 Begin sampling; Taking Displecate sample keve.

12:00 End sampling-1:20 Curius at 2646 Swell 1:25 Bogin purch, Kitchen 1:40 End punge; begin simpling 2:30 avrice at 3097 Billing 3:35 Buyin puriou - outside spirat 3:50 Begin Sampling; encl pince. 3:30 Ciroine at Cola Fitch. Lety Water 3:40 artive at 413 Fitch no one horse, resoluted says 3:45 Orvice at 800 Brannum-- no oir home 3: 50 Curice at 401 Sawyer no one home. 4:00 arrive at 505 Sawyer - no 4: 05 arrive at 809 Sawyer on coly water. 4:05 avrile at 410 Kennan 4: 95 Pagin proper. H: 12 the Bagin Supplies; ence purge.

2:20 ainuel at 3330 461 -4:20 CUSO Sampled for MISID

at this location —


5:00 End of day

Pancie N. Prusher


APPENDIX C

3-D CONTOUR PLOTS OF VOC CONTAMINANTS FOR IEPA/USEPA DATA


3-D CONTOUR PLOT OF TCE CONCENTRATIONS FOR IEPA/USEPA DATA




3-D CONTOUR PLOT OF 1,1,1-TCA
CONCENTRATIONS FOR
IEPA/USEPA DATA




3-D CONTOUR PLOT OF cis-1,2-DCE
CONCENTRATIONS FOR
JEPA/USEPA DATA




3-D CONTOUR PLOT OF trans-1,2-DCE CONCENTRATIONS FOR IEPA/USEPA DATA




3-D CONTOUR PLOT OF 1,2-DCA
CONCENTRATIONS FOR
IEPA/USEPA DATA




3-D CONTOUR PLOT OF 1,1-DCA CONCENTRATIONS FOR IEPA/USEPA DATA



3-D CONTOUR PLOT OF 1,1-DCE CONCENTRATIONS FOR IEPA/USEPA DATA




3 - D CONTOUR PLOT OF PCE CONCENTRATIONS FOR IEPA/USEPA DATA



3-D CONTOUR PLOT OF VINYL CHLORIDE SOUTHEAST ROCKFORD PROJECT CONCENTRATIONS FOR IEPA/USEPA DATA

OPERABLE UNIT



APPENDIX D

SPREADSHEETS USED TO CALCULATE HAZARD INDICES

S. E. ROCKFORD OPERABLE UNIT

Address	Contaminant	Water Concentration ug/l	Maximum Contaminant Levels (ug/l)	Chemical Hazard Index	Target Organ Hazard Index
1735 Hamilton	Carcinogens				
	Liver		•		
	TCE	0.8	5.00	0.16	0.16
2955 11th	Carcinogens				
	Liver				
	TCE	1.0	5.00	0.20	0.20
	Non-Carcinogens	-			
	Liver				
	Cis-1,2-DCE	11.00	70.00	0.20	0.20
	Carcinogens		•		
	Liver				
	PCE	1.1	5.00	0.21	0.21
3015 11th	Carcinogens	•			
	Liver				•
	TCE	3.3	5.00	0.66	0.66
	Non-Carcinogens				
. •	Liver				
	1,1,1-TCA	. 6.3	200.00	0.03	0.03
326 Brooks	Non-Carcinogens	•			
	Liver	÷			
	Cis 1,2-DCE	14.0	70.00	. 0.20	0.19

.

,

S. E. ROCKFORD OPERABLE UNIT

				Target	
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
************	=======================================			**********	=======
	•				
2620 Lindale	Carcinogens				
	Liver				
	TCE	1.1	5.00	0.22	
	PCE	0.9	5.00	0.18	0.40
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	1.7	200.00	0.01	0.01
2412 Lindberg	Carcinogens	•	•		
	Liver				
	TCE	1.6	5.00	0.32	0.32
2905 Saner	Carcinogens				
	Liver				
	TCE	1.7	5.00	0.34	
	PCE	1.0	5.00	0.20	0.54
	Non-Carcinogens				
	Liver			_	
	1,1,1-TCA	1.8	200.00	0.01	0.01

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hezard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
=======================================		**********	=======================================	=======================================	
409 Brooke	Carcinogens	·			
	Liver				
	TCE	2.4	5.00	0.48	
	PCE	2.0	5.00	0.40	0.88
	Non-Carcinogens				
	Liver				
	1,1-DCE	0.6	7.00	0.09	
	1,1,1-TCA	3.8	200.00	0.02	0.10
3301 8th	Carcinogens		•		
	Liver				
	TCE	0.6	5.00	0.12	
	PCE	0.5	5.00	0.10	0.22
3237 8th	Carcinogegns				
	Liver				
,	TCE	1.0	5.00	0.20	
	PCE	1.8	5.00	0.36	0.56
3109 20th	Carcinogens				
	Liver .		•	•	
	TCE	1.2	5.00	0.24	0.24

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water (Conteminant	Chemical	Organ Hazard
		Concentration	Levels	Hezard	
Address	Conteminant	ug/l ===========	(ug/l)	Index	Index
2801 Collins	Carcinogens				
2001 COLLINS	Liver				
	1CE	2.0	5.00	0.40	0.40
	Non-Carcinogens	2.0	3.00	0.40	0.40
	Liver				• •
	1,1-DCE	1.40	7.00	0.20	
	Cis -1,2-DCE	2.1	70.00	0.03	
	1,1,1-TCA	8.6	200.00	0.04	0.27
•	1,1,1 100	0.0	200.00	0.04	0.21
2602 17th	Carcinogens		·	•	
	Liver		•		
	TCE	1.1	5.00	0.22	0.22
	Non-Carcinogens				
	Liver				
	1,1-DCE	1.0	7.00	0.14	
	Cis 1,2-DCE	2.5	70.00	0.04	
	1,1,1-TCA	29.0	200.00	0.15	0.32
2315 Harrison	Non-Carcinogens		,		
	Liver				
	1,1-DCE	0.9	7.00	0.13	
	1,1,1-TCA	11.0	200.00	0.06	0.18

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	1 ndex	1 ndex
=======================================	************				=======
3310 Collins	Carcinogens				
	Liver				
	TCE	0.9	5.00	0.18	0.18
. •	Non-Carcinogens			31.12	
	Liver			•	
	1,1,1-TCA	2.5	200.00	0.01	0.01
	.,,,,				
3120 17th	Carcinogens			. ,	
	Liver				
	TCE	2.0	500	0.40	0.40
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	2.8	200.00	0.01	0.01
3102 16th	Carcinogens				
	Liver		. •		
	TCE	3.1	5.00	0.62	
	PCE	0.7	5.00	0.14	0.76
•	Non-Carcincogens		2.00	••••	*****
•	Liver				
	1,1-DCE	1.1	7.00	0.16	
~	Cis-1,2-DCE	1.5	70.00	0.02	
	1,1,1-TCA	7.0	200.00	0.04	0.21
	• • • • • • •		-		

S. E. ROCKFORD OPERABLE UNIT

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

Address	Contaminant	Water Concentration ug/l	Levels (ug/l)	Chemical Hazard Index	Target Organ Hazard Index
430 Martin	Carcinogens	•			
	Liver				
•	TCE	4.8	5.00	0.96	
	PCE	4.7	5.00	0.94	1.90
	Non-Carcinogens				
	Liver				
	Cis 1,2-DCE	2.0	70.00	0.03	0.03
3110 10th	Carcinogens				
	Liver				
•	TCE	2.9	5.00	0.58	0.58
2619 Lindberg	Carcinogens				
	Liver				
	TCE	3.20	5.00	0.64	
	PCE	0.60	5.00	0.12	0.76
	Non-Carcinogens		•		
•	Liver		-		`
-	1,1-DCE	0.8	7.00	0.11	
	Cis 1,2-DCE	1.1	70.00	0.02	0.13
3245 9th	Non-Carcinogens				
	Liver				
	1,1,1-TCA	1.9	200.00	0.01	0.01

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
	•	Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/ˌl)	Index	Index
=======================================		=======================================	*********		
					•
3239 Kishwaukee	Carcinogens				
	Liver				
	TCE	1.8	5.00	0.36	0.36
3302 Kishwaukee	Carcinogens			•	
TOTAL KYOMMUUNOO	Liver				
	PCE	1.2	5.00	0.24	0.24
	Non-Carcinogens		3.00	0.24	0.24
	Liver				
	1,1,1-TCA	2.5	200.00	0.01	0.01
	1,1,1-10K	2.3		0.01	0.01
3029 Collins	Carcinogens				
	Liver				
	TCE	0.6	5.00	0.12	0.12
2624 5th	0	•			
2024 Jth	Carcinogens				
	Liver	2.0	5.00	0.51	*
	TCE	2.8	5.00	0.56	
	PCE	2.1	5.00	0.42	0.98
	Non-Carcinogens				
	Liver				
	Cis 1,2-DCE	14.0	70.00	0.20	0.20

S. E. ROCKFORD OPERABLE UNIT

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
***************************************	*************		*********	.============	======
7777 44AL	Caralmana		•		
3237 11th	Carcinogens Liver				
		0.0	5.00	A 40	
	TCE	0.9	5.00	0.18	0.70
•	PCE	. 0.7	5.00	0.14	0.32
	Non-Carcinogens				
.'	Liver				
	1,1,1-TCA	2.1	200.00	0.01	0.01
4000 0	0				
1202 Brooke	Carcinogens				
	Liver				
	TCE	1.6	5.00	0.32	0.32
	Non-Carcinogens	•			
•	Liver			•	
	1,1,1-TCA	4.5	200.00	0.02	0.02
3115 7th	Carcinogens		•		
	Liver		•		
	TCE	1.0	5.00	0.20	
•	PCE	1.3	5.00	0.26	0.46
	Non-Carcinogens		3.00	0.20	0.40
	Liver				
		7.0	200.00	0.02	0.02
	1,1,1-TCA	3.0	200.00	0.02	U.UZ

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
	=======================================		************		*=======
3137 Marshall	Carcinogens				
	Liver				
	TCE '	1.8	5.00	0.36	0.36
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	3.4	200.00	0.02	0.02
	•				
1317 Brooke	Carcinogens				
	Liver				
	TCE	2.3	5.00	0.46	0.46
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	0.5	200.00	0.00	
	Cis 1,2-DCE	4.7	70.00	0.07	0.07
1726 Pershing	Carcinogens				
	Liver	•			
ង	TCE ·	2.1	5.00	0.42	0.42
	Non-Carcinogens				
	Liver		•		
•	1,1,1-TCA	4.1	200.00	0.02	0.02
	1,1,1 100	7.1	200.00	0.02	0.05

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
****************	-		***********		
1637 Pershing	Carcinogens				
	Liver				
	TCE	1.7	5.00	0.34	0.34
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	3.1	200.00	0.02	0.02
					· ·
3210 9th	Carcinogens				
	Liver				
	TCE	2.0	5.00	0.40	0.40
	PCE	2.40	5.00	0.48	. 0.88
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	3.2	200.00	0.02	0.02
3129 Horton	Carcinogens				
	Liver				
•	TCE	0.8	5.00	0.16	0.16
3202 Kishwaukee	Non-Carcinogens	,	, - ,		
	Liver			*	2 10
	1,1,1-TCA	3.4	200.00	0.02	0.02

S. E. ROCKFORD OPERABLE UNIT

			Maximum -		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
***************		************	=======================================	:===========	*******
3038 Bildahl	Carcinogens				
	Liver				
	TCE	1.6	5.00	0.32	0.32
	Non-Carcinogens				
•	Liver				
	1,1,1-TCA	2.9	200.00	0.01	0.01
3141 Bildahl	Carcinogens				
	Liver				
	TCE	2.2	5.00	0.44	
	PCE	2.3	5.00	0.46	0.90
•	Non-Carcinogens				
	Liver				
	1,1,1-TCA	3.8	200.00	0.02	0.02
3213 Lapey	Carcinogens				
	Liver				
	TCE	1.4	5.00	0.28	0.28

S. E. ROCKFORD OPERABLE UNIT

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

Address -	Contaminant	Water Concentration ug/l	Maximum Contaminant Levels (ug/l)	Chemical Hazard lodex	Target Organ Hazard Index
1713 Harrison	Carcinogens				
	Liver			•	
	TCE	3.3	5.00	0.66	
	PCE	0.7	5.00	0.14	0.80
	Non-Carcinogens Liver				
	1,1-DCE	1.5	7.00	0.21	
	Cis 1,2-DCE	5.8	70.00	0.08	
	1,1,1-TCA	33.0	200.00	0.17	0.46
3138 Lapey	Carcinogens				
	Liver				
	TCE .	2.7	5.00	0.54	0.54
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	4.0	200.00	0.02	0.02
	,			-	
3101 Lapey	Carcinogens			 s	•
	Liver				
	TCE	1.8	5.00	0.3 6.	. 0.36
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	2.8	200.00	0.01	0.01

S. E. ROCKFORD OPERABLE UNIT-

Address	Contaminant	Water Concentration ug/l	Maximum Contaminant Levels (ug/l)	Chemical Hazard Index	Target Organ Hazard Index
*********	=======================================		*********		=======
3126 Collins	Carcinogens				
	Liver TCE Non-Carcinogens	2.0	5.00	0.40	0.40
	Liver 1,1,1-TCA	2.9	200.00	0.01	0.01
3122 Bildahl	Carcinogens				
	Liver TCE Non-Carcinogens	2.6	5.00	0.52	0.52
	Liver	4.2	200.00	0.02	0.02
3206 Bildahl	Carcinogens				
	Liver TCE Non-Carcinogens	1.9	5.00	0.38	0.38
	Liver	2.7	200.00	0.01	0.01

S. E. ROCKFORD OPERABLE UNIT

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

Address	Contaminant	Water Concentration ug/l	Levels (ug/l)	Chemical Hazard Index	Target Organ Hazard Index
3101 9th	Carcinogens Liver TCE Non-Carcinogens Liver 1,1,1-TCA	2.1 3.8	5.00	0.42	0.42
3072 8th	Non-Carcinogens Liver 1,1,1-TCA	21.0	200.00	0.11	0.11
3138 8th	Carcinogen Liver TCE PCE Non-Carcinogens Liver 1,1,1-TCA	2.5 1.0 3.9	5.00 5.00	0.50 0.20 0.02	0.70
3109 8th	Carcinogens Liver TCE Non-Carcinogens Liver 1,1,1-TCA	1.8	5.00 200.00	0.36	0.36

S. E. ROCKFORD OPERABLE UNIT

			Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	· Contaminant	ug/l	(ug/l)	Index	Index
	*********			***********	=======
4470 11 11 1					
1630 Hamilton	Carcinogens				
	Liver				
	TCE	1.9	5.00	0.38	0.38
	Non-Carcinogens	•			
	Liver				
	1,1,1-TCA	- 3.0	200.00	0.02	0.02
841 Roosevelt	Carcinogens			•	
	Liver				
	TCE	0.9	5.00	0.18	
	PCE .	2.4	5.00	0.48	0.66
	Non-Carcinogens				*
	Liver				
	1,1,1-TCA	2.4	200.00	0.01	0.01
		(•		
804 Taft	Carcinogens			•	
	Liver				
	PCE	1.1	5.00	0.22	0.22
	Non-Carcinogens				
	Liver				
•	1,1,1-TCA	1.4	200.00	0.01	0.01

NON-CARCINOGENIC AND CARCINOGENIC TARGET ORGAN HAZARD INDICES

S. E. ROCKFORD OPERABLE UNIT

		•	Maximum		Target
		Water	Contaminant	Chemical	Organ
		Concentration	Levels	Hazard	Hazard
Address	Contaminant	ug/l	(ug/l)	Index	Index
		***********	=======================================		=======
3333 Kishwaukee	Carcinogens				
,	Liver				
	TCE	1.2	5.00	0.24	0.24
	Non-Carcinogens				
	Liver				
	1,1-DCE	0.7	7.00	0.10	0.10
		2	•		
3014 Saner	Carcinogens				
	Liver	•			•
	TCE	0.7	5.00	0.14	
	PCE	2.8	5.00	0.56	0.70
	Non-Carcinogens				
	Liver				
	1,1,1-TCA	2.0	200.00	0.01	0.01
1101 Brooke	Carcinogens				
****	Liver				
	TCE	0.7	5.00	0.14	0.14
	Non-Carcinogens				
	Liver	•			
	1,1,1-TCA	2.2	200.00	0.01	0.01

S. E. ROCKFORD OPERABLE UNIT

Address	Contaminant	Water Concentration ug/l	Maximum Contaminant Levels (ug/l)	Chemical Hazard Index	Target Organ Hazard Index
7047		=======================================		***********	
3013 Lapey	Carcinogens				
	Liver				
	TCE	2.2	5.00	0.44	
	PCE .	0.6	5.00	0.12	0.56
	Non-Carcinogens				
	Liver				
•	1,1,1-TCA	4.3	200.00	0.02	0.02
2646 Sewell	Carcinogens		•	•	
•	Liver	,			
	TCE	0.7	5.00	0.14	0.14
	Non-Carcinogens				
	Liver				
	1,1-DCE	1.2	7.00	0.17	
	1,1,1-TCA	39.0	290.00	0.20	0.37
	-		•		
3017 Bildahl	Carcinogens				
	Stomach				
	1,2-DCA	1.6	100.00	0.02	0.02
	Non-Carcinogens	·			
	Liver		• •		•
	Cis-1,2-DCE	0.1	70.00	0.00	0.00
505 Barnum	Non-Carcinogens			•	
•	Liver				
	TCE	0.5	5.00	0.10	0.10

S. E. ROCKFORD OPERABLE UNIT

			Maximum	Chemical Hazard Index	Target
		Water Concentration ug/l	Contaminant Levels (ug/l)		Organ
Address	•				Mazard
	Contaminant				Index
		==============		***********	
3122 16th	Carcinogens				-
	Liver		•		
	TCE	1.3	5.00	0.26	0.26
	Non-Carcinogens	· .			
	Liver.				
	1,1,1-TCA	2.9	200.00	0.01	0.01